



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2106817

300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

INV Date 01/10/2021  
Reference CC4/LPC21002566/T1gs3q2  
Code LPC2

### PROFESSIONAL SERVICE FEE

Vehicle No. SHC 1483Y  
Insured Veh. YM 8520Z  
Claim No. 20/21/21/VC05/024267  
Policy No. Z20VC05006076  
Accident Date 10/02/2021  
Inspection Date 24/02/2021

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00        |
| <b>Subtotal</b>                | <b>400.00</b> |
| <b>GST (7%)</b>                | <b>28.00</b>  |
| <b>Grand Total</b>             | <b>428.00</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                          |                 |                                                                |  |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------|-----------------|----------------------------------------------------------------|--|
| LONPAC INSURANCE BHD<br>300 BEACH ROAD<br>#17-04/07 THE CONCOURSE SINGAPORE 199555                                                     |                                                                          |                 | Ref: CC4/LPC21002566/T1gs3q2<br>Date: 01/10/2021<br>Code: LPC2 |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                          |                 |                                                                |  |
| Insured Veh.                                                                                                                           | YM 8520Z                                                                 | Veh. Inspected  | SHC 1483Y                                                      |  |
| Policy No.                                                                                                                             | Z20VC05006076                                                            | Coverage (\$)   | 0.00                                                           |  |
| Claim No.                                                                                                                              | 20/21/21/VC05/024267                                                     | Excess (\$)     | 0.00                                                           |  |
| Assign From                                                                                                                            | GERALD                                                                   | Assign Date     | 24/02/2021                                                     |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                          |                 |                                                                |  |
| Make & Model                                                                                                                           | TOYOTA PRIUS                                                             | c.c             | 1798                                                           |  |
| Engine No.                                                                                                                             | HIDDEN                                                                   | Year of Reg.    | 2017                                                           |  |
| Chassis No.                                                                                                                            | JTDKB3FU903563741                                                        | Colour          | BLUE                                                           |  |
| Odometer                                                                                                                               | -                                                                        | Steering        | IN ORDER                                                       |  |
| Brakes                                                                                                                                 | IN ORDER                                                                 | Modification    | SPORTS RIM                                                     |  |
| General                                                                                                                                | GOOD                                                                     |                 |                                                                |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                          |                 |                                                                |  |
|                                                                                                                                        | Size                                                                     | Make            | Balance                                                        |  |
| R/H Front Tyre                                                                                                                         | 195/65 R15                                                               | WEST LAKE       | 6 mm                                                           |  |
| L/H Front Tyre                                                                                                                         | 195/65 R15                                                               | WEST LAKE       | 6 mm                                                           |  |
| R/H Rear Tyre                                                                                                                          | 195/65 R15                                                               | WEST LAKE       | 6 mm                                                           |  |
| L/H Rear Tyre                                                                                                                          | 195/65 R15                                                               | WEST LAKE       | 6 mm                                                           |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                          |                 |                                                                |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION AND UNDERCAAIGE.<br>DAMAGES SEE DETAILS.                                         |                                                                          |                 |                                                                |  |
| <b>5. General Information</b>                                                                                                          |                                                                          |                 |                                                                |  |
| Accident Date                                                                                                                          | 10/02/2021                                                               | Inspection Date | 24/02/2021                                                     |  |
| Survey held at                                                                                                                         | COMFORTDELGRO ENGINEERING PTE LTD<br>59 LOYANG DRIVE<br>SINGAPORE 508969 |                 |                                                                |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                          |                 |                                                                |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                          |                 |                                                                |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                          |                 |                                                                |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                          |                 | 9 Working Days                                                 |  |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1483Y

| Qty | Description of Parts                       | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--------------------------------------------|----------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>         |                      |                           |                   |
| 1   | REAR TRUNK LID COVER                       | BENT                 | 1,126.60                  | 1,126.60          |
| 1   | REAR TRUNK LID LOCK                        | NOT NECESSARY        | 457.90                    | -                 |
| 1   | REAR TRUNK LID COVER TRIM BOARD            | NOT NECESSARY        | 254.40                    | -                 |
| 1   | REAR TRUNK LID RUBBER                      | NOT NECESSARY        | 365.20                    | -                 |
| 1   | REAR TRUNK LID GLASS (BLACK COLOR)         | BROKEN               | 1,569.70                  | 1,569.70          |
| 1   | BOARD ASSY ,BACK DOOR TRIM                 | NOT NECESSARY        | 360.80                    | -                 |
| 1   | GARNISH SUB-ASSY ,BACK DOOR ,OUTSIDE       | CRACKED              | 889.70                    | 889.70            |
| 1   | REAR TRUNK LID LOGO (PRIUS)                | NECESSARY            | 60.80                     | 60.80             |
| 1   | REAR TRUNK LID LOGO (HYBRID)               | NECESSARY            | 52.40                     | 52.40             |
| 1   | REAR TRUNK LID LOGO (TOYOTA STAR)          | NECESSARY            | 52.90                     | 52.90             |
| 1   | REAR BUMPER                                | CRACKED              | 458.60                    | 458.60            |
| 1   | REAR BUMPER REINFORCEMENT                  | NOT NECESSARY        | 318.80                    | -                 |
| 1   | REAR BUMPER UNDER COVER                    | DEFORMED             | 552.60                    | 552.60            |
| 1   | REAR BUMPER SIDE RETAINER RH               | DEFORMED             | 112.70                    | 112.70            |
| 1   | REAR BUMPER UNDER SIDE COVER (RH)          | NOT NECESSARY        | 232.00                    | -                 |
| 1   | REAR BUMPER TOWING COVER                   | NOT NECESSARY        | 82.70                     | -                 |
| 10  | REAR BUMPER CLIPS                          | NECESSARY            | 22.00                     | 22.00             |
| 1   | SEAL ,REAR BUMPER SIDE ,RH                 | DEFORMED             | 148.40                    | 148.40            |
| 1   | TAIL LAMP ASSY (UPPER) RH                  | CRACKED              | 557.90                    | 557.90            |
| 1   | TAIL LAMP ASSY (LOWER) RH                  | CRACKED              | 548.40                    | 548.40            |
| 1   | TAIL LAMP QUARTER PANEL                    | BUCKLED              | 216.00                    | 216.00            |
| 1   | REAR END PANEL                             | TO REPAIR SEE LABOUR | 602.10                    | -                 |
| 1   | REAR END PANEL GARNISH                     | NOT NECESSARY        | 165.80                    | -                 |
| 1   | REAR SPARE TYRE PANEL                      | TO REPAIR SEE LABOUR | 667.70                    | -                 |
| 1   | REAR SPARE TYRE CUSHION (FLR BOARD CENTRE) | NOT NECESSARY        | 101.40                    | -                 |
| 1   | REAR FLOOR BOARD (RH)                      | NOT NECESSARY        | 301.00                    | -                 |
| 1   | REAR FENDER RH                             | BUCKLED              | 836.70                    | 836.70            |
| 1   | REAR FENDER INNER PANEL RH                 | BUCKLED              | 728.00                    | 728.00            |
| 1   | REAR FENDER SHIELD (RH)                    | DEFORMED             | 134.20                    | 134.20            |

Report Ref No. CC4/LPC21002566/T1gs3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts                                                                | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| 1   | REAR FENDER TRIMBOARD (RH)                                                          | NOT NECESSARY | 725.00                    | -                 |
| 1   | REAR FENDER TOP COVER (BLACK COLOR) (RH)                                            | NOT NECESSARY | 301.10                    | -                 |
| 1   | REAR WINDSCREEN GLASS WITH MOULDING                                                 | CRACKED       | 1,778.30                  | 1,778.30          |
| 1   | REAR LOWER ARM RH                                                                   | BENT          | 497.50                    | 497.50            |
| 1   | REAR UPPER ARM RH                                                                   | NOT NECESSARY | 356.80                    | -                 |
| 1   | REAR ASSIST ARM RH                                                                  | NOT NECESSARY | 342.20                    | -                 |
| 1   | REAR TRAILING ARM RH                                                                | BENT          | 314.20                    | 314.20            |
| 1   | REAR KNUCKLE ARM RH                                                                 | BENT          | 810.60                    | 810.60            |
| 1   | HUB & BEARING ASSY ,REAR AXLE RH                                                    | BENT          | 489.40                    | 489.40            |
| 1   | TYRE RIM RH                                                                         | BENT          | 1,555.00                  | 1,555.00          |
| 1   | REAR EXHAUST PIPE                                                                   | NOT NECESSARY | 1,163.40                  | -                 |
| 1   | SMART TRANSMITTER KEY                                                               | NOT NECESSARY | 447.10                    | -                 |
| 1   | DUCT ASSY VENT RH                                                                   | DEFORMED      | 165.10                    | 165.10            |
|     | LESS 25% DISCOUNT                                                                   |               | -5,230.78                 | -3,419.43         |
|     |                                                                                     |               | 15,692.32                 | 10,258.27         |
|     | <b><u>SPECIAL NETT ITEMS</u></b>                                                    |               |                           |                   |
| 1   | REAR NO PLATE WITH TRIM COVER (SN)                                                  | NOT NECESSARY | 50.00                     | -                 |
| 1   | REAR TRUNK LID APPS STICKER (SN)                                                    | NECESSARY     | 40.00                     | 40.00             |
| 1   | REAR TRUNK LID COMFORT & TEL NO.STICKER (SN)                                        | NECESSARY     | 60.00                     | 60.00             |
| 1   | REAR BUMPER REVERSE SENSOR (SN)                                                     | NECESSARY     | 135.70                    | 135.70            |
| 1   | REAR BUMPER RUBBER MAT (SN)                                                         | NECESSARY     | 50.00                     | 50.00             |
| 1   | REAR TYRE RH (80%) (SN)                                                             | PUNCTURE      | 216.00                    | 172.80            |
| 1   | REAR WINDSCREEN SEALANT (SN)                                                        | NECESSARY     | 46.00                     | 46.00             |
|     |                                                                                     |               | 597.70                    | 504.50            |
|     | <b><u>LABOUR</u></b>                                                                |               |                           |                   |
|     | PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR SPARE TYRE PANEL . |               | 1,800.00                  | 1,400.00          |
|     | SPRAY PAINTING CHARGE.                                                              |               | 900.00                    | 875.00            |
|     | WIRING CHARGE.                                                                      |               | 120.00                    | 30.00             |
|     | TUFF KOTE.                                                                          |               | 50.00                     | 30.00             |
|     | TOWING CHARGE.                                                                      |               | 60.00                     | 60.00             |
|     | REMOVE/REFIX CUSHION & UPHOLSTERY REAR .                                            |               | 150.00                    | 60.00             |
|     | REMOVE/REFIX REAR WINDSCREEN GLASS .                                                |               | 120.00                    | 120.00            |

Report Ref No. CC4/LPC21002566/T1gs3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty                                                                     | Description of Parts                          | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-------------------------------------------------------------------------|-----------------------------------------------|-----------|---------------------------|-------------------|
|                                                                         | REMOVE/REFIX REVERSE SENSOR .                 |           | 120.00                    | 30.00             |
|                                                                         | REMOVE/REFIT REAR UNDER CARRIAGE SUSPENSION . |           | 120.00                    | 90.00             |
|                                                                         | REAR WHEEL ALIGNMENT.                         |           | 120.00                    | 80.00             |
|                                                                         |                                               |           | 3,560.00                  | 2,775.00          |
| GRAND TOTAL                                                             |                                               |           | 19,850.02                 | 13,537.77         |
| RECOMMENDED COST OF LUMP SUM REPAIRS<br>(TO ITS PRE-ACCIDENT CONDITION) |                                               |           |                           | 10,800.00         |

Report Ref No. CC4/LPC21002566/T1gs3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. SHC 1483Y**

**RE-INSPECTION**






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

