

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Vehicle No.: sSHC1483Y

Make : TOYOTA

Model : PRIUS

DOA : 2/10/2021

Date : 24/2/2021

Insurance:

MVA : CHIANG/LONPAC

Admin :

Part No.	Parts Description / Labour	Qty	Unit Price	Amount	
1	REAR TRUNK LID COVER			\$1,126.60	bt
1	REAR TRUNK LID LOCK			\$457.90	?
1	REAR TRUNK LID COVER TRIM BOARD			\$254.40	x
1	REAR TRUNK LID RUBBER			\$365.20	?
1	REAR TRUNK LID GLASS (BLACK COLOR)			\$1,569.70	bro
1	BOARD ASSY, BACK DOOR TRIM			\$360.80	?
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE			\$889.70	cu
1	REAR TRUNK LID LOGO (PRIUS)			\$60.80	ner
1	REAR TRUNK LID LOGO (HYBRID)			\$52.40	ng
1	REAR TRUNK LID LOGO (TOYOTA STAR)			\$52.90	ner
1	REAR BUMPER			\$458.60	cu
1	REAR BUMPER RE-INFORCEMENT			\$318.80	?
1	REAR BUMPER UNDER COVER			\$552.60	de
1	REAR BUMPER SIDE RETAINER RH			\$112.70	de
1	REAR BUMPER UNDER SIDE COVER (RH)			\$232.00	?
1	REAR BUMPER TOWING COVER			\$82.70	?
10	REAR BUMPER CLIPS			\$22.00	ng
1	SEAL, REAR BUMPER SIDE, RH			\$148.40	?
1	TAIL LAMP ASSY (UPPER) RH			\$557.90	ar
1	TAIL LAMP ASSY (LOWER) RH			\$548.40	ar
1	TAIL LAMP QUARTER PANEL			\$216.00	bu
1	REAR END PANEL			\$602.10	Ry
1	REAR END PANEL GARNISH			\$165.80	?
1	REAR SPARE TYRE PANEL			\$667.70	Ry
1	REAR SPARE TYRE CUSHION (FLR BOARD CENTRE)			\$101.40	?
1	REAR FLOOR BOARD (RH)			\$301.00	?
1	REAR FENDER RH			\$836.70	bu
1	REAR FENDER INNER PANEL RH			\$728.00	Ry
1	REAR FENDER SHIELD (/RH)			\$134.20	de
1	REAR FENDER TRIMBOARD (/RH)			\$725.00	?
1	REAR FENDER TOP COVER (BLACK COLOR)(RH)			\$301.10	?
1	REAR WINDSCREEN GLASS WITH MOULDING			\$1,778.30	ang
1	REAR LOWER ARM RH			\$497.50	?
1	REAR UPPER ARM RH			\$356.80	?
1	REAR ASSIST ARM RH			\$342.20	?
1	REAR TRAILING ARM RH			\$314.20	?
1	REAR KNICKLE ARM RH			\$810.60	?
1	HUB & BEARING ASSY, REAR AXLE RH			\$489.40	?
1	TYRE RIM RH			\$1,555.00	bt
1	REAR EXHAUST PIPE			\$1,163.40	x

Part No.	Parts Description / Labour	Qty	Unit Price	Amount	
1	SMART TRANSMITTER KEY			\$447.10	X
1	DUCT ASSY VENT RH			\$165.10	de
	SUB TOTAL			\$20,923.10	
	LESS 25%			\$5,230.78	
	DISCOUNTED TOTAL			\$15,692.33	
	REAR NO. PLATE WITH TRIM COVER			X \$50.00	Nett
	REAR TRUNK LID APPS STICKER			net \$40.00	Nett
	REAR TRUNK LID COMFORT & TEL NO. STICKER			net \$60.00	Nett
	REAR BUMPER REVERSE SENSOR			? \$135.70	Nett
	REAR BUMPER RUBBER MAT			net \$50.00	Nett
	REAR TYRE RH			parted 80% \$216.00	Nett
	REAR WINDSCREEN SEALANT			net \$46.00	Nett
				\$597.70	
	Labour Charge				
	Panel Beating			1400 \$1,800.00	
	Spray Painting Charge			875 \$900.00	
	Wiring Charge			30 \$120.00	
	Tuff Kote			50 \$50.00	
	Towing Charge			✓ \$60.00	
	Remove/Refix Cushion & Upholstery Rear			60 \$150.00	
	Remove/Refix Rear Windscreen Glass			✓ \$120.00	
	Remove/Refix Reverse Sensor			30 \$120.00	
	Remove/refi rear under carriage suspension			photo ? \$120.00	
	Rear Wheel Alignment			80 \$120.00	
	TOTAL LABOUR			\$3,560.00	
	ESTIMATE TOTAL			\$19,850.03	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Taughlin 97495749 . Westlake
 'WP' 24/2/210 /pm
 4/5 Resurvey after repair
 7 days
 taughlin @lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 23.02.2021 16:20

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD

Sales Order:

JC NO.: 305454144

CUSTOMER

RMS COMFORT TRANSPORTATION PTE LTD

CUSTOMER NO. 7010045

ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

L (R) 65508755 (O)

(P)

ACCOUNT CARD NO.

REGN NO.:

SHC1483Y

MILEAGE

MAKE:

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4)10.02.2021 19:40

DATE/TIME IN

YR OF MANU.

23.08.2017

TARGET DATE

CHASSIS CODE

JTDKB3FU903563741

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 10.02.2021

NATURE: TP /3P 10.02.2021

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

acknowledgement Slip

Exit Pass

Vehicle No.: SHC1483Y

CHIANG

Vehicle No.:

SHC1483Y

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard