

Our Job Ref No : 305454144
Date : 08/03/21

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : TAUFIKH
Vehicle Reg No. : SHC1483Y

Fax :

10/02/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- Z The repair job shall bill to: LONPAC YM8520Z
2. The finalized amount shall be:
- (a) Spare Parts after List discount _____
- (b) Labour Charges _____
- Total for Part-By-Part Repair Cost** _____
- (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: _____
Final Lumpsum Repair cost \$11,000.00 \$10,800

3. Estimated normal period for repairs: 9 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : 

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature : taufikh

Name : Taufikh

Date : 25/3/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Vehicle No.: sSHC1483Y
 Make : TOYOTA
 Model : PRIUS
 DOA : 2/10/2021

Date : 24/2/2021
 Insurance:
 MVA : CHIANG/LONPAC
 Admin :

Part No.	Parts Description / Labour	Qty	Unit Price	Amount
1	REAR TRUNK LID COVER			\$1,126.60 <i>bt</i>
1	REAR TRUNK LID LOCK			\$457.90 <i>? Xnn</i>
1	REAR TRUNK LID COVER TRIM BOARD			\$254.40 <i>nn</i>
1	REAR TRUNK LID RUBBER			\$365.20 <i>? Xnn</i>
1	REAR TRUNK LID GLASS (BLACK COLOR)			\$1,569.70 <i>pro</i>
1	BOARD ASSY, BACK DOOR TRIM			\$360.80 <i>? Xnn</i>
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE			\$889.70 <i>ena</i>
1	REAR TRUNK LID LOGO (PRIUS)			\$60.80 <i>ue</i>
1	REAR TRUNK LID LOGO (HYBRID)			\$52.40 <i>19</i>
1	REAR TRUNK LID LOGO (TOYOTA STAR)			\$52.90 <i>ue</i>
1	REAR BUMPER			\$458.60 <i>ovi</i>
1	REAR BUMPER RE-INFORCEMENT			\$318.80 <i>? Xnn</i>
1	REAR BUMPER UNDER COVER			\$552.60 <i>de</i>
1	REAR BUMPER SIDE RETAINER RH			\$112.70 <i>de</i>
1	REAR BUMPER UNDER SIDE COVER (RH)			\$232.00 <i>? Xnn</i>
1	REAR BUMPER TOWING COVER			\$82.70 <i>? Xnn</i>
10	REAR BUMPER CLIPS			\$22.00 <i>ue</i>
1	SEAL, REAR BUMPER SIDE, RH			\$148.40 <i>? de</i>
1	TAIL LAMP ASSY (UPPER) RH			\$557.90 <i>as</i>
1	TAIL LAMP ASSY (LOWER) RH			\$548.40 <i>as</i>
1	TAIL LAMP QUARTER PANEL			\$216.00 <i>buc</i>
1	REAR END PANEL			\$602.10 <i>Ry</i>
1	REAR END PANEL GARNISH			\$165.80 <i>? Xnn</i>
1	REAR SPARE TYRE PANEL			\$667.70 <i>Ry</i>
1	REAR SPARE TYRE CUSHION (FLR BOARD CENTRE)			\$101.40 <i>? Xnn</i>
1	REAR FLOOR BOARD (RH)			\$301.00 <i>? Xnn</i>
1	REAR FENDER RH			\$836.70 <i>buc</i>
1	REAR FENDER INNER PANEL RH			\$728.00 <i>Ry buc</i>
1	REAR FENDER SHIELD (/RH)			\$134.20 <i>de</i>
1	REAR FENDER TRIMBOARD (/RH)			\$725.00 <i>? Xnn</i>
1	REAR FENDER TOP COVER (BLACK COLOR)(RH)			\$301.10 <i>? Xnn</i>
1	REAR WINDSCREEN GLASS WITH MOULDING			\$1,778.30 <i>ang</i>
1	REAR LOWER ARM RH			\$497.50 <i>? bt</i>
1	REAR UPPER ARM RH			\$356.80 <i>? Xnn</i>
1	REAR ASSIST ARM RH			\$342.20 <i>? Xnn</i>
1	REAR TRAILING ARM RH			\$314.20 <i>? bt</i>
1	REAR KNICKLE ARM RH			\$810.60 <i>? bt</i>
1	HUB & BEARING ASSY, REAR AXLE RH			\$489.40 <i>? bt</i>
1	TYRE RIM RH			\$1,555.00 <i>bt</i>
1	REAR EXHAUST PIPE			\$1,163.40 <i>Xnn</i>

3/3

13677.70

Part No.	Parts Description / Labour	Qty	Unit Price	Amount	
1	SMART TRANSMITTER KEY			\$447.10	X Xnn
1	DUCT ASSY VENT RH	750 10258.27		\$165.10	de
	SUB TOTAL			\$20,923.10	
	LESS 25%			\$5,230.78	
	DISCOUNTED TOTAL			\$15,692.33	
	REAR NO. PLATE WITH TRIM COVER			nn \$50.00	Nett
	REAR TRUNK LID APPS STICKER			nel \$40.00	Nett
	REAR TRUNK LID COMFORT & TEL NO. STICKER			nel \$60.00	Nett
	REAR BUMPER REVERSE SENSOR		nw	\$135.70	Nett
	REAR BUMPER RUBBER MAT			nel \$50.00	Nett
	REAR TYRE RH		172.80 partnet 80%	\$216.00	Nett
	REAR WINDSCREEN SEALANT	504.50		nel \$46.00	Nett
				\$597.70	
	Labour Charge				
	Panel Beating			1400 \$1,800.00	
	Spray Painting Charge			875 \$900.00	
	Wiring Charge			30 \$120.00	
	Tuff Kote			50 \$50.00	
	Towing Charge			\$60.00	
	Remove/Refix Cushion & Upholstery Rear			60 \$150.00	
	Remove/Refix Rear Windscreen Glass			\$120.00	
	Remove/Refix Reverse Sensor			30 \$120.00	
	Remove/refi rear under carriage suspension		90 photo ?	\$120.00	90
	Rear Wheel Alignment			80 \$120.00	
	TOTAL LABOUR	2775.00		\$3,560.00	
	ESTIMATE TOTAL			\$19,850.03	
		13537.77		11,000	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Taughlin 97495749 Westlake

13537.77
I/s\$10,800
9 days #

'WP' 24/2/21 1pm

4/5 Resumy after repair

7 days + 2 days = 9 days

taughlin@khaauto.com