



Rico 60 Auto Services Pte Ltd
 Blk 8 , Kaki Bukit Avenue 4 , #02-24
 Premier @ Kaki Bukit Singapore 415875
 Email: claims@rico60.com
 Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -20%	
SN	
Labour	
Total	
Lump Sum	
ERV	15K

TO: AXA
Vehicle No : SKU 8953 G
Make & Model : HONDA MOBOLIO
DATE: 24/2/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	FRONT DOOR LH	1	\$ 779.20	\$ 66 779.20
2	FRONT DOOR BLACK STICKER LH	2	\$ 43.00	\$ rev 86.00
3	FRONT DOOR SIDE MIRROR LH	1	\$ 694.30	\$ dis 694.30
4	FRONT DOOR MOULDING LH	1	\$ 172.10	\$ de 172.10
5	FRONT DOOR INNER LOCK LH	1	\$ 299.70	\$ x 299.70
6	FRONT DOOR LOCK CATCH LH	1	\$ 46.00	\$ x 46.00
7	FRONT DOOR WEATHERSTRIP LH	1	\$ 189.30	\$ rev 189.30
8	FRONT DOOR INNER TRIM LH	1	\$ 511.40	\$ x 511.40
9	FRONT DOOR INNER STEP GARNISH LH	1	\$ 254.00	\$ x 254.00
10	CENTER OUTER PILLAR LH	1	\$ 673.40	\$ bf 673.40
11	CENTER INNER PILLAR LH	1	\$ 722.00	\$ Ry 722.00
12	CENTER PILLAR TOP TRIM LH	1	\$ 255.20	\$ x 255.20
13	CENTER PILLAR BOTTOM TRIM LH	1	\$ 312.30	\$ x 312.30
14	ROCKER PANEL LH	1	\$ 954.10	\$ Bt 954.10
15	SIDE SKIRT LH	1	\$ 754.00	\$ dis 754.00
16	REAR DOOR LH	1	\$ 825.20	\$ bt 825.20
17	REAR DOOR BLACK STICKER LH	1	\$ 43.00	\$ rev 43.00
18	REAR DOOR MOULDING LH	1	\$ 187.50	\$ de 187.50
19	REAR DOOR HINGE LH <i>lower. photo</i>	1.2	\$ 110.00	\$ Bt 220.00
20	REAR DOOR CHECKER LH	1	\$ 144.10	\$? 144.10
21	REAR DOOR INNER LOCK LH	1	\$ 297.40	\$ bt 297.40
22	REAR DOOR LOCK CATCH LH	1	\$ 46.00	\$ x 46.00
23	REAR DOOR WEATHERSTRIP LH	1	\$ 192.30	\$ rev 192.30
24	REAR DOOR INNER TRIM BOARD LH	1	\$ 546.10	\$? 546.10
25	REAR DOOR REGULATOR MOTOR LH	1	\$ 394.00	\$? 394.00
26	REAR DOOR REGULATOR GEAR LH	1	\$ 257.40	\$? 257.40
27	REAR DOOR CHANNEL LH	1	\$ 89.00	\$ x 89.00

28	REAR DOOR CHANNEL SEAL LH	1	\$	155.40	\$ [?] 155.40
29	REAR STEP TRIM LH	1	\$	90.00	\$ ^{de} 90.00
30	REAR FENDER LH	1	\$	799.40	\$ ^{bb} 799.40
31	REAR FENDER GLASS WITH MOULDING LH	1	\$	451.00	\$ ^{re} 451.00
32	REAR FENDER INNER SHIELD LH	1	\$	198.70	\$ ^{de} 198.70
33	REAR FENDER INNER TRIM LH	1	\$	845.00	\$ ^x 845.00
34	REAR ABSORBER LH	1	\$	479.10	\$ [?] 479.10
35	REAR WHEEL BEARING LH	1	\$	654.90	\$ [?] 654.90
36	REAR AXLE	1	\$	2,245.00	\$ ^x 2,245.00
37	REAR ORIGINAL RIM LH	1	\$	750.00	\$ ^{dd} 750.00
38	REAR BUMPER	1	\$	563.70	\$ ^{fr} 563.70
39	REAR BUMPER SIDE RETAINER ^{RH x}	2	\$	120.00	\$ ^{LH-20} 240.00

Subtotal : \$ 17,417.20

Less 20% \$ 3,483.44

Parts Total : \$ 13,933.76

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	CENTER PILLAR OUTER SEALANT	1	\$ 80.00	\$ ⁴⁰ 80.00
2	CENTER PILLAR INNER SEALANT	1	\$ 80.00	\$ ^x 80.00
3	CENTER PILLAR TOP TRIM CLIP	1	\$ 40.00	\$ ^x 40.00
4	CENTER PILLAR LOWER TRIM CLIP	1	\$ 40.00	\$ ^x 40.00
5	ROCKER PANEL SEALANT	1	\$ 80.00	\$ ^x 80.00
6	SIDE SKIRT CLIP	1	\$ 50.00	\$ ^{20m} 50.00
7	REAR DOOR INNER TRIM CLIP	1	\$ 50.00	\$ ^{20m} 50.00
8	REAR STEP TRIM CLIP	1	\$ 30.00	\$ ^{10m} 30.00
9	REAR FENDER INNER SHIELD CLIP	1	\$ 40.00	\$ ^{10m} 40.00
10	REAR FENDER GLASS SEALANT	1	\$ 80.00	\$ ^{40m} 80.00
11	REAR BUMPER CLIP	1	\$ 50.00	\$ ^{30m} 50.00
12	REAR TYRE	1	\$ 450.00	\$ ^x 450.00

\$ 1,070.00

LABOUR	PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	¹²⁰⁰ \$ 1,700.00
TO SPRAY PAINT AFFECTED AREA	¹⁴⁰⁰ \$ 1,600.00
TO PERFORM LIGHTING & WIRING CHECK	³⁰ \$ 100.00
TO APPLY ANTI-RUST & TUFF KOTE	⁴⁰ \$ 200.00

REMOVE AND INSTALL FRONT DOOR PART		\$ 60 180.00
REMOVE AND INSTALL REAR DOOR PART		\$ 60 180.00
REMOVE AND INSTALL REAR UNDER CARRIAGE	photo?	\$ 150 600.00
TO CHECK FOUR WHEEL ALIGMENT		\$ 80. 100.00
REMOVE AND INSTALL CARPET,SEAT AND INTERIOR	60	\$ 350.00
LABOUR TOTAL		\$ 5,010.00

	Total Parts Cost	\$ 15,003.76
	Total Labour Cost	\$ 5,010.00
	Total Repair Cost	\$ 20,013.76

APPROVED DETAILS
NO. OF WORKING DAYS
PART BY PART OR LUMP SUM
DATE & TIME OF SURVEY
SURVEYED BY
CONTACT NUMBER
FAX NUMBER

Taphin 9749 5749
 WP 25/2/2021 @ 1500
 1/5 Resurvey after repair
 Taphin @ 11hantown
 09 days

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: