

RICO60

AUTO SERVICES

Rico 60 Auto Services Pte Ltd
Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875
Email: claims@rico60.com
Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -20%	
SN	
Labour	
Total	
Lump Sum	
ERV	15K

TO: AXA

Vehicle No : SKU 8953 G

Make & Model : HONDA MOBOLIO

DATE: 24/2/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	FRONT DOOR LH	1	\$ 779.20	\$ 66 779.20
2	FRONT DOOR BLACK STICKER LH	2	\$ 43.00	\$ ner 86.00
3	FRONT DOOR SIDE MIRROR LH 284.10	1	\$ 694.30	\$ dis 694.30
4	FRONT DOOR MOULDING LH	1	\$ 172.10	\$ de 172.10
5	FRONT DOOR INNER LOCK LH	1	\$ 299.70	\$ xnn 299.70
6	FRONT DOOR LOCK CATCH LH	1	\$ 46.00	\$ xnn 46.00
7	FRONT DOOR WEATHERSTRIP LH	1	\$ 189.30	\$ ner 189.30
8	FRONT DOOR INNER TRIM LH	1	\$ 511.40	\$ xnn 511.40
9	FRONT DOOR INNER STEP GARNISH LH	1	\$ 254.00	\$ xnn 254.00
10	CENTER OUTER PILLAR LH	1	\$ 673.40	\$ bt 673.40
11	CENTER INNER PILLAR LH	1	\$ 722.00	\$ ky 722.00
12	CENTER PILLAR TOP TRIM LH	1	\$ 255.20	\$ xnn 255.20
13	CENTER PILLAR BOTTOM TRIM LH	1	\$ 312.30	\$ xnn 312.30
14	ROCKER PANEL LH 9492.60	1	\$ 954.10	\$ bt 954.10
15	SIDE SKIRT LH 476.40	1	\$ 754.00	\$ dis 754.00
16	REAR DOOR LH	1	\$ 825.20	\$ bt 825.20
17	REAR DOOR BLACK STICKER LH	1	\$ 43.00	\$ ner 43.00
18	REAR DOOR MOULDING LH	1	\$ 187.50	\$ de 187.50
19	REAR DOOR HINGE LH lower. photo 1.2	1.2	\$ (110.00)	\$ bt 220.00
20	REAR DOOR CHECKER LH	1	\$ 144.10	\$ mx 144.10
21	REAR DOOR INNER LOCK LH	1	\$ 297.40	\$ bt 297.40
22	REAR DOOR LOCK CATCH LH	1	\$ 46.00	\$ xnn 46.00
23	REAR DOOR WEATHERSTRIP LH	1	\$ 192.30	\$ de 192.30
24	REAR DOOR INNER TRIM BOARD LH 446.70	1	\$ 546.10	\$ de 546.10
25	REAR DOOR REGULATOR MOTOR LH 299.10	1	\$ 394.00	\$ bt 394.00
26	REAR DOOR REGULATOR GEAR LH	1	\$ 257.40	\$ kan 257.40
27	REAR DOOR CHANNEL LH	1	\$ 89.00	\$ xnn 89.00

28	REAR DOOR CHANNEL SEAL LH		1	\$	155.40	\$ <i>de</i> 155.40
29	REAR STEP TRIM LH		1	\$	90.00	\$ <i>de</i> 90.00
30	REAR FENDER LH		1	\$	799.40	\$ <i>bb</i> 799.40
31	REAR FENDER GLASS WITH MOULDING LH		1	\$	451.00	\$ <i>re</i> 451.00
32	REAR FENDER INNER SHIELD LH	<i>50.20</i>	1	\$	198.70	\$ <i>de</i> 198.70
33	REAR FENDER INNER TRIM LH		1	\$	845.00	\$ <i>nx</i> 845.00
34	REAR ABSORBER LH	<i>379.10</i>	1	\$	479.10	\$ <i>h?</i> 479.10
35	REAR WHEEL BEARING LH	<i>454.90</i>	1	\$	654.90	\$ <i>h?</i> 654.90
36	REAR AXLE		1	\$	2,245.00	\$ <i>x</i> 2,245.00
37	REAR ORIGINAL RIM LH	<i>600</i>	1	\$	750.00	\$ <i>dd</i> 750.00
38	REAR BUMPER		1	\$	563.70	\$ <i>fn</i> 563.70
39	REAR BUMPER SIDE RETAINER	<i>RH x nn</i>	2	\$	<u>120.00</u>	\$ <i>LH-20</i> 240.00

	<i>9218</i>	Subtotal :	\$	17,417.20
	<i>7374.40</i>	Less 20%	\$	3,483.44
		Parts Total :	\$	13,933.76

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	CENTER PILLAR OUTER SEALANT	1	\$ 80.00	\$ <i>40</i> 80.00
2	CENTER PILLAR INNER SEALANT	1	\$ 80.00	\$ <i>x</i> 80.00
3	CENTER PILLAR TOP TRIM CLIP	1	\$ 40.00	\$ <i>x</i> 40.00
4	CENTER PILLAR LOWER TRIM CLIP	1	\$ 40.00	\$ <i>x</i> 40.00
5	ROCKER PANEL SEALANT	1	\$ 80.00	\$ <i>x</i> 80.00
6	SIDE SKIRT CLIP	1	\$ 50.00	\$ <i>20m</i> 50.00
7	REAR DOOR INNER TRIM CLIP	1	\$ 50.00	\$ <i>20m</i> 50.00
8	REAR STEP TRIM CLIP	1	\$ 30.00	\$ <i>10m</i> 30.00
9	REAR FENDER INNER SHIELD CLIP	1	\$ 40.00	\$ <i>10m</i> 40.00
10	REAR FENDER GLASS SEALANT	1	\$ 80.00	\$ <i>40m</i> 80.00
11	REAR BUMPER CLIP	1	\$ 50.00	\$ <i>30m</i> 50.00
12	REAR TYRE	1	\$ 450.00	\$ <i>x</i> 450.00
				<i>170</i>

			\$	1,070.00
LABOUR			PRICE	
PANEL BEATING, REMOVAL AND REPLACING PARTS	<i>1200</i>	\$	1,700.00	
TO SPRAY PAINT AFFECTED AREA	<i>1400</i>	\$	1,600.00	
TO PERFORM LIGHTING & WIRING CHECK	<i>30</i>	\$	100.00	
TO APPLY ANTI-RUST & TUFF KOTE	<i>40</i>	\$	200.00	

REMOVE AND INSTALL FRONT DOOR PART		\$ 60 180.00
REMOVE AND INSTALL REAR DOOR PART		\$ 60 180.00
REMOVE AND INSTALL REAR UNDER CARRIAGE	photo?	\$150 600.00
TO CHECK FOUR WHEEL ALIGMENT		\$80 100.00
REMOVE AND INSTALL CARPET, SEAT AND INTERIOR	60	\$ 350.00
		3080
LABOUR TOTAL		\$ 5,010.00

	Total Parts Cost	\$ 15,003.76
	Total Labour Cost	\$ 5,010.00
	Total Repair Cost	\$ 20,013.76

APPROVED DETAILS
NO. OF WORKING DAYS
PART BY PART OR LUMP SUM
DATE & TIME OF SURVEY
SURVEYED BY
CONTACT NUMBER
FAX NUMBER

Tamplin 97495749
 WP 25/2/2015
 1/5 Resurvey after repair
 Tamplin 11/11/2015
 09 days

7374.40
 170
 3080
 10624.40
 1/5 8500 #
 9 days

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: