

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0055/2021
DATE : 24-FEB-2021

24/03/2021

LONPAC INSURANCE BHD
300 BEACH RD
#17-04/07 THE CONCOURSE
S(199555)
TEL : 62507388
FAX : 62962706
MOTOR CLAIMS DEPT

OWNER'S NAME : MR LIM CHENG HAN
ADDRESS : BLK 291C BUKIT BATOK STREET 24
#18-27
S(652291)
TELEPHONE NO : 65657215/97858741

RASUL
D/S

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-GBF3903U
VEHICLE NO : SLU7215Z
MODEL CODE : FRLARDWJ11USA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2 MY2017
ENGINE NO : HRA2531456A
CHASSIS NO : SJNFEAJ11U2119610
MILEAGE : 1 KM
DATE IN : 24/02/2021
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 23/02/2021

Prime
\$100/any X 0.4
= \$40000 cash
= \$428

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLU7215Z

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RITCAM	REMOVE/INSTALL & TEST REAR REVERSE CAMERA	120.00	120.00
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 03	360.00	120.00
3	RS	SUPPLY & INSTALL REVERSE SENSOR	110.00	110.00
4	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 03	300.00	100.00
5	SRW	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN	150.00	150.00
6	UG14	RENEW REAR WINDSCREEN GLASS ASSY.	240.00	240.00
7	ZZ/001	REPAIR LH/RH REAR FENDER AND RENEW TAILGATE, REAR BUMPER AND END PANEL	1500.00	1170.00
8	ZZ/002	S/PAINT REAR PORTION	1500.00	850.00
9	ZZ/003	CHECK LIGHTING	48.00	48.00
10	ZZ/004	TRANSFER TAILGATE MECHNICAL PARTS	80.00	80.00
11	ZZ/005	R/I REAR DVR TO ASSIST REPAIR	120.00	120.00
TOTAL LABOUR CHARGES			4528.00	3108.00

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLU7215Z

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	EMBLEM	90892-4EA0A	94.40			OK
2	EMBLEM-REAR	90890-4EA0A	64.90			OK
3	STRIKER-TAIL GA	90570-4EA0A	34.80			X
4	A LOCK LIFT	90502-4EA1B	173.20			X
5	GROMMET BUMPER \$2.70 EA X 04	63846-5V000	10.80			OK
6	CLIP BUMPER \$8.00 EA X 03	85284-JD00A	24.00			OK
7	CANOE RIVET BUMPER \$7.10 EA X 02	76882-0M000	14.20			OK
8	RETAINER-BUMPER RH	79184-4EA0A	25.70			X
9	RETAINER-BUMPER LH	79185-4EA0A	25.70			X
10	BRACKET-BUMPER RH	85220-4EA0A	38.90			X
11	BRACKET-BUMPER LH	85221-4EA0A	38.90			X
12	STAY ASSY-REAR RH	H5210-4EAMA	141.00			X
13	STAY ASSY-REAR LH	H5211-4EAMA	141.00			X
14	REINF-BUMPER RR	H5030-4EAMA	691.50			X
15	ENERGY ABSORBER	85090-HV00A	141.40			X
16	FASCIA-RR BUMP	85022-HV00H	796.70			OK
17	CLIP FINISHER END PANEL \$1.30 EA X 04	01554-00181	5.20			X
18	CLIP END PANEL \$1.30 EA X 02	01553-05323	2.60			X
19	PLATE-LUGGAGE	84992-4EA0A	68.80			X
20	PANEL-REAR UPPE	G9110-HV0MA	482.60			X
21	CLIP FENDER ARC/BUMPER \$1.30 EA X 04	01553-05933	5.20			OK
22	FENDER RH REAR ARC	93828-4EA0A	540.50			X
23	FENDER ARC LH REAR	93829-4EA0A	540.50			X
24	WEATHER STRIP	90830-4EA0B	167.00			X
25	A FIN BACK DOOR TOP NO PLATE	90810-4ES0H	352.00			OK

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLU7215Z

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
26	RUBBER-DUM	G2716-89900	63.80			OK
27	GLASS-TAIL GATE	90300-HV00A	990.00			OK
28	DOOR BACK	K0100-HV0MB	3062.60			OK
29	GROMMET BUMPER \$2.40 EA X 02	01281-00111			4.80	OK
30	MOTOR-WIPER	28710-4ELOA			427.30	X
31	GROMMET C/LAMP \$27.90 EA X 02	76848-83P00	55.80			OK
32	GROMMET C/LAMP \$2.00 EA X 02	76848-35F00	4.00			OK
33	CLIP C/LAMP \$5.40 EA X 02	26398-ED000	10.80			OK
34	LAMP COMB RR,LH BOOT	26555-HV55A	231.30			X
35	LAMP COMB RR,LH	26555-HV00A	346.90			X
36	CLIP GRILLE RAD \$1.80 EA X 04	01515-00QAB	7.20			X
37	GRILLE-RADIATOR	62310-HV00A	486.00			X
38	CAMERA BRACKET	BRACKET-CAM			20.00	OK
39	SUNDRIES	NPN			20.00	OK
40	REAR W/SCREEN SEALANT	SEALANT - 4			80.00	OK
41	SENSOR-REVERSE	SENSOR			250.00	OK
SUB TOTAL			5549.20	0.00	374.80	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			1109.84	0.00	0.00	
GRAND TOTAL			4439.36	0.00	374.80	
OVERALL TOTAL			4814.16			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLU7215Z

NETT ITEM	5549.20
LESS 20.00%)	-1109.84
NETT AMOUNT	4439.36
LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	374.80
LESS .00%)	0.00
SPECIAL NETT AMOUNT	374.80
TOTAL LABOUR CHARGES	3108.00
TOTAL SPARE PARTS CHARGES	4814.16
TOTAL CHARGES	7922.16
ADD 7 % GST	554.55
GRAND TOTAL	8476.71
