

NGS MOTORSPORT PTE LTD

Blk 10 Ang Mo Kio Industrial Park 2A #02-01 AMK AutoPoint Singapore 568047

Tel : 9695 5547 Fax: 6481 5727 e-mail : evelynngstrading@gmail.com

Reg No: 201812604N

23/02/2021

Aviva Limited
4 Shenton Way
#01-01 SGX Centre 2
Singapore 068807
Attn: Motor Claims Dept

Not Authorized
1/1m &
Repair After Paint
2 days

RE: Accident On 19/02/2021@16:30Hrs Involving SJZ245E & SKN1374K

Along 122 Sengkang East West

CLAIMS AGAINST SKN1374K

We submit herewith our direct claim estimate quotation as follow:-

Replacement parts - Toyota Vios

- 1 Frt fender LH
- 1 Frt Fender Liner LH
- 1 Frt Bumper
- 1 Frt bumper side retainer LH
- 1 Frt Bumper support LH
- 1 Frt bumper Grille lower LH
- 1 Headlamp LH

\$0.00

30 Sep 2024

A - Car (1600cc & below)

\$14,743.00

\$10,598.00

\$10,598.00

R \$ 371.40 *x*
su \$ 153.80 *x*
Budum \$ 447.90 *✓*
\$0.7 48.16 *✓*
\$ su 59.80 *x*
\$ su 66.40 *x*
mgcm \$ 294.80 *✓*

\$ 1,442.26

Less 25% \$ (360.57)

\$ 1,081.69

\$ 3.50 \$ *su* 70.00 *x*

\$ 400.00 *20d*

20 Clips, Fender Liner S/net

To remove all damaged part with all necessary component/attachm.

Straighten chassis member, repair/reshape dented body panel..

Replace damaged part. Refit into position.

To spray painting

\$ 500.00 *22d*

Check wiring & light function

\$ 50.00 *2d*

\$ 2,101.69

no. plate *s/net* *\$30* *cm* *20sm*

Any other parts which necessitate repair or renewal will incur additional charged.

Please contact our Ms Evelyn @HP96955547 to arrange for survey. Thank you

Yours faithfully.

NGS MOTORSPORT PTE LTD

EVELYN NG

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: