

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21002581/R1VF3E2  
**Date:** 19/03/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100399589  
**Claimant Vehicle No :** GBH7829P **Insured Vehicle No :** SKR1555J  
Date of Loss: 22/02/2021 Nature of Claim: TP Claim No: 0804215307SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH7829P**  
Make & Model: NISSAN NV350, 2.5 PANEL VAN 5MT 5DR (M) Engine No: YD25426481A  
Reg. Date: 25/09/2018 (Man. Year: 2017) Chassis No: JN1MC2E26Z0009157  
Colour: Grey Odometer: 55267 km  
Engine Capacity: 2488 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C  
Front Left Side: GREEN-MAX 6 mm Rear Left Side: GREEN-MAX 6 mm  
Front Right Side: GREEN-MAX 6 mm Rear Right Side: GREEN-MAX 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 24/02/2021  
Date Inspected: 26/02/2021 Inspected At: Thiam Heng Auto (s) Pte Ltd (HQ)  
1 BUKIT BATOK CRESCENT #03-17/18 WCEGA  
PLAZA  
Singapore 658064  
Estimated Period of Repair: 4.0 days

**Adjuster:** MOHD RASUL

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR LH TAILLAMP	Scratched	0.00 F	*- F	
2	1		*SLIDING DOOR LH	Bent	0.00 F	*- F	
3	1		*REAR LH RIM COVER	Scratched	0.00 F	*- F	
4	1		*LH SIDE PILLAR (OUTER)	Repair	0.00 F	*- F	
5	1		*REAR LH SIDE PANEL	Repair	0.00 F	*- F	
					<b>Total Parts (\$)</b>	<b>0.00</b>	<b>0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**