

ASS. REC. BY: Jim

REF: CS/LPC21002588/R/H/3

6/04

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No: YQ1804E

at Workshop m/s FALCON AIR

of BLK 8, ARROW LANE

Insured: LPC

Policy No. _____

Claims No. 20/2/21/VC05/024258


Sum Insured: _____ Excess: 700

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value: 85K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: YQ1804E Yr Regn: 2019 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MITSUBISHI CANTER c.c. 2998

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: FEB21EA30335

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: F: 195/85R15Z

R: n n

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or. UWDA

Front: _____ Rear: _____

R/Bal. 7 mm R/Bal. 7/7 mm

L/Bal. 7 mm L/Bal. 7/7 mm

D.O.A. 20/02/21 D.O.I. 25/02/21

Survey held at FALCON AIR

Des. of Damages: ☒ Front / ☐ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Repair limit - 63K</u>
	<u>Finalised lump sum \$25,000 - (Red: 12,170.10 - 32%)</u>

Date/Time, File Pass to?

☐ : Prel. Report

☒ : Final Report

1) _____ Date/Time, File Return to?

2) _____

Days Of Repair: 18

Resurvey No. of Trip: 1

Survey Fee:

Transportation: _____ \$ + RS. _____ SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Rep. Format: OD

Lump Sum / L.S. (\$ 25000/-)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	22/02/2021 14:51 (SGT)
Date of Accident	20/02/2021 17:20 (SGT)
Exact Location of Accident	Jln Bahar, Singapore
Additional Location Information	JALAN BAHAR SLIP ROAD TO JURONG WEST AVE 3
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YQ1804E
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	HYPEX ENGINEERING & SERVICES PTE LTD
Company Reg No	2XXXXX610H
Email Address	TECK@HYPEX.COM.SG
Mobile Phone No	(Phone) +65-98530548
Alternative Phone No	+65-94237632

VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Fuso
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Commercial vehicle

INSURANCE COMPANY

Name of Insurance Company	Lonpac
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	Z20VC05006351
Cover Note Number	-

DRIVER

Name of Driver	CHINNAKOUNDER MUTHU
Passport No/FIN	GXXXX060T
Date Of Birth	04/03/1976
Occupation	Outdoor

Address		-
Address complement		-
Postcode		-
Insurance Company Name		-
Nature Of Damage		-
Details of property damaged in accident		-
No. Of Passenger (Including Driver)		-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GI Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore (GIA) may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the sending of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/postal packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



C. Nanthan



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Jln Bahau slip road to Jurong West Ave 3.



[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	610H
Vehicle Details	
Vehicle No.:	YQ1804E
Vehicle to be Exported:	Yes
Intended Deregistration Date:	22 Feb 2021
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEB21ER4SDEN
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	4P10D93008
Chassis No.:	FEB21EA30335
Maximum Power Output:	-
Open Market Value:	\$37,910.00
Original Registration Date:	14 Nov 2019
First Registration Date:	14 Nov 2019
Transfer Count:	0
Actual ARF Paid:	\$1,896.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	13 Nov 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$26,509.00
COE Rebate Amount:	\$21,207.00
Total Rebate Amount:	\$21,207.00

The information contained herein is correct as at 22 Feb 2021

OK



LONPAC INSURANCE BHD
300 BEACH ROAD, #17-04/07
THE CONCOURSE SINGAPORE 199555

Attention : Motor Claim Department
Contact : 62507388 Fax No. : 62962706

Estimate : ES003741

Date : 24/02/2021
Vehicle Num. : YQ1804E
Make/Model : MITSUBISHI FUSO
Chassis/Eng#: FEB21EA30335
Accident Date : 20/02/2021
Claim No. :
Reference : OD LONPAC
Policy No. : Z20VC05006351

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

PARTS PURCHASED :				
1.	1	FRONT WINDSCREEN GLASS <i>bro</i>		650.00
2.	1	FRONT WINDSCREEN GLASS RUBBER <i>neu</i>		200.00
3.	1	FRONT PANEL CENTRE <i>bt</i>		1,150.00
4.	1	FRONT PANEL CENTRE SUPPORT <i>?-bt</i>		650.00
5.	1	FRONT PANEL EMBLEM FUSO <i>neu</i>		65.00
6.	1	FRONT GRILLE <i>mis</i>		550.00
7.	1	FRONT WIPER PANEL <i>com</i>		396.00
8.	2	FRONT WIPER GARNISH LH/RH <i>com</i>	123.00	246.00
9.	1	WIPER WASHER TANK <i>?-xsuc</i>		125.00 X
10.	1	FRONT WIPER LINKAGE <i>?-bt</i>		650.00
11.	2	WIPER BLADE <i>neu</i>	55.00	110.00
12.	2	WIPER ARM <i>com</i>	95.00	190.00
13.	1	FRONT HEATER ASSY <i>?-bro</i>		1,300.00
14.	2	FRONT HEATER WATER HOSE <i>?-xsuc</i>	20.00	40.00 X
15.	2	FRONT HEATER WATER PIPE <i>?-bt</i>	40.00	80.00
16.	1	AIRCON BLOWER <i>?-com</i>		550.00
17.	1	AIRCON INLET PIPE <i>?-xsuc</i>		450.00 X
18.	1	AIRCON DISCHARGE PIPE <i>?-xsuc</i>		385.00 X
19.	1	DASHBOARD FRONT <i>de</i>		1,482.00
20.	1	DASHBOARD FRAME RH <i>?-bt</i>		180.00
21.	1	DASHBOARD LH FRAME <i>?-bt</i>		316.00
22.	1	DASHBOARD CENTRE LOWER COVER <i>de</i>		285.00
				9050

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 ■ No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

LONPAC INSURANCE BHD
300 BEACH ROAD, #17-04/07
THE CONCOURSE SINGAPORE 199555

Attention : Motor Claim Department
Contact : 62507388 Fax No. : 62962706

Estimate : ES003741

Date : 24/02/2021
Vehicle Num. : YQ1804E
Make/Model : MITSUBISHI FUSO
Chassis/Eng# : FEB21EA30335
Accident Date : 20/02/2021
Claim No. :
Reference : OD LONPAC
Policy No. : Z20VC05006351

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	1	GLOVE BOX ASSY <i>cm</i>		390.00
24.	1	FRONT GLOVE BOX LOWER <i>cut</i>		373.00
25.	1	DASHBOARD RH CORNER COVER <i>? xsrc</i>		117.00 X
26.	1	DASHBOARD LH CORNER COVER <i>src</i>		117.00
27.	1	DASHBOARD LOWER GARNISH LH SIDE <i>? xsrc</i>		255.00 X
28.	2	DASHBOARD SUPPORT LH/RH BRACKET <i>? bt (1pc)</i>	(165.00/-)	330.00 X
29.	1	WIRE HARNESS <i>cut</i>		880.00
30.	1	RH SIDE MIRROR <i>cm</i>		65.00
31.	1	RH SIDE MIRROR BASE <i>bt</i>		165.00
32.	1	RH SIDE MIRROR COVER <i>mis</i>		20.00
33.	1	FRONT DOOR INNER HANDLE RH <i>? bt</i>		369.00
34.	1	FRONT DOOR INDICATOR LAMP RH <i>? xsrc</i>		70.00 X
35.	1	RH FRONT DOOR <i>bt</i>		950.00
36.	1	RH FRONT DOOR WEATHERSTRIP <i>new</i>		200.00
37.	1	RH FRONT DOOR INNER BOARD <i>de</i>		428.00
38.	1	RH FRONT DOOR REGULATOR WITH LOCK <i>? cut</i>		190.00
39.	1	RH FRONT DOOR GLASS RUN/CHANNEL <i>? de</i>		200.00
40.	1	RH FRONT DOOR PILLAR <i>bt</i>		900.00
41.	1	RH FRONT DOOR PILLAR RUBBER <i>de</i>		180.00
42.	1	RH FRONT DOOR PILLAR TOP GARNISH <i>de</i>		42.00
43.	1	LH FRONT DOOR <i>xsrc</i>		950.00 X
44.	1	LH FRONT DOOR RUBBER <i>xnn</i>		180.00 X
45.	1	LH FRONT DOOR PILLAR <i>st</i>		900.00
46.	1	LH FRONT DOOR PILLAR GARNISH <i>xsrc</i>		39.00 X

6534

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

LONPAC INSURANCE BHD
300 BEACH ROAD, #17-04/07
THE CONCOURSE SINGAPORE 199555

Attention : Motor Claim Department
Contact : 62507388 Fax No. : 62962706

Estimate : ES003741

Date : 24/02/2021
Vehicle Num. : YQ1804E
Make/Model : MITSUBISHI FUSO
Chassis/Eng# : FEB21EA30335
Accident Date : 20/02/2021
Claim No. :
Reference : OD LONPAC
Policy No. : Z20VC05006351

S/N	Quantity	Particular	Unit Price	Amount S\$
47.	1	LH FRONT DOOR TRIM BOARD <i>X sul</i>		428.00 X
48.	1	LH FRONT DOOR PILLAR RUBBER <i>X sul</i>		180.00 X
49.	1	LH SIDE MIRROR <i>scr</i>		65.00
50.	1	LH SIDE MIRROR BASE <i>? x sul</i>		165.00 X
51.	1	LH FRONT DOOR MIRROR COVER <i>X sul</i>		20.00 X
52.	1	ROOF PANEL <i>bt - photo</i>		1,086.00
53.	1	ROOF LINING <i>de</i>		760.00
54.	2	ROOF PANEL SUN VISOR LH/RH <i>? x sul</i>	182.00	364.00 X
55.	2	ROOF PANEL SUPPORT LH/RH <i>? LH-bt / RH-sul x</i>	(476.00) ✓	952.00 X
56.	2	ROOF PANEL SUN VISOR CASING LH/RH <i>? cm</i>	340.00	680.00
57.	1	FRONT CABIN BRACKET RH <i>? bt</i>		85.00
58.	1	FRONT CABIN BRACKET LH <i>? bt</i>		495.00
59.	2	FRONT CABIN MOUNTING BUSHING RH/LH <i>? cut</i>	135.00	270.00
60.	2	FRONT CABIN MOUNTING LH/RH <i>? bt</i>	230.00	460.00
61.	1	FRONT INSTRUMENT PANEL ASSY <i>? cm</i>		2,100.00
62.	1	REAR VIEW MIRROR <i>X sul</i>		98.00 X
63.	1	RH SIGNAL LAMP <i>cm</i>		150.00
64.	1	RH FRONT DOOR GLASS <i>X sul</i>		280.00
65.	2	FRONT WINDSCREEN PILLAR GARNISH LH/RH <i>de</i>	88.00	176.00 7083
Total Parts Purchased S\$:				27,174.00
15.00% Of The Above Parts S\$:				4,076.10
Based On Cost Plus S\$:				31,250.10

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

LONPAC INSURANCE BHD
300 BEACH ROAD, #17-04/07
THE CONCOURSE SINGAPORE 199555

Attention : Motor Claim Department

Contact : 62507388 Fax No. : 62962706

Supplementary Estimate : ES003758

Date : 15/03/2021
Vehicle Num. : YQ1804E
Make/Model : MITSUBISHI FUSO
Chassis/Eng# : FEB21EA30335
Accident Date : 20/02/2021
Claim No. :
Reference : OD LONPAC
Policy No. : Z20VC05006351

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	PARTS PURCHASED :		
2.	1	ROOF REINFORCEMENT FRONT		285.00
		FRONT FLOOR TOP PANEL		985.00
		Total Parts Purchased S\$:		1,270.00
		15.00% Of The Above Parts S\$:		190.50
		Based On Cost Plus S\$:		1,460.50

Paul
26/03/21

SingDollars : One Thousand Four Hundred Sixty & Cents Fifty Only

E. & O.E.	Total S\$:	1,460.50
		=====

for FALCON AIR AUTO SERVICES PTE LTD

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 ■ No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



LONPAC INSURANCE BHD
300 BEACH ROAD, #17-04/07
THE CONCOURSE SINGAPORE 199555

Attention : Motor Claim Department
Contact : 62507388 Fax No. : 62962706

Pass
Hp 90010028

18 days

L/S
25/02/2021 @ 1130

EXCESS: 700

REVERT

Resurvey
after
repair

Estimate : ES003741

Date : 24/02/2021
Vehicle Num. : YQ1804E
Make/Model : MITSUBISHI FUSO
Chassis/Eng#: FEB21EA30335
Accident Date : 20/02/2021
Claim No. :
Reference : OD LONPAC
Policy No. : Z20VC05006351

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	SPECIAL NETT ITEMS : ERP IU BRACKET		NEC 20.00
----	---	--	--	-----------

Special Nett Total S\$:

20.00

LABOUR :

(TO REMOVE/ REPLACE FRONT WINDSCREEN GLASS)
(SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER) @180
(TO COMPUTER RESET ECU SYSTEM)
(TO TRANSFER DOOR PARTS (x2 @ \$50))
(TO REMOVE/REPLACE DASHBOARD)
(TO REMOVE/REPLACE / REFIX INSTRUMENT PANEL, STEERING
PEDAL ASSY, METER, AIRCON PARTS, WIRE HARNESS, BRAKE
PIPES, HOSES, WIPER, BLOWER ETC.)
(TO REMOVE/REFIX AIRCON CONDENSER VACUUM & REGAS)
(TO REMOVE/REFIX CUSHION, SEATBELTS, GARNISHES, CARPET
AND REPLACE ROOF LINING)
(TO REMOVE/REPLACE /REFIX CABIN MOUNTING BUSHES
CABIN SHAFT BAR)
TO CUT OUT REWELD AFFECTED DAMAGED PANELS, REPAIR
CABIN, INNERT PANELS INCLUDES PANEL BEATING AND
REPLACEMENT OF PARTS @150

Labour Total S\$:

5,900.00

SingDollars : Thirty-Seven Thousand One Hundred Seventy & Cents Ten Only

E. & O.E.	Total S\$:	37,170.10
-----------	-------------	-----------

for FALCON AIR AUTO SERVICES PTE LTD



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg