

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06351

Vehicle Insured : SKZ4727T
Accident Date : 23-Feb-2021

Date : 24-Feb-2021

Our Ref : 021033 (AIG) / CHAN

PAGE : 1

KONG AH YAN
900 DUNEARN ROAD
#03-12
Singapore 589473

Not Authorized

1/1000 & 3200/

Recovery After Point

4 days

ESTIMATED COST OF REPAIR FOR NISSAN QASHQAI SLP1675U

1 pc Rear bumper fascia
1 pc Rear bumper reinforcement
1 pc Rear bumper sponge
1 pc Rear bumper tow cover
2 pcs Rear bumper reflector
1 pc Rear end panel

@ S\$ 61.90

<i>Per</i>	796.70	n	<i>✓</i>
<i>By</i>	618.20	n	<i>✓</i>
<i>CM</i>	126.40	n	<i>✓</i>
<i>Per</i>	22.00	n	<i>✓</i>
<i>SL</i>	123.80	n	<i>X</i>
<i>By</i>	482.60	n	<i>✓</i>

2,169.70

Less 10% : 216.97

1 pc Rear bumper reverse sensor (4pc *1 set*)
1 pc Rear bumper clip (set)

3500m Shan 1,952.73 *2000*
400.00 sn
nu 50.00 sn *✓*

To remove roof lining, front and rear seats, trim board and carpet

120.00 *600*

To apply undersealing

60.00 *300*

To putty and spray replaced parts

600.00 *4500*

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

700.00 *3000*

Total : S\$ 3,882.73

Singapore Dollars Three Thousand Eight Hundred and Eighty Two and Cents Seventy Three Only

Only to Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: