

Our Job Ref No : 305453938
Date : 21.02.21

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : Mr NAZ
Vehicle Reg No. : SHA2227A CTPL

Fax :

16.02.21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- The repair job shall bill to: CHINA — GBG8377A
- The finalized amount shall be:

(a) Spare Parts after List discount	\$2,626.56
(b) Labour Charges	\$1,300.00
Total for Part-By-Part Repair Cost	\$3,926.56
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: 20%	
Final Lumpsum Repair cost	

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : LIM KWOK ENG
Tel : 62148316
Fax : 65468156

Signature : 
Name : NAZ LKK
Date : 11/03/2021

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

VEHICLE NO. : SHA2227A
MODEL IONIQ(G3)
JOB NO 305453938

TYPE OF CASE : TP-SDS8140D

SURVEY BY : LK/Na3

DATE : 17/02/21

[illegible]

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 16.02.2021
Time: 18:10:03
Page: 1COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755JOB NO : 305453938
REGN NO : SHA2227A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 30.09.2020
DATE/TIME IN : 16.02.2021 10:45
ACCIDENT DATE : 16.02.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	COVER-RR BUMPER#	1 L	459.40	20.00	367.52	/ CRK
0002	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	/ NEC
0003	04-01-0104-2531-G	BRACKET ASSY-RR BUMPER SI	1 L	55.80	20.00	44.64	? XSVL
0004	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1 L	451.25	20.00	361.00	/ CRK
0005	04-01-0104-2544-G	CAP-RR HOOK	1 L	98.80	20.00	79.04	? ✓ part taken - missing / MIS
0006	FNPS	NUMBER PLATE WITH TRIM CO	1 N	55.00	2.00-	55.00	/ CRK
0007	09-01-0104-2133-G	ANTENNA ASSY-SMARTKEY	1 L	40.50	20.00	32.40	? XSVL
0008	04-01-0104-2370-G	LAMP ASSY-REAR FOG	1 L	201.50	20.00	161.20	? XSVL
0009	09-01-9999-0068-A	REVERSE SENSOR ASSY*	1 N	180.00	2.00-	180.00	/ MIS
0010	04-01-0104-2545-G	MOULDING-REAR BUMPER LWR	1 L	155.00	20.00	124.00	? XSVL
0011	04-01-0104-2540-G	COVER-RR BPR UNDER CTR	1 L	225.00	20.00	180.00	/ DEF
Supple Rear Bumper Side under Cover LH - \$108.00 ✓ part taken photo attached / CRK							
Supple Rear Corner Radar unit Assy LH - \$1,625.00 ✓ part taken photo attached / DEF							
SUB-TOTAL						1,602.40	

JOB NATURE

JOB NATURE

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 16.02.2021
Time: 18:10:03
Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305453938
REGN NO : SHA2227A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 30.09.2020
DATE/TIME IN : 16.02.2021 10:4
ACCIDENT DATE : 16.02.2021

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0000 L	PANEL BEATING[repair rr fender Lh]	900.00		700		
1 23-502	SPRAYPAINT ON AFFECTED AREA	550.00		400		500
0002 17-01	CHECK ALL LIGHTING	50.00		30		
0003 20-00	TUFF COAT ON AFFECTED PARTS.	50.00		40		
0004 20-22	REMOVE/REFIX REVERSE SENSOR	120.00		30		
SUB-TOTAL						: 1,670.00
TOTAL						: 3,272.40

AUTHORISED : YES / NO

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

NAZ LKK HP: 98804220
17/2/2021 1540
P/R
3 DAYS
CHECK ITEM PHOTOS
BEFORE PAINT PHOTOS

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 11.03.2021
Time: 12:11:09
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305453938
REGN NO : SHA2227A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 30.09.2020
DATE/TIME IN : 16.02.2021 10:45
ACCIDENT DATE : 16.02.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	COVER-RR BUMPER#	1 L	459.40	20.00	367.52	✓ CRK
0002	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	✓ NEU
0003	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1 L	451.25	20.00	361.00	✓ CRK
0004	04-01-0104-2544-G	CAP-RR HOOK	1 L	98.80	20.00	79.04	✓ MIS
0005	FNPS	NUMBER PLATE WITH TRIM CO	1 N	55.00	2.00-	55.00	✓ CRK
0006	09-01-9999-0068-A	REVERSE SENSOR ASSY*	1 N	180.00	0.20	180.00	✓ MIS
0007	04-01-0104-2546-G	COVER-RR BUMPER SIDE UNDE	1 L	108.00	20.00	86.40	✓ CRK
0008	04-01-0104-2540-G	COVER-RR BPR UNDER CTR	1 L	225.00	20.00	180.00	✓ DEF
0009	09-01-0104-2206-G	UNIT ASSY-REAR CORNER RAD	1 L	1,625.00	20.00	1,300.00	✓ DEF

SUB-TOTAL : 2,626.56

JOB NATURE

2,391.56

0000 L	PANEL BEATING[repair rr fender Lh]	700.00	✓
0001 23-502	SPRAYPAINT ON AFFECTED AREA	500.00	✓

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 11.03.2021
Time: 12:11:09
Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305453938
REGN NO : SHA2227A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 30.09.2020
DATE/TIME IN : 16.02.2021 10:4
ACCIDENT DATE : 16.02.2021

JOB / PARTS DESCRIPTION		QTY IND UNIT-PRICE DISC% AMOUNT	
0002 17-01	CHECK ALL LIGHTING	30.00	✓
0003 20-00	TUFF COAT ON AFFECTED PARTS.	40.00	✓
0004 20-22	REMOVE/REFIX REVERSE SENSOR	30.00	✓
		SUB-TOTAL : 1,300.00	
		TOTAL : 3,926.56	

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :