



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2102985

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 29/04/2021  
Reference CC3/CTI21002594/Grs3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SHC 8247S  
Insured Veh. SKB 5264G  
Claim No. SNM21D200948/LKKDS  
Policy No. DMPCSNW00149952002  
Accident Date 17/02/2021  
Inspection Date 18/02/2021

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI21002594/Grs3q2 Date: 29/04/2021 Code: CTI	
<b>1. Policy Particulars :- THIRD PARTY (FOLLOW THROUGH INSPECTION)</b>				
Insured Veh.	SKB 5264G	Veh. Inspected	SHC 8247S	
Policy No.	DMPCSNW00149952002	Coverage (\$)	0.00	
Claim No.	SNM21D200948/LKKDS	Excess (\$)	0.00	
Assign From		Assign Date	18/02/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HYUNDAI IONIQ1.6	c.c	1580	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	KMHC851CVLU192685	Colour	BLUE	
Odometer	7325 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MICHELIN	9 mm	
L/H Front Tyre	195/65 R15	MICHELIN	9 mm	
R/H Rear Tyre	195/65 R15	MICHELIN	9 mm	
L/H Rear Tyre	195/65 R15	MICHELIN	9 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	17/02/2021	Inspection Date	18/02/2021	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8247S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	459.40	-
1	REAR BUMPER CTR MOULDING	DEFORMED	451.25	451.25
1	REAR BUMPER BEAM	NOT NECESSARY	394.80	-
1	REAR BUMPER LWR MOULDING	NOT NECESSARY	155.00	-
1	REAR BUMPER TOW COVER	NOT NECESSARY	98.80	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER FOGLAMP	NOT NECESSARY	201.50	-
	LESS 20% DISCOUNT		-356.55	-94.65
			1,426.20	378.60
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REVERSE SENSOR (SN)	NOT NECESSARY	180.00	-
1	REAR BUMPER MAT (SN)	NOT NECESSARY	50.00	-
1	REAR NO PLATE W/TRIM COVER (SN)	CRACKED	55.00	55.00
			285.00	55.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER .		400.00	350.00
	SPRAYPAINT CHARGE.		300.00	250.00
	R/I REVERSE SENSOR .		120.00	40.00
			820.00	640.00
	<b>GRAND TOTAL</b>		<b>2,531.20</b>	<b>1,073.60</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>1,073.60</b>

Report Ref No. CC3/CTI21002594/Grs3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SHC 8247S

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SHC 8247S

### RE-INSPECTION

