

LCRF PTE LTD
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms: China Taiping Insurance (Singapore) Pte Ltd

Date: 23/02/2021

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLU9808A

CHASSIS NO : NHP1707068033

MAKE / MODEL : Toyota Sienta Hybrid 1.5X CVT

DATE OF ACCIDENT : 22/02/2021

YOUR INSURED VEHICLE NUMBER : SLZ753G

MILEAGE : 165938 km

	PARTS DESCRIPTION	QTY	UNIT PRICE	LIST PRICE
1	Rear tailgate / <i>DD</i>	1PC	\$1,879.00	\$1,879.00 <i>1,180</i>
2	Rear tailgate weatherstrip / <i>CNY</i>	1PC	\$432.00	\$432.00 <i>389</i>
3	Rear tailgate lock / <i>Turn</i>	1PC	\$504.00	\$504.00 <i>318.67</i>
4	Rear tailgate lock catch <i>X Svc</i>	1PC	\$64.80	\$64.80 <i>X</i>
7	Rear tailgate center garnish <i>X Svc</i>	1PC	\$342.00	\$342.00 <i>X</i>
8	Rear tailgate Toyota logo / <i>NK</i>	1PC	\$60.00	\$60.00 <i>/</i>
9	Rear tailgate emblem 'Hybrid' / <i>NK</i>	1PC	\$86.80	\$86.80 <i>/</i>
10	Rear end panel / <i>DD</i>	1PC	\$828.00	\$828.00 <i>502</i>
11	Rear end panel lower <i>X Svc</i>	1PC	\$633.60	\$633.60 <i>X</i>
12	Rear end panel top garnish / <i>CNY</i>	1PC	\$250.00	\$250.00 <i>208</i>
13	Rear bumper reinforcement <i>X Svc</i>	1PC	\$338.10	\$338.10 <i>X</i>
14	Rear bumper sponge <i>X Svc</i>	1PC	\$157.50	\$157.50 <i>X</i>
15	Rear bumper <i>X R</i>	1PC	\$1,257.83	\$1,257.83 <i>X</i>
16	Rear bumper RH retainer <i>X Svc</i>	1PC	\$67.05	\$67.05 <i>X</i>
17	Rear bumper RH seal <i>X Svc</i>	1PC	\$104.40	\$104.40 <i>X</i>
18	Rear bumper RH support <i>X Svc</i>	1PC	\$88.05	\$88.05 <i>X</i>
19	Rear bumper LH extension <i>X Svc</i>	1PC	\$216.00	\$216.00 <i>X</i>
20	Rear bumper RH extension <i>X Svc</i>	1PC	\$216.00	\$216.00 <i>X</i>
21	Rear bumper center extension / <i>CNY</i>	1PC	\$288.00	\$288.00 <i>209</i>
22	Rear bumper pad <i>X Svc</i>	1PC	\$64.80	\$64.80 <i>X</i>
23	Rear bumper RH reflector <i>X Svc</i>	1PC	\$93.60	\$93.60 <i>X</i>
24	Rear bumper LH reflector <i>X Svc</i>	1PC	\$93.60	\$93.60 <i>X</i>

LIST TOTAL S\$: \$8,065.13
25.00% DISCOUNT S\$: \$2,016.28
\$6,048.85

2,953.47
- 25%
2,215.10

SPECIAL NETT

1	Bumper clips / <i>NK</i>	1 SET	\$80.00	<i>70</i>
2	Reverse sensor / <i>Shut</i>	1 SET	\$260.00	<i>200</i>
3	Windscreen sealant / <i>NK</i>	1PC	\$100.00	<i>50</i>
4	Body sealant / <i>NK</i>	1PC	\$300.00	<i>50</i>
Special Nett Total S\$:			\$740.00	<i>330</i>

LABOUR CHARGES

- | | | | |
|---|---|------------|-----|
| 1 | To remove and install rear tailgate glass | \$120.00 | / |
| 2 | Transfer tailgate mechanism | \$100.00 | 60 |
| 3 | To labour charge for removing rear tailgate, rear bumper, end panel and spare tyre panel out to facilitate repairs and replacement of damaged parts | \$1,000.00 | 750 |
| 4 | To respray rear tailgate, rear end | \$1,000.00 | 650 |
| 5 | To conduct a standard of operating | \$300.00 | X |

LABOUR TOTAL S\$:	\$2,520.00	1,580.
TOTAL S\$:	\$9,308.85	
7% GST	\$651.62	
GRAND TOTAL S\$:	<u>\$9,960.47</u>	

Repair day - 4 days

~~by~~ P/P

Inter ~~After~~ part photo

25/02/2024

Sun Pin (4rb)

TP with prejudice

2,215.10
330
1,580
<u>4,125.10</u>

P/P
\$4,125.10
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: