

ASS. REC. BY:

REF:

C31A16 21002597/A+f3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

2070173466

Claims No.

5223387286

Sum Insured:

Excess:

3600

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07/8/1 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMW8123B

Yr Regn:

2010, Dec.

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi Q2

C.C

1395

Colour

Red.

A/C: Insured / Std / NI / NA

Sp. Reading

2622

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAUZZ2GA3LA064870

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R17.

R:

215/55R17.

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

24/02/21

Survey held at

Premium.

Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OD A16.

Confirm final figure @ \$9653.72 @ 7 days

MV: 140K

PV: 663K

Nett: 73.7K

Red: 26221

Red: 17067.28 (63%)

Days Of Repair: 7

Resurvey No. of Trip:

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

Formet:

9653.72

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0168/2021/TF
DATE : 24-Feb-21
WIP : 16782

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 24/2/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. LI HANCHAO
ADDRESS : BLK 678C JURONG WEST ST 64
#08-341
SINGAPORE 643678
TELEPHONE : HP +65 82998305
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070173466
VEHICLE NO : **SMW 8123 B**
MODEL CODE : AUDI Q2 SPORT 1.4 TFSI COD
MODEL YEAR : 11/12/2020
ENGINE NO : CZE 867545
CHASSIS NO : WAUZZZGA3LA064870
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Feb-21
PLACE OF ACCIDENT : ALONG BUKIT TIMAH ROAD

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMW 8123 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNITS AND POWER MODULES.	S/N \$ 800.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHTS. TO REPAIR BONNET. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,600.00	500 ✓
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BONNET, AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 3,800.00	1775 1675 Bumper 550 Bonnet 550 Spoiler 275 Arch Trim = 200x2 = 4
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		\$ 6,752.00	167

Paint Protection per piece \$1.50

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 8123 B

S/N	PARTS DESCRIPTION	QTY		DAMAGED PARTS & PRICES	
				S/NETT	REMARKS
1	FRONT BUMPER <i>Repair</i>	1	\$	1,936.00	X
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$	347.00	X
3	FRONT BUMPER LOWER GRILLE - CENTER <i>new</i>	1	\$	407.00	✓ 325.20
4	FRONT BUMPER SILVER TRIM - LOWER CENTER <i>cut</i>	1	\$	356.00	✓ 284.40
5	FRONT BUMPER AIR GRILLE - LH / RH <i>RH cut</i>	2	\$	684.00	342 - 273.20
6	FRONT BUMPER SILVER TRIM - LH / RH <i>RH cut</i>	2	\$	446.00	223 - 178.40
7	FRONT BUMPER AIR GRILLE END CAP - LH / RH <i>Not new</i>	2	\$	226.00	X
8	FRONT BUMPER SPOILER <i>Repair</i>	1	\$	536.00	X
9	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>new</i>	1	\$	156.00	X
10	FRONT WHEEL SPOILER - LH / RH <i>new</i>	2	\$	68.00	X
11	FRONT WHEEL HOUSING LINER TRIM - LH / RH <i>new</i>	2	\$	66.00	X
12	FRONT RADIATOR GRILLE <i>changed</i>	1	\$	1,411.00	✓ 1128.80
13	FRONT RADIATOR GRILLE STRIKER PLATE <i>Not new</i>	1	\$	124.00	X
14	FRONT BUMPER CARRIER <i>Not new</i>	1	\$	723.00	X
15	FRONT BUMPER CARRIER FORM FILLER PIECE <i>Not new</i>	1	\$	78.00	X
16	FRONT BUMPER TOP COVER <i>changed</i>	1	\$	100.00	✓ 80
17	CAUTION STICKER <i>new</i>	1	\$	14.00	✓ 10.88
18	A/C STICKER	1	\$	8.00	✓ 5.68
19	HORN - LH / RH <i>new</i>	2	\$	466.00	X
20	HORN BRACKET - LH / RH <i>new</i>	2	\$	62.00	X
			:	\$	8,214.00

SUB TOTAL SPARE PARTS

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



45 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6342 1183
 EMAIL : NICHOL KHALI@PREMIUM, MAIL TO : COMESQ / CLAIMS@PREMIUMMAIL TO : COMESQ

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 8123 B

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	HEADLIGHT MOUNTING - LH / RH <i>new</i>	2	\$	236.00	+
22	HEADLIGHT - LH / RH <i>new</i>	2	\$	9,830.00	+
23	HEADLIGHT LIFT CYLINDER - LH / RH <i>new</i>	2	\$	284.00	+
24	FRONT BONNET IMPACT PROTECTION - LH / CENTER / RH <i>new</i>	3	\$	90.00	+
25	FRONT BUMPER TEMPERATURE SENSOR - EXTERNAL <i>new</i>	1	\$	59.00	+
26	FRONT RADIATOR AIR GUIDE - LH / RH <i>new</i>	1	\$	76.00	+
27	FRONT RADIATOR AIR GUIDE - UPPER CENTRE <i>new</i>	1	\$	22.00	17.20
28	FRONT WHEEL ARCH COVER - LH / RH <i>new</i>	1	\$	848.00	618.40
29	FRONT NO. PLATE <i>Dented</i>	S/N	\$	60.00	60
30	SUNDRIES <i>new</i>		\$	250.00	?
TOTAL SPARE PARTS			:	\$	19,969.00
TOTAL LABOUR CHARGES			:	\$	6,752.00
GRAND TOTAL			:	\$	26,721.00

17.20
 618.40
 60
 14.72

ALL CHARGES ARE INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

EMIUM AUTOMOBILES



ROAD 1, SINGAPORE 408699
6366 2323 FAX: 6841 1183
AIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian King
SURVEYED DATE : 24/02/10
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 04 Days *7 days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

18/3/21 wip: 16782
kiam/choi



Adrian

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 8123 B

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Rep</i>	1	\$ 1,936.00	X
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 347.00	X
3	FRONT BUMPER LOWER GRILLE - CENTER <i>new</i>	1	\$ 407.00	✓
4	FRONT BUMPER SILVER TRIM - LOWER CENTER <i>at</i>	1	\$ 356.00	✓
5	FRONT BUMPER AIR GRILLE - LH / RH <i>RH at</i>	2	\$ 684.00	342
6	FRONT BUMPER SILVER TRIM - LH / RH <i>RH at</i>	2	\$ 446.00	223
7	FRONT BUMPER AIR GRILLE END CAP - LH / RH	2	\$ 226.00	?
8	FRONT BUMPER SPOILER <i>Rep</i>	1	\$ 536.00	X
9	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>at</i>	1	\$ 156.00	X
10	FRONT WHEEL SPOILER - LH / RH <i>new</i>	2	\$ 68.00	X
11	FRONT WHEEL HOUSING LINER TRIM - LH / RH <i>new</i>	2	\$ 66.00	X
12	FRONT RADIATOR GRILLE <i>could</i>	1	\$ 1,411.00	✓
13	FRONT RADIATOR GRILLE STRIKER PLATE	1	\$ 124.00	?
14	FRONT BUMPER CARRIER	1	\$ 723.00	?
15	FRONT BUMPER CARRIER FORM FILLER PIECE <i>? can</i>	1	\$ 78.00	?
16	FRONT BUMPER TOP COVER <i>could</i>	1	\$ 100.00	✓
17	CAUTION STICKER	1	\$ 14.00	✓
18	A/C STICKER <i>new</i>	1	\$ 8.00	✓
19	HORN - LH / RH	2	\$ 466.00	X
20	HORN BRACKET - LH / RH <i>new</i>	2	\$ 62.00	X
SUB TOTAL SPARE PARTS			\$ 8,214.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Paul
19/03/21



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0168/2021/TF
DATE : 24-Feb-21
WIP : 16782

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 24/2/21

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

7 days - ok - by 23 Feb 21

OWNER'S NAME : MR. LI HANCHAO
ADDRESS : BLK 678C JURONG WEST ST 64
#08-341
SINGAPORE 643678
TELEPHONE : HP +65 82998305
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070173466
VEHICLE NO : SMW 8123 B
MODEL CODE : AUDI Q2 SPORT 1.4 TFSI COD
MODEL YEAR : 11/12/2020
ENGINE NO : CZE 867545
CHASSIS NO : WAUZZZGA3LA064870
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Feb-21
PLACE OF ACCIDENT : ALONG BUKIT TIMAH ROAD

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMW 8123 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNITS AND POWER MODULES.	S/N \$ 800.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHTS. TO REPAIR BONNET. RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.	\$ 1,600.00	\$ 500.00
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BONNET, AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 3,800.00	\$ 1,775.00
	SUPPLEMENTARY		\$ 2,650.00
	SUPPLEMENTARY		\$ 100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 6,752.00	\$ 5,217.00

PREMIUM AUTOMOBILES



45 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 8123 B

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 1,936.00		
2	FRONT BUMPER FIXING PARTS	1	\$ 347.00		
3	FRONT BUMPER LOWER GRILLE - CENTER	1	\$ 407.00	\$ 325.20	
4	FRONT BUMPER SILVER TRIM - LOWER CENTER	1	\$ 356.00	\$ 284.40	
5	FRONT BUMPER AIR GRILLE - LH / RH	2	\$ 684.00	\$ 273.20	
6	FRONT BUMPER SILVER TRIM - LH / RH	2	\$ 446.00	\$ 178.40	
7	FRONT BUMPER AIR GRILLE END CAP - LH / RH	2	\$ 226.00		
8	FRONT BUMPER SPOILER	1	\$ 536.00		
9	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 156.00		
10	FRONT WHEEL SPOILER - LH / RH	2	\$ 68.00		
11	FRONT WHEEL HOUSING LINER TRIM - LH / RH	2	\$ 66.00		
12	FRONT RADIATOR GRILLE	1	\$ 1,411.00	\$ 1,128.80	
13	FRONT RADIATOR GRILLE STRIKER PLATE	1	\$ 124.00		
14	FRONT BUMPER CARRIER	1	\$ 723.00		
15	FRONT BUMPER CARRIER FORM FILLER PIECE	1	\$ 78.00		
16	FRONT BUMPER TOP COVER	1	\$ 100.00	\$ 80.00	
17	CAUTION STICKER	1	\$ 14.00	\$ 10.88	
18	A/C STICKER	1	\$ 8.00	\$ 5.68	
19	HORN - LH / RH	2	\$ 466.00		
20	HORN BRACKET - LH / RH	2	\$ 62.00		
SUB TOTAL SPARE PARTS		:	\$ 8,214.00	\$ 2,286.56	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

ALL CHARGES ARE NOT INCLUSIVE OF GST

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

REMARKS (ON) - APPROVED
SPARE PARTS ARE SPECIAL NETT.