

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0168/2021/TF
DATE : 24-Feb-21
WIP : 16782

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 24/2/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. LI HANCHAO
ADDRESS : BLK 678C JURONG WEST ST 64
#08-341
SINGAPORE 643678
TELEPHONE : HP +65 82998305
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070173466
VEHICLE NO : **SMW 8123 B**
MODEL CODE : AUDI Q2 SPORT 1.4 TFSI COD
MODEL YEAR : 11/12/2020
ENGINE NO : CZE 867545
CHASSIS NO : WAUZZZGA3LA064870
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Feb-21
PLACE OF ACCIDENT : ALONG BUKIT TIMAH ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMW 8123 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNITS AND POWER MODULES.	S/N \$ 800.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHTS. TO REPAIR BONNET. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,600.00	500 ✓
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BONNET, AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 3,800.00	Bumper 550 Bonnet 550 Spoiler 275 Arch Trim = 200 x 2 = 400 1675
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		\$ 6,752.00	

Paint Protection per piece \$1.50

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 8123 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Rep</i>	1	\$ 1,936.00	X	
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 347.00	f	
3	FRONT BUMPER LOWER GRILLE - CENTER <i>new</i>	1	\$ CRACKED 407.00	✓	325.20
4	FRONT BUMPER SILVER TRIM - LOWER CENTER <i>cut</i>	1	\$ 356.00	✓	284.40
5	FRONT BUMPER AIR GRILLE - LH / RH <i>RH cut</i>	2	\$ 684.00	✓	342 - 273.20
6	FRONT BUMPER SILVER TRIM - LH / RH <i>RH cut</i>	2	\$ 446.00	✓	223. 178.40
7	FRONT BUMPER AIR GRILLE END CAP - LH / RH <i>new</i>	2	\$ 226.00	X	
8	FRONT BUMPER SPOILER <i>Rep</i>	1	\$ 536.00	X	
9	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>new</i>	1	\$ 156.00	X	
10	FRONT WHEEL SPOILER - LH / RH <i>new</i>	2	\$ 68.00	X	
11	FRONT WHEEL HOUSING LINER TRIM - LH / RH <i>new</i>	2	\$ 66.00	X	
12	FRONT RADIATOR GRILLE <i>new</i>	1	\$ 1,411.00	✓	1128.80
13	FRONT RADIATOR GRILLE STRIKER PLATE <i>new</i>	1	\$ 124.00	X	
14	FRONT BUMPER CARRIER <i>new</i>	1	\$ 723.00	X	
15	FRONT BUMPER CARRIER FORM FILLER PIECE <i>new</i>	1	\$ 78.00	X	
16	FRONT BUMPER TOP COVER <i>new</i>	1	\$ 100.00	✓	80
17	CAUTION STICKER <i>new</i>	1	\$ 14.00	✓	10.88
18	A/C STICKER <i>new</i>	1	\$ 8.00	✓	5.68
19	HORN - LH / RH <i>new</i>	2	\$ 466.00	X	
20	HORN BRACKET - LH / RH <i>new</i>	2	\$ 62.00	X	
SUB TOTAL SPARE PARTS		:	\$ 8,214.00		

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 8123 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	HEADLIGHT MOUNTING - LH / RH <i>new</i>	2	\$ 236.00	+
22	HEADLIGHT - LH / RH <i>new</i>	2	\$ 9,830.00	+
23	HEADLIGHT LIFT CYLINDER - LH / RH <i>new</i>	2	\$ 284.00	+
24	FRONT BONNET INPACT PROTECTION - LH / CENTER / RH <i>2mp</i>	3	\$ 90.00	+
25	FRONT BUMPER TEMPERATURE SENSOR - EXTERNAL <i>1m</i>	1	\$ 59.00	+
26	FRONT RADIATOR AIR GUIDE - LH / RH <i>new</i>	1	\$ 76.00	+
27	FRONT RADIATOR AIR GUIDE - UPPER CENTRE <i>could</i>	1	\$ 22.00	17.20
28	FRONT WHEEL ARCH COVER - LH / RH <i>new</i>	1	\$ 848.00	678.40
29	FRONT NO. PLATE <i>Dented</i>	S/N	\$ 60.00	60
30	SUNDRIES <i>new</i>		\$ 250.00	? 74.72
TOTAL SPARE PARTS		:	\$ 19,969.00	
TOTAL LABOUR CHARGES		:	\$ 6,752.00	
GRAND TOTAL		:	\$ 26,721.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian King
24/02/10

Not Authorised, 04 Days

7 days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT