PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers Correspondence Mail Address: My Mail Box 886259 Singapore 919191. Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No.: PAS/TP/0090221

Date of Report

: 15/02/2021

To: M/s. Forte Auto Leasing Pte Ltd

Date of Assignment : 02/02/2021

C/o. 53, Ubi Ave 1, #05-44

Date of Accident

Report requested by : M/s. Forte Auto Leasing Pte I

Paya Ubi Industrial Park Singapore 408934

Date of Inspection

: 31/01/2021 : 02/02/2021

Claim No.

: Third Party Claim

Policy No.

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No.

: SLF5098L

Engine Capacity (cc) : 1496cc

计回线 医电流 整一门的 网络沙丘鸡鸡属属鸡鸡

Make & Model

: Mazda 2

Mileage (km)

: 253155km

Date of Registration

: 29/08/2016

Chassis / Frame No. : MM6DL2SAAGW209201

医多种毒素

Colour

: Met. Silver

Engine No.

: P520360046

TYRE CONDITION

Front LH Make

· 7 mm : Firenza Front RH

: 7 mm

Make

: Firenza

Rear LH

: 8 mm

Rear RH

: 8 mm

Make

: Firenza

Make

: Firenza

Road wheels Type: Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork

: Good

Paintwork

Good

Handbrake

Serviceable

Footbrake

Serviceable

Steering

Serviceable

Apparent Engine Modification

: Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

:---- --- M/s. Neo Automotive Pte Ltd

53. Ubi Ave 1, #05-44. Paya Ubi Industrial Park, Singapore 408934

ASSESSMENT

Repairer's Estimate

6,302.56

Revised Amount

7,612.00

Less Excess

\$: \$

Recommended Reserve

S

(Lump Sum) 5,040.00

Estimated Normal Period of Repairs

: 7 Working Days

Disclaimer: The information contained in this report is intended for exclusive use of the addresses (including any attachments) solely in relation to the loss occurrence in which the assessed vehicle involved. It is confidential and may protected by legal privileged. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party. If you are not the intended recipient, please contact us immediately to arrange for its return and you should not disseminate, distribute, copy any information contained herein or use of this communication is strictly prohibited.

Qualified Loss Adjusters And Motor Appraisers
Correspondence Mail Address: My Mail Box 886259 Singapore 919191.
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No: SLF5098L

Report No.: PAS/TP/0090221

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. Neo Automotive Pte Ltd, 53, Ubi Ave 1, #05-44, Paya Ubi Industrial Park, Singapore 408934.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the rear portion.

DAMAGES

The boot lid, rear bumper, rear end panel, rear floor panel, rear chassis members, rear fenders, taillamps, rear reflectors, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$6,302.56.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$5,040.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

ery in a state of a general control of the season of a first control of

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd

Andrew How

Automobile Appraiser

MSAAA

Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No: SLF5098L

Report No.: PAS/TP/0090221

<u>APPRAISEMENT SCHEDULE</u>

1	1	Boot lid	Dented/Distorted			\$	862.40	\$	862.4
2		Boot hinge R/L	Bent/Repair	\$	127.60	\$	255.20	\$	-
3		Boot emblem (Logo)	Necessary	-		\$	62.30	\$	62.3
<i>3</i>		Boot emblem (Mazda 2)	Necessary			\$	61.40	\$	61.4
5		Boot reflector lamp R/L	Broken/Defaced	\$	231.70	\$	463.40	\$	463.4
6	4	Boot lock	Bent			\$	181.80	\$	181.8
7		Boot inner trim lining	Refit			\$	288.10	\$	-
8		Boot weatherstrip	Torn/Necessary			\$	133.60	\$	133.6
9		Taillamp R/L	Cracked	\$	397.20	\$	794.40	\$	794.
10	-	Rr bumper	Dented/Deformed			\$	931.70	\$	931.
11		Rr bumper reflector lamp R/L	RH Cracked	\$	52.70	\$	105.40	\$	52.
12		Rr bumper clip	Necessary	\$	3.20	\$	22.40	\$	22.
13		Rr bumper retainer R/L	Cracked/Necessary	\$	28.30	\$	56.60	\$	56.
14	•	Rr bumper stay R/L	Necessary	S	18.20	\$	36.40	\$	36.
15		Rr end panel	Dented/Distorted			\$	657.10	\$	657.
16		Rr end panel trim garnish	Dented/Deformed			\$	82.00	\$	82.
17		Rr spare tyre board cover	Serviceable			\$	278.30	\$	-
18	•	Rr fender inner trim R/L	Cracked/Deformed	\$	198.20	\$	396.40	\$	396.
19	•	Rr fender inner trim clip R/L	Necessary	\$	2.80	\$	33.60	\$	33.
20		Rr fender R/L	Dented/Repair	-			(Refer	labour no	, 3, 5 &
20 21		Rr floor panel	Dented/Repair				(Refer	labour no	. 3, 5 &
22		Rr chassis member R/L	Dented/Repair				•	labour no	
	•					\$	5,702.50	\$	4,828
				Less	Discount: 20%	\$	1,140.50	20%_\$	965
			List	Parts S	Sub-Total:	\$	4,562.00	-\$	3,862
1	l set	Rr reverse sensor	Dented/Damaged		S/N	S	200.00	\$	200
2	1 pc	Rr end panel sealant	Necessary		S/N	\$	50.00	\$	40
	•	•	Specia	1 Nett S	Sub-Total :	\$	250.00	\$	240

\$ 4,812.00 Parts Total:



PROMINENT APPRAISER SERVICES PTE LTD Qualified Loss Adjusters And Motor Appraisers Correspondence Mail Address: My Mail Box 886259 Singapore 919191. Mobile: 9295 2204 Fax: 6722 8508 Email: pasvos@hotmail.com Business Reg. 201404434D

Vehic	le No : SLF5098L		Report No.	: PAS/T	P/0090221
S/No.	Labour Descriptions		nairer's imate (S\$)		ur nent (S\$)
1	To remove and reinstall electrical wiring system for necessary repairs. To check rear electrical wiring system.	. \$	60.00	\$	50.00
2	To transfer boot component parts to new boot.	\$	100.00	S	80.00
3	To remove and reinstall rear interior trims, garnishes, etc. for necessary repairs.	\$	100.00	\$	80,00
4	To remove, replace and reinstall rear reverse sensors & control unit.	\$	50.00	: :== s	₹ 50.00
5	To straighten, repair, realign on affected area and replace damaged parts.	s	1,200.00	\$	880.00
6	To spray painting, blending on affected and adjacent area.	\$	1,200.00	\$	1,000.00
7	To spray anti-rust coating on new and affected panels.	\$	90.00	\$	60.00
	Labour Total :	\$	2,800.00	\$	2,200.00

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is ___\$__

Under normal circumstances, the repairs should be completed within a reasonable period

7 Working Days. (Exclude waiting days of PRI, Sunday, Pubic Holiday and awaiting of shipment for spare parts)

Photographs were taken at the time of inspection. 90

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall has the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.



Police Station Of Origin: Marine Parade N.P.C 300 Marine Parade Road SINGAPORE 449296

2 of 3 Report No. T/20210201/2080

Tel No: 1800-4428999

CONTINUATION OF REPORT

Driver						
Nante	SU SOOI HONG			ID No		S2585873E
Related Vehicle	NIL		Contact No.		93875538	
Hospital/Clinic FAITH FAMILYCLINIC				Class Driving Licent Expiry	g ce &	Class: NIL Date of Expiry: NIL
Date Treatment	01/02/2021		Date Disc			2/2021
No. of Days granted Medical Leave 07			Degree of Injury NIL			
Driver 7			and the second			Sente. El Spalle and Albert Spanio
Name	Veerappan Azhagapp	oan		ID No		G6911851N
Related Vehicle NIL			the programme is the contract of the contract	Contact No.		94499257
Hospital/Clinic	NIL			Class of Driving Licence & Expiry Date		Class: NIL Date of Expiry: NIL
Date Treatment	NIL	· · · · · · · · · · · · · · · · · · ·	Date Disci		NIL	
No. of Days gran	ted Medical Leave	NIL	Degree of		NIL	

Brief Details.

On 31.01.2021 at about 1555hrs I was driving (SLF5098L) on the 4th lane from Lornie Highway toward CTE. I was driving alone, and I was about to fetch my passenger at Bishan.

While I was driving suddenly there was an impact and my car more forward, we then stepped out from the car and discovered that there is a lorry (YM7842B) from the rear had collided with my car. I then make a checked and there was a scratch mark centre bumper and left side, dislocate on the left and right side of the car from the original position. There is no damage on the lorry. We exchange particular and drove off and I would like to state there were two passengers in his car and there is no police or ambulance at scene. There is no in car camera in my car.

On 01/02/2021 I felt pain on my neck, shoulder and back of my body, I went to the doctor and I was given 7 days medical certification,





Police Station Of Origin; Marine Parade N.P.C 300 Marine Parade Road SINGAPORE 449296

1 of 3 Report No. T/20210201/2080

Tel No: 1800-4428999

PERCETOE	A TRAFFIC	ACCIDENT
REPORT OF	A IKAFFIC	ACCIDENT

Date/Time 01/02/202	•	ade:	Vide Report No.:	Station Diary No.: 31	
linforman	S Partici	lars.			
Name of I	nformant:		Address:	RACE #11-242 SINGAPORE 440007	
ID Type / NRIC NO		'3E	Contact No.: Home/Office: Mobile: 93875538		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Age: Date of Birth: Female 61 13/12/1959			Type of Informant: Driver		
Race: Chinese			Language:	Institution / School Name:	
Occupation GRAB DR			Driving Licence Informatio Class:	on; Date of Expiry;	

Type of Accident:	Injury Others	dent Drink Drive: No	Date/Time of Accident: 31/01/2021 15:55	Type of Location: Straight Road
Location:				<u></u>
LORNIE ROA	AD.			
Weather:		Road Surface:	R	oad Speed Limit:
		Wet	i	
Drizzling		ivvet	1	
Drizzling Traffic Flow: One Way		Traffic Control; Not Controlled	1	raffic Volume: ght

Details of V	ehicle Involved						
Vehicle No.	Type	Make	Model	1. J	Color	Condition	No of Passenger
SLF5098L	Car					Slightly	0
144.50.400						Damaged	
YM78428	Lorry					No	2
		<u> </u>	<u> </u>			Damage	

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL.	Use of Pedestrian Crossing: NA





Police Station Of Origin: Marine Parade N.P.C 300 Marine Parade Road SINGAPORE 449296 3 of 3 Report No. T/20210201/2080

Tel No: 1800-4428999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the <u>report number</u> as reference.

Signature Of Officer Recording The Report: G / Sr Staff Sgt SALINA BINTETSMAH.	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 01/02/2021 15:01
Officer In Charge Of Case: TP-I-AEIT-I-Sgt & NUMBER SIZWAN BIN KAMALUDIN	Classification Of Case:
Authentication Stamp NP 68 SIGNECURE	