

Ullucialia

Not Authorized
Labour around
2/3/21 4 days.



1st Auto Pro Pte Ltd

We Believe In Service

8 KAKI BUKIT AVENUE 4 PREMIER @ KAKI BUKIT #01-49 & #01-51/52 SINGAPORE 415875

Tel : 9188 3197 / 8614 6767 | Email: christina@1ap.com.sg

1/5 \$2650 /
Weight Afternoon

ESTIMATION QUOTE

AXA INSURANCE PTE LTD
8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811
ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : SGS1582Y
MAKE MODEL : HONDA CIVIC
REFERENCE : 1AP-202102-05
DOA : 03-Feb-21
CLAIM TYPE : TP CLAIM

PAGE 1 OF 2

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
REAR BUMPER <i>Sport</i>	1	\$ 717.00	Dis ✓
REAR BUMPER REINFORCEMENT	1	\$ 268.00	NSX
REAR BUMPER RETAINER <i>30.50</i>	2	\$ 68.00	N/S sent PC
REAR BUMPER BRACKET	2	\$ 78.00	NSX
REAR BUMPER REFLECTOR WITH COVER LH	1	\$ 75.00	NSX
REAR BUMPER REFLECTOR WITH COVER RH	1	\$ 75.00	NSX
REAR BUMPER INNER SIDE COVER LH	1	\$ 90.00	NSX
REAR BUMPER INNER SIDE COVER RH	1	\$ 90.00	NSX
END PANEL <i>316.20</i>	1	\$ 545.00	DD ✓
END PANEL TOP GARNISH <i>80.60</i>	1	\$ 119.00	Re ✓
REAR TAILLAMP LH <i>285.50</i>	1	\$ 382.00	Re ✓
REAR TAILLAMP RH	1	\$ 382.00	NSX
BOOTLID LAMP LH	1	\$ 255.00	NSX
BOOTLID LAMP RH	1	\$ 255.00	NSX
BOOTLID	1	\$ 687.00	NSX
BOOTLID LOCK	1	\$ 95.00	NSX
BOOTLID LOCK STRIKER	1	\$ 56.00	NSX
BOOTLID OUTER GARNISH	1	\$ 215.00	NSX
BOOTLID WEATHERSTRIP	1	\$ 119.00	NSX
BOOTLID EMBLEM -CIVIC	1	\$ 41.00	NSX
BOOTLID EMBLEM -I VTEC	1	\$ 42.00	NSX
BOOTLID LOGO	1	\$ 38.00	NSX
BOOTLID HINGE	2	\$ 102.00	NSX
SPARE TYRE TOP BOARD	1	\$ 115.00	NSX
REAR EXHAUST	1	\$ 810.00	NSX
REAR EXHAUST HEAT SHIELD	1	\$ 95.00	NSX
EXHAUST MOUNTING	2	\$ 50.00	NSX

\$ 5,864.00
 LESS 20% \$ 1,172.80
 SUBTOTAL \$ 4,691.20
 BALANCE C/F \$ 4,691.20

ESTIMATION QUOTE

AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #24-01 AXA TOWER
 SINGAPORE 068811
 ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : SGS1582Y
MAKE MODEL : HONDA CIVIC
REFERENCE : 1AP-202102-05
DOA : 03-Feb-21
CLAIM TYPE : TP CLAIM

PAGE 2 OF 2

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
BALANCE B/F		\$ 4,691.20	
REAR BUMPER LOWER GARNISH <i>spoiler</i>	1	\$ 600.00	✓
REAR BUMPER CLIP	1 SET	\$ 30.00	✓
BOOTLID INNER TIRM CLIP	1 SET	\$ 20.00	✗
REAR REVERSE SENSOR	1 SET	\$ 400.00	Should do
JOINT SEALANT	1	\$ 120.00	✗
REAR NUMBER PLATE	1	\$ 80.00	✗
SUBTOTAL		\$ 1,250.00	
BALANCE C/F		\$ 5,941.20	

LABOUR	S/NO	LIST PRICE (\$)	REMARKS
BALANCE B/F		\$ 5,941.20	
CHECK REAR WIRING AND LIGHTNING SYSTEM	1	\$ 80.00	20
REMOVE, REIT REAR LINING, TRIM AND GARNISH	2	\$ 200.00	80
REMOVE AND RENEW REAR REVERSE SENSOR	3	\$ 120.00	50
REMOVE AND RENEW REAR EXHAUST	4	\$ 120.00	✗
TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	5	\$ 200.00	✗
PANEL BEATING ON AFFECTED AREAS	6	\$ 1,400.00	600
SPRAY PAINTING ON AFFECTED AREAS	7	\$ 1,600.00	600
APPLY ANTI RUST ON AFFECTED AREAS	8	\$ 120.00	
SUBTOTAL		\$ 3,840.00	

GRAND TOTAL \$ 9,781.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-1429.80
 20%
 2-1143.84
 S/N-830.00
 2-1350.00

 3323.84
 20%
 2659.