



TRANS EUROKARS PTE LTD



## ESTIMATE COST OF REPAIRS

<b>INDIA INTERNATIONAL INSURANCE PTE LTD</b> 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711  <b>ATTN. :</b> MOTOR CLAIMS <b>FAX :</b>		<b>NAME :</b> <b>ADDRESS :</b>  <b>TEL :</b>		<b>WIP :</b> 48592 <b>EXCESS :</b> <b>DATE:</b> 23-Feb-21			
<b>VEH NO :</b>	<b>SMD7626Z</b>	<b>DATE IN :</b>		<b>CONTACT PERSON :</b>	JESS 8128 9802		
<b>CHASSIS NO :</b>	JM6BN24A8J0241807	<b>MILEAGE :</b>		<b>TYPE OF CLAIM :</b>	THIRD PARTY CLAIM		
<b>MODEL :</b>	MAZDA 3	<b>DATE REG.:</b>	31-Aug-18	<b>POLICY NO. :</b>			
<b>NATURE OF WORKS</b>							
<b>Parts Description</b>							
<b>NO</b>	<b>DESCRIPTION</b>	<b>PARTS NO</b>	<b>QTY</b>	<b>1st</b>	<b>Supp</b>	<b>REVISED</b>	<b>PRICES</b>
1	REAR BUMPER	MB63C-50-221ABB	1				997.50
2	BRACKET, REAR BUMPER	MKD53-50-251	1				5.40
3	RETAINER RHS, REAR BUMPER	MBHN9-50-2H1C	1				37.40
4	PROTECTOR, REAR BUMPER	MBHN9-50-369	1				58.80
5	TOWING COVER RHS	MB63B-50-EK1 BB	1				15.80
6	TAPE, PROTECTOR	MG51D-50-EM1A	2				17.20
7	REAR BUMPER REFLECTOR RHS	MD350-51-5M0E	1				53.00
8	BRACKET'A' RHS, REAR BUMPER	MBHN9-51-067B	1				47.90
9	REAR BUMPER REINFORCEMENT	MB45C-50-260	1				564.20
10	RETAINER, SENSOR	MKD47-67-UC5A53	4				72.80
11	SENSOR, ULTRASONIC	MGMK6-67-UC1 53	2				361.80
12	SENSOR, ULTRASONIC	MKD47-67-UC1 53	2				407.20
13	RIVET, REAR BUMPER	MEA01-50-037	2				16.00
14	GROMMET, REAR BUMPER	MBHN1-50-0Z1A	4				10.80
15	CLIP, REAR BUMPER	MC274-50-133	4				14.80
16	RIVET, REAR BUMPER	MBBM4-50-355	10				45.00
17	FASTENER, REAR BUMPER	MB45A-56-146A	2				6.00
18	T/LAMP GASKET RHS, BODY	MBHP1-51-153	1				22.00
19	T/LAMP GASKET LHS, BODY	MBHP1-51-163	1				22.00
<b>TOTAL PARTS</b>							2,775.60
<b>TOTAL PARTS COST</b>							2,775.60
<b>SUPPLEMENTARY</b>							
<b>NO</b>	<b>DESCRIPTION</b>	<b>PARTS NO</b>	<b>QTY</b>	<b>1st</b>	<b>Supp</b>	<b>REVISED</b>	<b>PRICES</b>
1							
2							
3							

			<b>TOTAL PARTS</b>		-
			<b>TOTAL PARTS COST</b>		-
<b><u>Labour Description</u></b>					
1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			
2	MZ-SP-SREAR2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.			
3	MZ-BR-REVEN	TO TRANSFER REVERSE SENSORS.			330.00
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.			330.00
5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			350.00
7	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOUC)			250.00
8	MZ-BR-SUNDRI	SUNDRIES.		NETT	100.00

TOTAL LABOUR	-	<b>1,610.00</b>
TOTAL PARTS	-	<b>2,775.60</b>
TOTAL	-	<b>4,385.60</b>
LESS EXCESS	-	-
TOTAL AFTER EXCESS	-	
GST 7%	-	-
GRAND TOTAL	-	-

<b><u>SUPPLEMENTARY LABOUR DESCRIPTION</u></b>					
1		#N/A			
2		#N/A			

TOTAL LABOUR	-	-
TOTAL PARTS	-	-
TOTAL	-	-
LESS EXCESS	-	-
TOTAL AFTER EXCESS	-	
GST 7%	-	-
GRAND TOTAL	-	-

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE

**TRANS EUROKARS PTE LTD**

DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

---

Authorised Signature