

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: S0M02QFU Date: 13th April 2021

Our Ref: CS3/ASM20007200/R1qf3e2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01 Axa Tower Singapore 068811 (The Motor Claims Department)

Attn: Heng Xin Yi

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GBB 2592K INSURED VEHICLE: YM 5184E

ACCIDENT DATE: 08/07/2020

We thank you for your instruction on 25/02/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GBB 2592K from M/s Pro-option Services.
- b) Singapore Accident Statement of Vehicles GBB 2592K and YM 5184E.
- c) Final Repair Bill of GBB 2592K from M/s Million Auto Service.
- d) Colour damaged vehicle photographs of GBB 2592K.

Pre-Repair Inspection Date: 13/07/2020 at M/s Million Auto Service, 4 Penjuru Place #01-12 2.8 Penjuru Tech Hup, Singapore 608782.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : GBB 2592K

Make & Model : Mitsubishi FB70BB1SRDEA

Year of Registration : 2008

Chassis Number : FB70BBA10621

Engine Capacity : 2977 cc

- 2. We recommend that the repairs of the entire damage require about <u>5 (Five)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.