



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV15926/SADAYAN EQBAL Reg No/Reg Date SMU6648C / 25/08/202 Date In/Mileage / 5431 Chassis No GF7W0700630 Engine No 4J11CN0387 Make/Model MIT/ZOMY OUTLANDER 2.0 CVT MODERN () Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	25/02/2021/ 17:31	BLE	261 / Edwin Caina	63365		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW (RR portion) RR BUMPER , RR END PNL & TAILGATE REPAIR / RE-ALIGN RR FLR PNL , LHR FENDER & RHR FENDER				450 x 2	910		2700.00
E PNT88000 RENEW (FRT portion) FRT BUMPER REPAIR FRT SUPPORT PNL , LHF FENDER & RHF FENDER				450 x 1	450		2250.00
E PNT88000 REMOVE & REFIT AC COND & RADIATOR					?		100.00
M SUNDRY TOP UP AIRCON GAS					?		50.00
E PNT88000 REMOVE & REFIT TAILGATE COMPONENT							120.00
E PNT88000 REMOVE & REFIT RR FLR BOARD TRIM & CARPET							120.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
E PNT88000 REMOVE & REFIT RR WINDSCREEN GLASS							240.00
M SUNDRY SUPPLY RR WINDSCREEN SEALANT							80.00
M SUNDRY SUPPLY FRT NUMBER PLATE WITH CASING				cut	100		50.00
M SUNDRY SUPPLY RR NUMBER PLATE WITH CASING				APC			50.00
M SUNDRY RE-SEAL FRT & RR NUMBER PLATE							180.00
E PNT88000 REMOVE & REFIT REVERSE SENSOR							60.00
M SUNDRY SUPPLY REVERSE SENSOR				TN			220.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV15926/SADAYAN EQBAL Reg No/Reg Date SMU6648C / 25/08/202 Date In/Mileage / 5431 Chassis No GF7W0700630 Engine No 4J11CN0387 Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN () Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	25/02/2021/ 17:31	BLE	261 / Edwin Caina	63365			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								49 120.00
APPLY ANTI CORROSION ON AFFECTEAD AREAS								80.00
M SUNDRY								40.00
SUPPLY BODY PNL SEALANT								20.00
M SUNDRY								
SUPPLY C&C BADGE								
M SUNDRY								
Sundries								
E PNT98000								1050 3850.00
RESPRAY RR BUMPER , RR END PNL , TAILGATE , RR FLR PNL , LHR FENDER , 3 X 350								
RHR FENDER , BODYKIT ,								
FRT BUMPER , LHF FENDER & RHF FENDER								
M FACE,RR BUMPER / 00					1.00	811.00	23.00	624.47
M BRKT,R/BMPR FACE SIDE,LH X N/A					1.00	12.00	23.00	9.24
M BRKT,R/BMPR FACE SIDE,RH X N/A					1.00	12.00	23.00	9.24
M REINFORCEMENT,RR BUMPER,LH X N/A					1.00	79.00	23.00	60.83
M REINFORCEMENT,RR BUMPER,RH X BT					1.00	79.00	23.00	60.83
M CLIP,ENG ROOM COVER X N/A					15.00	2.00	23.00	23.10
M EXTENSION,RR BUMPER CRU (Silver)					1.00	360.00	23.00	277.20
M MOULDING,RR BUMPER,LH X n/c (Black)					1.00	106.00	23.00	81.62
M MOULDING,RR BUMPER,RH X n/c (Black)					1.00	106.00	23.00	81.62
M REFLECTOR,TAIL LAMP,LH X N/A					1.00	100.00	23.00	77.00
M REFLECTOR,TAIL LAMP,RH X N/A					1.00	100.00	23.00	77.00
M PANEL,RR END X R					1.00	326.00	23.00	251.02
M PANEL,RR END,INR LH X N/A					1.00	146.00	23.00	112.42
M PANEL,RR END,INR RH X N/A					1.00	146.00	23.00	112.42
M TRIM,RR END X N/A					1.00	113.00	23.00	87.01
M BOX,CARGO FLOOR X N/A					1.00	204.00	23.00	157.08
M PANEL ASSY,TAILGATE / 00					1.00	989.00	23.00	761.53
M GARNISH,TAILGATE X N/A					1.00	496.00	23.00	381.92
M W/STRIP,TAILGATE OPENING X N/A					1.00	213.00	23.00	164.01
M LATCH,TAILGATE X BT					1.00	477.00	23.00	367.29
M STRIKER,TAILGATE LATCH X BT					1.00	19.00	23.00	14.63

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV15926/SADAYAN EQBAL Reg No/Reg Date SMU6648C / 25/08/202 Date In/Mileage / 5431 Chassis No GF7W0700630 Engine No 4J11CN0387 Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN () Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	25/02/2021/ 17:31	BLE	261 / Edwin Caina	63365			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	DAM, TAILGATE SIDE	✓ REC			2.00	27.00	23.00	✓ 41.52
M	FASTENER, WINDSHIELD	✓ REC			4.00	6.00	23.00	✓ 18.48
M	DAM, TAILGATE, UPR	✓ REC			1.00	13.00	23.00	✓ 10.01
M	STOPPER, WINDSHIELD GLASS	✓ REC			2.00	3.00	23.00	✓ 4.62
M	DAM, TAILGATE, LWR	✓ REC			1.00	41.00	23.00	✓ 31.57
M	MARK, OUTLANDER	✓ REC			1.00	95.00	23.00	✓ 73.15
M	LAMP ASSY, COMB, RR LH	X NN			1.00	603.00	23.00	464.31
M	LAMP ASSY, COMB, RR RH	X NN			1.00	603.00	23.00	464.31
M	LAMP ASSY, TAIL, LH	X NN			1.00	506.00	23.00	389.62
M	LAMP ASSY, TAIL, RH	X NN			1.00	506.00	23.00	389.62
M	DECAL, MIVEC	✓ REC			1.00	36.00	23.00	✓ 27.72
M	BODY KIT, OUTLANDER	X NN			1.00	1554.00	20.00	1243.20
M	LLC 4L	X NN			1.00	26.00	23.00	20.02
M	FACE, FR BUMPER	✓ BR			1.00	1048.00	23.00	✓ 806.96
M	EXTENSION, FR BUMPER	✓ CUT (Silver)			1.00	509.00	23.00	✓ 391.93
M	BRACKET, FR BUMPER SIDE, LH	✓ X NN			1.00	18.00	23.00	13.86
M	BRACKET, FR BUMPER SIDE, RH	✓ X NN			1.00	18.00	23.00	13.86
M	GARNISH, FR BUMPER, LH	X NN			1.00	48.00	23.00	36.96
M	GARNISH, FR BUMPER, RH	X NN			1.00	48.00	23.00	36.96
M	COVER, FR BUMPER	✓ CR4 (Black)			1.00	361.00	23.00	✓ 277.97
M	GARNISH, FR BUMPER SIDE	✓ X NN			1.00	48.00	23.00	36.96
M	GARNISH, FR BUMPER SIDE	✓ X NN			1.00	48.00	23.00	36.96
M	GARNISH, FR BUMPER SIDE	✓ BR (chrome)			1.00	220.00	23.00	✓ 169.40
M	GARNISH, FR BUMPER SIDE	✓ BR (chrome)			1.00	220.00	23.00	✓ 169.40
M	GARNISH, FR BUMPER SIDE	✓ X NN			1.00	112.00	23.00	86.24
M	GARNISH, FR BUMPER SIDE	✓ X NN			1.00	112.00	23.00	86.24
M	REINFORCEMENT, FR BUMPER	✓ X NN			1.00	493.00	23.00	379.61
M	BAR, FR BUMPER GUARD	✓ X NN			1.00	130.00	23.00	100.10
M	REINF, FR BUMPER SIDE, LH	✓ OT			1.00	60.00	23.00	✓ 46.20
M	REINF, FR BUMPER SIDE, RH	✓ OT			1.00	69.00	23.00	✓ 53.13
M	REINFORCEMENT, FR BUMPR SIDE	✓ X NN			2.00	22.00	23.00	33.88
M	REINFORCEMENT, FR BUMPER	✓ OT			1.00	135.00	23.00	✓ 103.95
M	MOULDING, FR BUMPER, LH	✓ REC (Black)			1.00	116.00	23.00	✓ 89.32

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV15926/SADAYAN EQBAL Reg No/Reg Date SMU6648C / 25/08/202 Date In/Mileage / 5431 Chassis No GF7W0700630 Engine No 4J11CN0387 Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN (U01 TITANIUM GREY M/ BK BLACK Colour/Trim

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	25/02/2021/ 17:31	BLE	261 / Edwin Caina	63365			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M MOULDING,FR BUMPER,RH ✓ acc (black)					1.00	116.00	23.00	89.32

Estimate

Steve (LKK) 25/2/21, 1.00pm

00- NM AvL

Excess - ?

P/P

By Bel SM

10 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Confirm & accepted by

Signature:
Date:

7% GST on 20508.90

Total Payable

20,508.90
1435.62

21,944.52

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.