

Section A - Accident Details

Registration Number	SHC4725E
Case Reference Number	TAX/02/21/2047
Registration Date	24/10/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	TAN CHIN SENG
Type of Accident	Head to Rear
Accident Date and Time	19/2/2021 9:50 AM
Accident Reported Date and Time	19/2/2021 2:45 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24109822
Special Instruction to ARC, if any	TP
Prepared Date and Time	20/2/2021 9:24 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$200.00
Total Spray Cost	\$1,116.00	\$200.00
Total Spare Part Cost	\$2,754.31	\$383.76
Total Other Cost	\$480.00	\$50.00
TOTAL COST	\$4,857.31	\$833.76
Lump Sum Total	\$4,850.00	\$850.00
Number of Repair Days	5.0	2.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	22/02/2021 5:23 PM	22/02/2021 1:48 PM
Signature		
Remarks		L/S, after paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2103-0061	Invoice Number	
Quotation Date	04.03.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$507.00	\$200.00
Total Labour	\$507.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$1,116.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$480.00	\$50.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace	✓CR4
		90467-07211	BUMPER CLIPS	10.00	\$2.10	25.00	\$15.75	Replace	Replace	✓NEC
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	✓NEC
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check	XSVC
		52016-47030	ARM SUB-ASSY. RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check	XSVC
		52016-47030	ARM SUB-ASSY. RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check	XSVC
		89997-30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Not Given	XSVC
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	XSVC
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	XSVC
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	XSVC
		52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given	XSVC
		52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given	XSVC
		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given	XSVC
		76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given	XSVC
		76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given	XSVC
		58308-47011	UNDER COVER SUB-ASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given	XSVC

		51442-12210	UNDER COVER RR SHIELD	0.00	\$63.90	0.00	\$0.00	Replace	Not Given	XSVC
		58307-47060	END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Check	XSVC
			SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	XSVC
		67005-47241	TAILGATE ASY	0.00	\$1,007.90	0.00	\$0.00	Replace	Not Given	XSVC
			NUMBER PLATE	0.00	\$15.00	0.00	\$0.00	Replace	Not Given	XSVC
			NUMBER PLATE FRAME	0.00	\$12.00	0.00	\$0.00	Replace	Not Given	XSVC
Total					\$4,358.80		\$479.70			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

479.70 /

- 207

383.76 /

+ 200.00 /

+ 250.00 /

833.76 /

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

45 \$ 850 /

2 days