

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

25-Feb-21

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1265 E

1 pc	Tailgate lower garnish	\$	362.61
1 pc	Tailgate lock	\$	216.48
1 pc	Tailgate striker	\$	36.50
1 pc	Tailgate inner trim	\$	431.12
1 pc	Tailgate weatherstrip	\$	276.98
1 pc	Emblem I30	\$	27.80
1 pc	Emblem CRDI	\$	29.40
1 pc	Emblem Hyundai	\$	29.40
1 pc	Rear bumper	\$	811.11
1 pc	Rear bumper sponge	\$	79.20
1 pc	Rear bumper reinforcement	\$	815.64
1 pc	Rear bumper reinforcement centre	\$	79.20
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	\$	104.40
2 pcs	Rear bumper n/s & o/s reflector @\$107.50	\$	215.00
		\$	3,514.84
		Less 20%	\$ 702.97
			\$ 2,811.87

S/NETT

1 set	Rear bumper clips	\$	48.00
1 set	Reverse sensor	\$	280.00
1 set	Tailgate stickers	\$	100.00
1 set	Tailgate lower garnish clips	\$	38.00
1 pc	Rear bumper top protector	\$	80.00

25-Feb-21

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1265 E

Sundry	\$	50.00
To dismantle and replace reverse sensor and test system	\$	80.00
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00
To labour charge for dismantle and renew the accident damaged parts. To heat/cut and weld on the end panel. Including to knock-out, straighten, repair, reshape of the tailgate, etc	\$	800.00
To putty and spray painting on the rear bumper, tailgate, tailgate lower garnish, end panel, tailgate	\$	800.00
To apply rustproofing on the repaired and replaced panels	\$	80.00
Total	\$	5,347.87

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.