

Assigned By: 60.

ALG

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TB / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s Premier Auto

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SUD1265 E

Yr Regn:

MP Dec 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai

1301.6

c.c

1582

Colour:

silver

A/C:

Insured / Std / NI / NA

Sp. Reading

346282

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

TNA D281UVHJ17503

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD ☒ A/Rim or

Tyre Size:

F:

195/65 R15

R:

N

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MAXXIS

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

05-03-21

Survey held at

W/S

12:30 pm

Des. of Damages: Frt / ☒ Rear / OIS / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Got Body injured.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Final Insp (\$

Survey Fee:

Transportation:

3 + RS \$

Fuel

Other

Total

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

25-Feb-21

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1265 E

1 pc	Tailgate lower garnish	✓ CAA	\$	362.61	✓
1 pc	Tailgate lock	X	\$	216.48	
1 pc	Tailgate striker	X	\$	36.50	
1 pc	Tailgate inner trim	X	\$	431.12	
1 pc	Tailgate weatherstrip	X	\$	276.98	
1 pc	Emblem I30	✓	\$	27.80	✓
1 pc	Emblem CRDI	✓	\$	29.40	✓
1 pc	Emblem Hyundai	X	\$	29.40	
1 pc	Rear bumper	✓	\$	811.11	✓
1 pc	Rear bumper sponge	X NN	\$	79.20	
1 pc	Rear bumper reinforcement	X NN	\$	815.64	
1 pc	Rear bumper reinforcement centre	X NN	\$	79.20	
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	X	\$	104.40	
2 pcs	Rear bumper n/s & o/s reflector @\$107.50	X	\$	215.00	107.5
				\$	3,514.84
				\$	702.97
				\$	2,811.87
					1070.73
S/NETT					
1 set	Rear bumper clips	✓	\$	48.00	✓
1 set	Reverse sensor	X	\$	280.00	
1 set	Tailgate stickers	✓	\$	100.00	30
1 set	Tailgate lower garnish clips	✓	\$	38.00	✓
1 pc	Rear bumper top protector	X	\$	80.00	

116

25-Feb-21

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1265 E

Sundry	\$ 50.00	X NN
To dismantle and replace reverse sensor and test system	\$ 80.00	40
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00	X NN
To labour charge for dismantle and renew the accident damaged parts. To heat/cut and weld on the end panel. Including to knock-out, straighten, repair, reshape of the tailgate, etc	\$ 800.00	300
To putty and spray painting on the rear bumper, tailgate, tailgate lower garnish, end panel, tailgate	\$ 800.00	300
To apply rustproofing on the repaired and replaced panels	\$ 80.00	X NN
Total	\$ 5,347.87	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

1826.73

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

-20%: 1450

3 Days.
 Impair repair
 After repair photos.
 Gme Qway 8288 0282
 05/3/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: