



CYCLE & CARRIAGE

AIG-OD (REVERT)
SURVEY: 25/02/21
LKK-STEVE

VEHICLE NO : SGB 3377A

MODEL : KIA/STINGER 2.0 A

WIP : 29433

Material	:	\$	<u>1,531.20</u>
Labour	:	\$	<u>1,670.00</u>
Sub-Total	:	\$	<u>3,201.20</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>—</u>
Total	:	\$	<u>3,201.20</u>
GST 7%	:	\$	<u>224.08</u>
Grand Total	:	\$	<u>3,425.28</u>

Re-Finalise By/Date : LARRY ON 25/03/21

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 04 WORKING DAYS



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 27/02/2021	Cust No/Name LCV10084/LEUNG HOK LUN Reg No/Reg Date SGB3377A / 10/06/2019 Date In/Mileage 27/02/2021/ 14756 Chassis/Package KNAE351AMK6060627 /KC17P Engine No G4CLKH020358 Make/Model KIA/STINGER 2.0 A GAA3 RED LEATHER Colour/Trim P2M PANTHERA METAL / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	25/03/2021/ 08:11	BLE	884 / Lauro Songcuan	29433		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E	PNT88000	RENEW REAR BUMPER					400.00
E	PNT98000	SPRAY PAINT REAR BUMPER					350.00
A	54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM					30.00
A	10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST					120.00
E	PNT88000	REMOVE & REFIT REVERSE SENSOR					60.00
M	SUNDRY	SUPPLY C&C BADGE					40.00
M	SUNDRY	SUNDRIES					20.00
S	SPECIALISTJOB	SUPPLY REAR LICENSE PLATE WITH FRAME (RECTANGULAR & BLACK) → <i>Supp</i>					50.00
E	PNT88000	REPAIR REAR END PANEL → <i>Supp</i>					200.00
E	PNT98000	SPRAY PAINT REAR END PANEL AND BOOT GARNISH → <i>Supp</i>					400.00
X	COVER-RR BUMPER ✓		1.00	639.00	20.00		511.20
X	COVER-RR BUMPER LWR ✓		1.00	342.00	20.00		273.60
X	MOULDING ASSY-RR BUMPER,CTR ?		1.00	93.00	20.00		74.40
X	CAP-RR HOOK ✓		1.00	6.00	20.00		4.80
X	BEAM-RR BUMPER ✓		1.00	263.00	20.00		210.40
X	BRACKET-RR BEAM LWR,CTR ?		1.00	6.00	20.00		4.80
X	BRACKET-RR BUMPER,LWR ?		2.00	5.00	20.00		8.00
X	LOGO-KIA ✕		1.00	64.00	20.00		51.20
X	EMBLEM-STINGER ✕		1.00	68.00	20.00		54.40
X	EMBLEM-GT LINE ✕		1.00	45.00	20.00		36.00
X	ULTRASONIC SENSOR ASSY-BWS ?		2.00	189.00	20.00		302.40
Z	TEXT						

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co. Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 27/02/2021	Cust No/Name LCV10084/LEUNG HOK LUN Reg No/Reg Date SGB3377A / 10/06/2019 Date In/Mileage 27/02/2021/ 14756 Chassis/Package KNAE351AMK6060627 /KC17P Engine No G4CLKH020358 Make/Model KIA/STINGER 2.0 A GAA3 RED LEATHER Colour/Trim P2M PANTHERA METAL / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	25/03/2021/ 08:11	BLE	884 / Lauro Songcuan	29433

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
AIG OD CLAIM - REVERT SURVEY: STEVE (LKK) 25.02.2021 DOA: 23.02.2021 04 DAYS				
Pro Forma				
Guarantee Your Warranty, Maintain with Cycle & Carriage!				

Parts	1,531.20		Nett	3,201.20
Labour	1,560.00	7% GST on	3201.20	224.08
Standard Menu	0.00			
Specialist Job	50.00			
Diagnostics Job	0.00		Total Payable	3,425.28
Sundry/Others	60.00			
Total(w/o GST)	3,201.20			

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SGB 3377 A

<u>Labour</u>		<u>Cost \$</u>
1	Supply Rear License Plate with Frame	50.00 / BT
2	Repair Rear End panel	200.00 /
3	Spray Paint Rear End Panel and Boot Garnish	400.00 /
		<u>650.00</u>
7% GST		45.50
Total		<u>695.50</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE KIA PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SGB3377AWIP: 29433

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	RE Numpel plate w/ CRGINS	? / SUPP	[Signature]	✓ CUT	
2	RE Numpel KEVIN	? / SUPP		✓ RR	
3	11 11 CENTRE MOUNT	? / SUPP		✓ MIS	
4	Release sensor (centre) 2PCS	? / SUPP		✓ RR	
5	RE Numpel dentel GRNICH	? / SUPP	[Signature]	✓ CRU	Store
6	11 11 MKT LH/RH	? / SUPP		✓ CRU	2/3/21
7		? / SUPP			
8	REPHIN RE END PM	✓ ? / SUPP	[Signature]	✓	
9	REPHIN RE PM PM	✓ ? / SUPP		✓	
10	REPHIN ROOF GRNICH	✓ ? / SUPP		✓	
11		? / SUPP			
12	KIA	? / SUPP	[Signature]	✓ RR	
13	STINGEL	? / SUPP		✓ RR	
14	GT LIME	? / SUPP		✓ RR	Store 2/3/21
15	GT C PPHW	? / SUPP		✓ RR	
16		? / SUPP			
17	Add 1 repair chys - Total 4 days	? / SUPP		✓ Store	3/3/21
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT	2/3	[Signature]
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: STINGELSURVEYOR: STINGEL

HOME
 Online

Stinger(CK)/2019/G 2.0 T-G..

VCI

Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save

AHLS
 RVM
 AIRCON

8/8

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ESHIFTER	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good

System	DTC	Description	State
No History or Pending DTC			

S/W Ver.	M-E-K-01-00-0239	VCI Ver.	02.50
ECU Ver.	M-E-K-01-00-0180	OS Ver.	Android 10



HOME

Online



Stinger(CK)/2019/G 2.0 T-G..

VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



PTG



ICU



CLU

21/21

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ESHIFTER	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good

System	DTC	Description	State
No History or Pending DTC			

S/W Ver.

M-E-K-01-00-0240

VCI Ver.

02.51

ECU Ver.

M-E-K-01-00-0181

OS Ver.

Android 10



HOME

Online



Stinger(CK)/2019/G 2.0 T-G..

VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



6/6

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ESHIFTER	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.

M-E-K-01-00-0240

VCI Ver.

02.51

ECU Ver.

M-E-K-01-00-0181

OS Ver.

Android 10