



# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

## PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

CYCLE & CARRIAGE

Reg No : 1977014696

### ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Loh Tai Hui (Lu Dahui) Reg No/Reg Date SGT7840H / 02/02/201 Date In/Mileage / 0 Chassis No JMYXTGF3WGZ002146 Engine No 4B12QQ2668 Make/Model MIT/OUTLANDER 2.4 CVT AWD 16MY (E12) Colour/Trim X04 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	25/02/2021/ 15:36		442 / CocoLu	63374

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER, BONNET, FRT FENDER LH, FRT SUPPORT PANEL REPAIR FRT FENDER RH, FRT DOOR LH, A-PILLAR LH	3 5 X 450			2250.00
E PNT88000 REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR				100.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER, BONNET, FRT SUPPORT PANEL FRT FENDER RH & LH, FRT DOOR LH, A-PILLAR, LH	6 X 350			2100 2800.00
M SUNDRY FRT NUMBER PLATE WITH FRAME				50.00
M SUNDRY APPLY SEALANT FOR ACCIDENT PORTION				40.00
A 54900099 TOP UP AIRCON GAS				80.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
A 54900099 RENEW THROTTLE BODY AND MANIFOLD INLET				200.00 X
A 54900099 RENEW IN OIL COOLER T/M AND PIPING				300.00
M SUNDRY Sundry				20.00
M FACE,FR BUMPER / BR	1.00	863.00	23.00	664.51
M EXTENSION,FR BUMPER / cut (Silver)	1.00	428.00	23.00	329.56
M GARNISH,FR BUMPER,LH ? X 1/M	1.00	78.00	23.00	60.06
M BRACKET,FR BUMPER SIDE,LH / BR	1.00	18.00	23.00	13.86
M COVER,FR BUMPER / MIS (Black)	1.00	281.00	23.00	216.37
M GARNISH,FR BUMPER SIDE / BR (chrome)	1.00	220.00	23.00	169.40
M GARNISH,FR BUMPER SIDE / BR (chrome)	1.00	112.00	23.00	86.24
M GARNISH,FR BUMPER SIDE ? / BR	1.00	48.00	23.00	36.96

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CLE &amp; CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Reg No : 1977014696

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Loh Tai Hui (Lu Dahui) Reg No/Reg Date SGT7840H / 02/02/201 Date In/Mileage / 0 Chassis No JMYXTGF3WGZ002146 Engine No 4B12QQ2668 Make/Model MIT/OUTLANDER 2.4 CVT AWD 16MY (E12 Colour/Trim X04 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	25/02/2021/ 15:36		442 / CocoLu	63374		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	BRKT,FR BUMPER SIDE,LWR LH	nn		1.00	6.00	23.00	4.62
M	REINFORCEMENT,FR BUMPER	00		1.00	505.00	23.00	388.85
M	REINFORCEMENT,FR BUMPER	BT		1.00	135.00	23.00	103.95
M	REINF,FR BUMPER SIDE,RH	nn		1.00	69.00	23.00	53.13
M	REINFORCEMENT,FR BMPR SIDE	nn		1.00	22.00	23.00	16.94
M	REINF,FR BUMPER SIDE,LH	BT		1.00	60.00	23.00	46.20
M	REINF,F/BMPR SIDE,LWRRH	NN		1.00	25.00	23.00	19.25
M	REINF,F/BMPR SIDE,LWRLH	NN		1.00	25.00	23.00	19.25
M	MOULDING,FR BUMPER,LH	REC (Black)		1.00	116.00	23.00	89.32
M	MOULDING,FR WHEEL ARCH,RH	REC (Black) (LH partim)		1.00	199.00	23.00	153.23
M	COVER,FR BUMPER	nn		1.00	25.00	23.00	19.25
M	COVER,HEADLAMP SUPT PANEL	CR4		1.00	50.00	23.00	38.50
M	GRILLE ASSY,RADIATOR	ms		1.00	572.00	23.00	440.44
M	BRACKET,RADIATOR GRILLE,LH	nn		1.00	13.00	23.00	10.01
M	BRACKET,RADIATOR GRILLE	nn		1.00	10.00	23.00	7.70
M	BRACKET,RADIATOR GRILLE	nn		1.00	12.00	23.00	9.24
M	HOOD	00		1.00	980.00	23.00	754.60
M	HINGE,HOOD,RH	nn		1.00	68.00	23.00	52.36
M	HINGE,HOOD,LH	nn		1.00	68.00	23.00	52.36
M	INSULATOR,HOOD	CR4		1.00	133.00	23.00	102.41
M	WEATHERSTRIP,HOOD	X		1.00	41.00	23.00	31.57
M	WEATHERSTRIP,HOOD	NN		1.00	40.00	23.00	30.80
M	LATCH,HOOD	BT		1.00	76.00	23.00	58.52
M	FENDER,FR LH	00		1.00	622.00	23.00	478.94
M	SHIELD,FR WHEELHOUSE,LH	nn		1.00	164.00	23.00	126.28
M	PANEL,HEADLAMP SUPPORT,UPR	00		1.00	230.00	23.00	177.10
M	PNL,HEADLAMP SUPT,UPR RH	nn		1.00	58.00	23.00	44.66
M	PNL,HEADLAMP SUPT,UPR LH	00		1.00	58.00	23.00	44.66
M	HEADLAMP ASSY,LH	OR		1.00	2135.00	23.00	1643.95
M	HEADLAMP ASSY,RH	OR		1.00	2135.00	23.00	1643.95
M	CONDENSER ASSY,A/C REFRIGE	00		1.00	941.00	23.00	724.57
M	HOSE,A/C COMPR DISCHARGE	BT		1.00	191.00	23.00	147.07
M	HOSE,A/C COMPR SUCTION	nn		1.00	235.00	23.00	180.95

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Reg No : 1977014696

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Loh Tai Hui (Lu Dahui) Reg No/Reg Date SGT7840H / 02/02/201 Date In/Mileage / 0 Chassis No JMYXTGF3WGZ002146 Engine No 4B12QQ2668 Make/Model MIT/OUTLANDER 2.4 CVT AWD 16MY (E12) Colour/Trim X04 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	25/02/2021/ 15:36		442 / CocoLu	63374			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	PIPE, A/C CONDENSER OUTLET	1	X N/A		1.00	262.00	23.00	201.74
M	RADIATOR ASSY	1	BR		1.00	1096.00	23.00	843.92
M	HOSE, RADIATOR, LWR	1	X N/A		1.00	22.00	23.00	16.94
M	TANK ASSY, RADIATOR COND	1	X N/A		1.00	103.00	23.00	79.31
M	HOSE, RADIATOR, UPR	1	X N/A		1.00	27.00	23.00	20.79
M	HOSE, RADIATOR, UPR	1	X N/A		1.00	58.00	23.00	44.66
M	HOSE, RADIATOR, UPR	1	X N/A		1.00	43.00	23.00	33.11
M	HOSE, RADIATOR, LWR	1	X N/A		1.00	260.00	23.00	200.20
M	SHROUD, COOLING FAN	1	BR		1.00	78.00	23.00	60.06
M	FAN, COOLING, LH	1	X N/A		1.00	78.00	23.00	60.06
M	FAN, COOLING, LH	1	X N/A		1.00	479.00	23.00	368.83
M	MOTOR, COOLING FAN, LH (120W)	1	X N/A		1.00	479.00	23.00	368.83
M	MOTOR, COOLING FAN, LH (120W)	1	X N/A		1.00	1516.00	23.00	1167.32
M	THROTTLE BODY ASSY	1	X N/A		1.00	932.00	23.00	717.64
M	MANIFOLD, INLET	1	X N/A		1.00	188.00	23.00	144.76
M	DUCT, A/CLNR INTAKE	1	X N/A		1.00	161.00	23.00	123.97
M	DUCT, A/CLNR TO THROT BODY	1	X N/A		1.00	156.00	23.00	120.12
M	COVER, AIR CLEANER	1	X N/A		1.00	146.00	23.00	112.42
M	BODY ASSY, AIR CLEANER	1	X N/A		1.00	988.00	23.00	760.76
M	OIL COOLER, T/M	1	BR		1.00	28.00	23.00	21.56
M	BRACKET, T/M OIL COOLER	1	X N/A		1.00	20.00	23.00	15.40
M	BRACKET, T/M OIL COOLER	1	X N/A		1.00	25.00	23.00	19.25
M	HOSE, T/M OIL COOLER LINE	1	X N/A		1.00	28.00	23.00	21.56
M	HOSE, T/M OIL COOLER LINE	1	X N/A		1.00	41.00	23.00	31.57
M	HOSE, T/M OIL COOLER LINE	1	X N/A		1.00	41.00	23.00	31.57
M	HOSE, T/M OIL COOLER LINE	1	X N/A		1.00	28.00	23.00	21.56
M	HOSE, T/M OIL COOLER LINE	1	X N/A		1.00	32.00	23.00	24.64
M	HOSE, T/M OIL COOLER LINE	1	X N/A		1.00	48.00	23.00	36.96
M	TUBE ASSY, T/M O/CLR LINE	1	BT		1.00	27.00	23.00	20.79
M	HOSE, T/M OIL COOLER LINE	1	X N/A		1.00	62.00	23.00	47.74
M	TUBE ASSY, T/M O/CLR LINE	1	X N/A		1.00	27.00	23.00	20.79
M	TRAY, BATTERY	1	X N/A		1.00	11.00	23.00	8.47
M	L-BOLT, BATTERY	1	X N/A		1.00	11.00	23.00	8.47
M	HOLDER, BATTERY	1	X N/A					

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

Co Reg No : 197701469G

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name Reg No/Reg Date Date In/Mileage Chassis No Engine No Make/Model Colour/Trim	/Loh Tai Hui (Lu Dahui) / 02/02/201 / 0 JMYXTGF3WGZ002146 4B12QQ2668 MIT/OUTLANDER 2.4 CVT AWD 16MY (E12 X04 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	25/02/2021/ 15:36		442 / CocoLu	63374			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M HARNESS, FOG LAMP					1.00	139.00	23.00	107.03
M LAMP ASSY, FOG, FR					1.00	224.00	23.00	172.48

Estimate

Steve (LKK) 25/2/21, 4.00pm

00- NM AL

EXCNS - ?

P/P

My Bel spy

9 days

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Confirm &amp; accepted by

Nett	21,336.87
7% GST on	21336.87
Total Payable	22,830.45

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.