

Surveyor : STEVE LKK
 Claim : AIG OD
 DOA : 25.02.2021
 Emailed : 22.03.2021, 12.50pm
 Date Survey : 25.02.2021

VEHICLE NO : SGT 7840 H
 MODEL : MIT OUTLANDER 2.4
 WIP : 63374

Material	:	\$	<u>10,833.90</u>
Labour	:	\$	<u>5,090.00</u>
Sub-Total	:	\$	<u>15,923.90</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>15,623.90</u>
GST 7%	:	\$	<u>1,093.67</u>
Grand Total	:	\$	<u>16,717.57</u>
Finalise By/Date	:	<u>LOI / 22/03/2021</u>	

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 25/02/2021	<table> <tr> <td>Cust No/Name</td><td>/Loh Tai Hui (Lu Dahui)</td></tr> <tr> <td>Reg No/Reg Date</td><td>SGT7840H / 02/02/2016</td></tr> <tr> <td>Date In/Mileage</td><td>25/02/2021/ 151932</td></tr> <tr> <td>Chassis/Package</td><td>JMYXTGF3WGZ002146 /#</td></tr> <tr> <td>Engine No</td><td>4B12QQ2668</td></tr> <tr> <td>Make/Model</td><td>MIT/OUTLANDER 2.4 CVT AWD 16MY (E12)</td></tr> <tr> <td>Colour/Trim</td><td>X04 / BK</td></tr> </table>	Cust No/Name	/Loh Tai Hui (Lu Dahui)	Reg No/Reg Date	SGT7840H / 02/02/2016	Date In/Mileage	25/02/2021/ 151932	Chassis/Package	JMYXTGF3WGZ002146 /#	Engine No	4B12QQ2668	Make/Model	MIT/OUTLANDER 2.4 CVT AWD 16MY (E12)	Colour/Trim	X04 / BK
Cust No/Name	/Loh Tai Hui (Lu Dahui)														
Reg No/Reg Date	SGT7840H / 02/02/2016														
Date In/Mileage	25/02/2021/ 151932														
Chassis/Package	JMYXTGF3WGZ002146 /#														
Engine No	4B12QQ2668														
Make/Model	MIT/OUTLANDER 2.4 CVT AWD 16MY (E12)														
Colour/Trim	X04 / BK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	11/03/2021/ 14:34	BLC	260 / AiTing	63374			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount	
E	PNT88000	REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, BONNET, LH FRONT FENDER, FRONT SUPPORT PANEL, REPAIR RH FRONT FENDER, LH FRONT DOOR, LH A PILLAR, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME						✓ 2250.00
E	PNT88000	REMOVE & INSTALL A/COND CONDENSOR & RADIATOR TO FACILITATE REPAIR						✓ 100.00
E	PNT98000	RESPRAY ON FRONT BUMPER, BONNET, FRONT SUPPORT PANEL, LH FRONT FENDER, LH FRONT DOOR, LH A PILLAR, AND ALL OTHER AFFECTED AREAS TO THE SAME						✓ 2100.00
M	SUNDRY	APPLY SEALANT ON ACCIDENT PORTIONS						✓ 40.00
A	54900099	TOP UP A/COND GAS						✓ 80.00
A	54900099	CHECK WIRING & ELECTRICAL SYSTEM						✓ 30.00
A	10028901	CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE						✓ 120.00
A	54900099	REPLACE A/T OIL COOLER AND PIPING						? 300.00
M	SUNDRY	SUNDRIES						✓ 20.00
S	SPECIALISTJOB	SUPPLY & REPLACE FRONT LICENSE PLATE WITH FRAME						✓ 50.00
X	EXC	EXCESS FOR OWN DAMAGE CLAIM						-300.00
X	FACE,FR BUMPER			1.00	✓ 863.00	23.00	664.51	
X	EXTENSION,FR BUMPER			1.00	✓ 428.00	23.00	329.56	
X	BRACKET,FR BUMPER SIDE,LH			1.00	✓ 18.00	23.00	13.86	
X	COVER,FR BUMPER			1.00	✓ 281.00	23.00	216.37	
X	GARNISH,FR BUMPER SIDE			1.00	✓ 220.00	23.00	169.40	
X	GARNISH,FR BUMPER SIDE			1.00	✓ 112.00	23.00	86.24	
X	GARNISH,FR BUMPER SIDE			1.00	? 48.00	23.00	36.96	

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Loh Tai Hui (Lu Dahui) Reg No/Reg Date SGT7840H / 02/02/2016 Date In/Mileage 25/02/2021/ 151932 Chassis/Package JMYXTGF3WGZ002146 /# Engine No 4B12QQ2668 Make/Model MIT/OUTLANDER 2.4 CVT AWD 16MY (E12) Colour/Trim X04 / BK
25/02/2021	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	11/03/2021/ 14:34	BLC	260 / AiTing	63374
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
X REINFORCEMENT,FR BUMPER		1.00	505.00	23.00	388.85
X REINFORCEMENT,FR BUMPER		1.00	135.00	23.00	103.95
X REINF,FR BUMPER SIDE,RH		1.00	69.00	23.00	53.13
X REINF,FR BUMPER SIDE,LH		1.00	60.00	23.00	46.20
X MOULDING,FR BUMPER,LH		1.00	116.00	23.00	89.32
X COVER,HEADLAMP SUPT PANEL		1.00	50.00	23.00	38.50
X GRILLE ASSY,RADIATOR		1.00	572.00	23.00	440.44
X HOOD		1.00	980.00	23.00	754.60
X INSULATOR,HOOD		1.00	133.00	23.00	102.41
X LATCH,HOOD		1.00	76.00	23.00	58.52
X FENDER,FR LH		1.00	622.00	23.00	478.94
X PANEL,HEADLAMP SUPPORT,UPR		1.00	230.00	23.00	177.10
X PNL,HEADLAMP SUPT,UPR LH		1.00	58.00	23.00	44.66
X HEADLAMP ASSY,LH		1.00	2135.00	23.00	1643.95
X HEADLAMP ASSY,RH		1.00	2135.00	23.00	1643.95
X CONDENSER ASSY,A/C REFRIGE		1.00	941.00	23.00	724.57
X HOSE,A/C COMPR DISCHARGE		1.00	191.00	23.00	147.07
X RADIATOR ASSY		1.00	1096.00	23.00	843.92
X SHROUD,COOLING FAN		1.00	260.00	23.00	200.20
X OIL COOLER,T/M		1.00	988.00	23.00	760.76
X TUBE ASSY,T/M O/CLR LINE		1.00	48.00	23.00	36.96
X CLIP,ENG ROOM COVER		20.00	2.00	23.00	30.80
X CLIP,RR BUMPER		20.00	3.00	23.00	46.20
X CLIP,INST PANEL CONSOLE		6.00	3.00	23.00	13.86
X RIVET,FR BUMPER		6.00	5.00	23.00	23.10
X HOSE ASSY,HEADLAMP WASHER		1.00	135.00	23.00	103.95
X PANEL,HEADLAMP SUPPORT,LH		1.00	58.00	23.00	44.66
X PIPE,RADIATOR		1.00	10.00	23.00	7.70
X COVER,ENG ROOM UNDER,FR		1.00	150.00	23.00	115.50
X MOULDING,FR WHEEL ARCH,LH		1.00	199.00	23.00	153.23
Z TEXT					
AIG OD CLAIM					
DOA : 25.02.21					

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/Loh Tai Hui (Lu Dahui)
	Reg No/Reg Date	SGT7840H / 02/02/2016
	Date In/Mileage	25/02/2021/ 151932
	Chassis/Package	JMYXTGF3WGZ002146 /#
	Engine No	4B12QQ2668
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD 16MY (E12)
25/02/2021	Colour/Trim	X04 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	11/03/2021/ 14:34	BLC	260 / AiTing	63374

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
SURVEYOR STEVE LKK 25.02.21 POLICY NO: 2100450627-05				
Pro Forma				
Guarantee Your Warranty, Maintain with Cycle & Carriage!				

Parts	10,833.90	Nett	15,623.90
Labour	4,980.00	7% GST on	15623.90
Standard Menu	0.00		1093.67
Specialist Job	50.00	Total Payable	16,717.57
Diagnostics Job	0.00		
Sundry/Others	-240.00		
Total(w/o GST)	15,623.90		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

INSURANCE CO. : AIG


Supplementary Parts For Registration No.: SGT 7840 H

<u>Materials</u>		<u>Cost (\$)</u>
1	Clips (x20)	40.00 / nec
2	Clips (x20)	60.00 / nec
3	Clips (x6)	18.00 / nec
4	Rivets (x6)	30.00 / nec
5	Hose assy, headlamp washer	135.00 / TN
6	Panel, Headlamp support, LH	58.00 / BT
7	Pipe, Radiator	10.00 / BT
8	Cover, Eng room under, Fr	150.00 /
Total		501.00
Less 23% discount		115.23
Total after discount		385.77
7% GST		27.00
Grand total		<u>\$ 412.77</u>

stain by oil

Thank You.

Yours faithfully



LOI AI TING
SENIOR OFFICER - ADMIN
MITSUBISHI SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

Per Mr. SGT F840H
DTCs to Gary out

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	GF3W 2016MY

Diagnostic check on electronic Control System
to use MTF-3 via unit
to Base all the found
to Test drive good condition.

2021.03.08

All DTCs

2021.03.08

All DTCs

2021.03.08

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name		Malfunction Condition
	Power Gate	ETG_92080000		No DTCs		
	KOS/IMMO/Keyless (IMMOBI & KOS)	KOS_8A880020		No DTCs		
	OSS	OSS_9588000B		No DTCs		
	CORNER SENSOR/BACK SENSOR	CornerSens_96000001		Non-equipped System or Communication Error		