



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV09863/CHUA YONG LIANG HENRY (CAI YONG
	Reg No/Reg Date	SML4507L / 22/05/201
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5031214
	Engine No	G4FGJH722113
	Make/Model	KIA/CERATO 1.6 A EX G333
Colour/Trim		B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	25/02/2021/ 16:00	BLE	261 / Edwin Caina	29554			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000	3	T 12						3200.00
RENEW RHR FENDER , RHR DOOR , RHF DOOR & RR BUMPER					5.5	X	400	2200
REPAIR RH ROCKER PNL & RH CENTRE PILLAR PNL								2100.00
E PNT98000	1/2							1750
RESPRAY RR BUMPER , RHR FENDER , RHR DOOR , RHF DOOR ,					5	X	350	
RH ROCKER, PNL & RH CENTRE PILLAR PNL								120.00
E PNT88000								120.00
REMOVE & REFIT RHR DOOR COMPONENT								30.00
E PNT88000								30.00
REMOVE & REFIT RHF DOOR COMPONENT								380.00
M SUNDRY								120.00
RENEW RHR SPORT RIM & TRANSFER TYRE								120.00
M SUNDRY								30.00
SUPPLY RHR SPORT RIM -16" \$8004								120.00
E PNT88000								30.00
REMOVE & REFIT RR FLR BOARD, TRIM, CARPET & SEAT (photo)								120.00
A 54900099								120.00
CHECK WIRING ELECTRICAL SYSTEM								120.00
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								120.00
USING HI-SCAN PRO TEST								240.00
A WHEELALIGNMENTBP								80.00
To Conduct Computerize Full Wheel Alignment								100.00
E PNT88000								60.00
REMOVE & REFIT RR WINDSCREEN GLASS (photo)								120.00
M SUNDRY								40
SUPPLY WINDSCREEN SEALANT								40
M SUNDRY								
INSTALL RHR QTR GLASS SOLAR FILM								
E PNT88000								
REMOVE & REFIT REVERSE SENSOR								
M SUNDRY								
APPLY ANTI CORROSION ON AFFECTED AREAS								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address

AIG Asia Pacific Insurance Pte.
 Ltd.
 MOTOR CLAIM DEPARTMENT
 78 SHENTON WAY #09-16
 AIG BUILDING
 SINGAPORE 079120
 Contact No 64191000

Owner Name & Vehicle Info

Cust No/Name	LCV09863/CHUA YONG LIANG HENRY (CAI YONG)
Reg No/Reg Date	SML4507L / 22/05/201
Date In/Mileage	/ 0
Chassis No	KNAF3416MK5031214
Engine No	G4FGJH722113
Make/Model	KIA/CERATO 1.6 A EX G333
Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	25/02/2021/ 16:00	BLE	261 / Edwin Caina	29554

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M SUNDRY				80.00
SUPPLY BODY PNL SEALANT				20.00
M SUNDRY				
Sundries				
M COVER-RR BUMPER X R / TN	1.00	651.00	20.00	520.80
M COVER-RR BUMPER LWR X	1.00	241.00	20.00	192.80
M COVER-RR BUMPER UNDER, RH X	1.00	33.00	20.00	26.40
M BRACKET-ASSY RR BPR SIDE UPR, R ?	1.00	31.00	20.00	24.80
M PAD-WINDSHIELD GLASS / REC	10.00	2.00	20.00	16.00
M STOPPER-GLASS / REC	2.00	4.00	20.00	6.40
M PANEL ASSY-QUARTER OUTER, RH / REC	1.00	1349.00	20.00	1079.20
M FILM-ANTI CHIPPG RH / REC	1.00	27.00	20.00	21.60
M GUARD-REAR WHEEL, RH ?	1.00	75.00	20.00	60.00
M PANEL ASSY-REAR DOOR, RH / REC	1.00	1377.00	20.00	1101.60
M HINGE ASSY-RR DOOR UPP, RH ?	1.00	33.00	20.00	26.40
M HINGE ASSY-RR DOOR LWR, RH ?	1.00	26.00	20.00	20.80
M HANDLE ASSY-DR OUTSIDE, RHR X R	1.00	58.00	20.00	46.40
M PAD-FR DR O/S HDL HINGE, RHR X	1.00	5.00	20.00	4.00
M PAD-FR DR O/S HDL COVER, RHR X	1.00	5.00	20.00	4.00
M COVER-FR DR O/S HDL RHR X	1.00	14.00	20.00	11.20
M CHECKER ASSY- DOOR, RHR X	1.00	44.00	20.00	35.20
M LATCH ASSY- DOOR, RHR X	1.00	309.00	20.00	247.20
M MOULDING ASSY-RR DR FRAME, RH / REC	1.00	44.00	20.00	35.20
M W/STRIP ASSY-RR DR BELT O/S RH ?	1.00	60.00	20.00	48.00
M GLASS & MOULDING ASSY-QUARTER / REC	1.00	252.00	20.00	201.60
M PANEL ASSY-FRONT DOOR, RH / REC	1.00	1277.00	20.00	1021.60
M HINGE ASSY-UPP DOOR, RHF ?	1.00	30.00	20.00	24.00
M HINGE ASSY-DOOR LWR, RHF ?	1.00	27.00	20.00	21.60
M MOULDING ASSY-FRT DR FRAME, RH / REC	1.00	37.00	20.00	29.60
M W/STRIP ASSY-FR DR BELT O/S RH ?	1.00	64.00	20.00	51.20
M W/STRIP ASSY-FR DR SIDE RH ?	1.00	102.00	20.00	81.60
M W/STRIP-DR BODY SIDE RH ?	1.00	125.00	20.00	100.00
M HANDLE ASSY-DR OUTSIDE, RHF X R	1.00	164.00	20.00	131.20

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address

AIG Asia Pacific Insurance Pte.
Ltd.
MOTOR CLAIM DEPARTMENT
78 SHENTON WAY #09-16
AIG BUILDING
SINGAPORE 079120
Contact No 64191000

Owner Name & Vehicle Info

Cust No/Name LCV09863/CHUA YONG LIANG HENRY (CAI YONG)
Reg No/Reg Date SML4507L / 22/05/201
Date In/Mileage / 0
Chassis No KNAF3416MK5031214
Engine No G4FGJH722113
Make/Model KIA/CERATO 1.6 A EX G333
Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No LAX00000 Terms Credit Date/Time Printed 25/02/2021/ 16:00 CSE BLE Operator 261 / Edwin Caina WIP No 29554

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M COVER- DR O/S HDL RHF X	1.00	14.00	20.00	11.20
M PAD-FR DR O/S HDL COVER, RHF X	1.00	5.00	20.00	4.00
M PAD-FR DR O/S HDL HINGE, RHF X	1.00	5.00	20.00	4.00
M BASE ASSY-FR DR O/S HANDLE RH X	1.00	52.00	20.00	41.60
M STRIKER ASSY-DR X	1.00	14.00	20.00	11.20
M LATCH ASSY-FRONT DOOR, RH X	1.00	400.00	20.00	320.00
M PANEL ASSY-FRONT DR MODULE, RH ?	1.00	241.00	20.00	192.80
M BLACK TAPE-FR DR RR, RH - APC	1.00	13.00	20.00	10.40
M BLACK TAPE-RR DR FR, RH - APC	1.00	13.00	20.00	10.40
M BLACK TAPE-RR DR FRAME RR OTR, - APC	1.00	8.00	20.00	6.40

Estimate

SURVEYOR NAME: Steve CLKK 25/2/21, 4.00pm
SURVEYOR SIGNATURE: OO- NH AL
DATE: EXHIBITS - ?
REMARKS: PIP
My BL SJ
11 days

Confirm & accepted by

Nett	12,842.40
7% GST on	12842.40
Total Payable	13,741.37

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.