

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

Accident Date : 09.02.2021

Not Authorised
Recovery Bypassing

2 days Third Party

Policy No: _____

Date: 24.02.2021

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Honda Vezel" Reg. No. SLL8060T Claiming Against Your Insured Reg. No. SKJ180E		
1pc	Rear Fender Protector RH		<i>Ref / Mgr. Mr</i> 251.00 ✓
10pcs	Rear Fender Protector Clips	2.80	<i>mc</i> 28.00 ✓
	Less 20%		279.00
			55.80
			223.20
	Labour Charge - Panel Beating, Repairing Of Dents at Fender & Rear Door and Parts Replacement		<i>1800</i> 250.00
	To Respray Affected Areas (2k Pearl White)		<i>4000</i> 600.00
	Total		1,073.20

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: