

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 26 Feb 2021

## Preliminary Advice

Insured Vehicle No : SJQ1023U  
TP Vehicle No : GBH3013C  
Make : OPEL COMBO  
Date of Inspection : 08/02/2021  
Inspection At : AUTOMOBILE INTEGRATED MANAGEMENT PTE LTD (HQ)  
23 KAKI BUKIT AVE 4 #04-01, KAKI BUKIT (SOUTH WING)  
SINGAPORE 415933

Accident Date : 21/01/2021  
Assignment Date : 04/02/2021  
Est. Duration of Repair : 3

### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,787.00
Revised Amount	:S\$	2,508.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,508.20
Lump Sum Repair	:S\$	2,000.00

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

- The vehicle is economical for repair
  - The vehicle is not economical for repair
  - Part-by-Part repair
  - Lump Sum repair
- The above survey was conducted on a 'without prejudice' basis.