



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 25.02.2021
Emailed : 23.03.2021, 9am
Date Survey : 26.02.2021

VEHICLE NO : SJL 4519 M
MODEL : KIA CARENS 1.7 A D SX
WIP : 29577

Table with 2 columns: Description and Amount. Rows include Material (\$694.40), Labour (\$1,370.00), Sub-Total (\$2,064.40), Less Excess (\$300.00), Total (\$1,764.40), GST 7% (\$123.51), Grand Total (\$1,887.91), and Finalise By/Date (LOI / 23/03/2021).

[X] REVERT BACK WITHIN 7 DAYS, OTHERWISE WILL PROCEED WITH INVOICING

[] SURVEYOR'S REPORT REQUIRED

[] REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends + 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

[] TP claim

[] Claim GIA / LTA fee

[] Claim Loss of [] Use / [] Rental

[] Claim Medical Fee / Others

[] Third Party Report -



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 26/02/2021	Cust No/Name	/Mr Koo
	Reg No/Reg Date	SJL4519M*KC17/ 13/06/2018
	Date In/Mileage	27/02/2021/ 31030
	Chassis/Package	KNAHU815VJ720559C /A1
	Engine No	D4FDJH551776
	Make/Model	KIA/CARENS 1.7 A D SX FL DY6
	Colour/Trim	K7N GALAXY BROWN / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	22/03/2021/ 09:07	BLD	260 / AiTing	29577			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								✓ 400.00
REPLACE DAMAGED PARTSM REPLACE REAR BUMPER, REPAIR REAR TAILGATE, AND ALL OTEHR AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								
E PNT88000								✓ 60.00
REMOVE AND INSTALL PARKING SENSOR TO FACILITATE REPAIR								
E PNT98000								✓ 700.00
RESPRAY ON REAR TAILGATE, REAR BUMPER, AND ALL OTHER AFFECTED PORTIONS TO THE SAME								
A 54900099								✓ 30.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								
M SUNDRY								✓ 40.00
SUPPLY C&C LOGO								
A 10028901								✓ 120.00
CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE								
M SUNDRY								✓ 20.00
SUNDRIES								
X EXC								-300.00
INSURANCE EXCESS								
X COVER-RR BUMPER,UPR					1.00	✓ 576.00	20.00	460.80
X COVER-RR BUMPER LWR					1.00	✓ 211.00	20.00	168.80
X HOLDER-BACK WARING SYSTEM OTR					1.00	✓ 4.00	20.00	3.20
X HOLDER-BACK WARING SYSTEM OTR					1.00	✓ 4.00	20.00	3.20
X HOLDER-BACK WARING SYSTEM INR					1.00	✓ 4.00	20.00	3.20
X HOLDER-BACK WARING SYSTEM INR					1.00	✓ 4.00	20.00	3.20
X EMBLEM-CARENS					1.00	✓ 36.00	20.00	28.80
X EMBLEM-CRDI					1.00	✓ 29.00	20.00	23.20
Z TEXT								
AIG OD CLAIM								
DOA : 25.02.21								
SURVEYOR STEVE LKK 26.02.21								
POLICY NO: 1800069376-02								
<i>Guarantee Your Warranty, Maintain with Cycle & Carriage!</i>								


Pro Forma

Parts	694.40		Nett	1,764.40
Labour	1,310.00	7% GST on	1764.40	123.51
Standard Menu	0.00			
Specialist Job	0.00			
Diagnostics Job	0.00			
Sundry/Others	-240.00			
Total(w/o GST)	1,764.40		Total Payable	1,887.91

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

Fault Code Searching

Rescan Erase All DTC Go to DTC Save



System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ESP	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.	M-E-K-01-00-0240	VCI Ver.	02.51
ECU Ver.	M-E-K-01-00-0181	OS Ver.	Android 10