

AIR DETAILS

SMT5243Z

TP/CITINA

reference

Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Feb 2021)
 143 PERODUA BEZZA 1.3 Premium (A) (Catalogue:Merimen Singapore 1.0)
Repairer's: (Price-denominated Standard List)
Code: (Unsubmitted, no print-code for SMT5243Z)
Notes: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Other Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

Qty	Part No.	Particulars	%Disc	%Depr	Amount	
		*1 PC FRT BUMPER	0.00	0.00	*300.00 F	✓
		*1 PC FRT BUMPER LH SIDE RETAINER	0.00	0.00	*25.00 F	✓
		*1 PC FRT BUMPER LH FOG LAMP	0.00	0.00	*120.00 F	X
		*1 PC FRT BUMPER LH FOG LAMP GARNISH	0.00	0.00	*65.00 F	✓
		*1 PC FRT BUMPER LH PARKING SENSOR	0.00	0.00	*55.00 F	✓
		*1 PC FRT BUMPER LH TOW COVER	0.00	0.00	*30.00 F	X
		*1 PC FRT BUMPER BEAM	0.00	0.00	*90.00 F	X
		*6 PCS FRT BUMPER CLIPS @2/PC	0.00	0.00	*12.00 F	✓
		*1 PC LH HEADLAMP (HID)	0.00	0.00	*750.00 F	✓
		*1 PC BONNET	0.00	0.00	*450.00 F	✓
		*1 PC FRT LH FENDER	0.00	0.00	*260.00 F	✓
		*1 PC FRT LH FENDER INNER SHIELD	0.00	0.00	*50.00 F	✓
		*1 PC AIR-CON CONDENSER	0.00	0.00	*380.00 F	X
		*1 PC RADIATOR	0.00	0.00	*260.00 F	X
		*1 PC FRT TOP PANEL	0.00	0.00	*80.00 F	✓
		*1 PC FRT WIPER GARNISH	0.00	0.00	*149.00 F	✓
		*1 PC FRT WIPER TANK	0.00	0.00	*80.00 F	✓
		*1 PC RH HEADLAMP (HID)	0.00	0.00	*750.00 F	✓

chise part.

Total Parts (S\$)

3,906.00

Report was unsubmitted during this print-out.
 Generated using **Merimen e-Claims IEAS**

imates on Miscellaneous Items
 ere are no new miscellaneous items selected.

imates on Labour

Particulars	Lab.Type	Amount
our Items		
REMOVE & REFIX FRT BUMPER ASSY,BONNET,FRT LH FENDER,RADIATOR & MOTOR,GRILLE,HEADLAMPS,TO CUT,WELD & RENEW FRT SUPPORT PANEL,TO STRAIGHTEN,KNOCK & REPAIR FRT LH FENDER INNER PANEL & REALIGN THE SAME	New	800.00 <i>6501</i>
REMOVE & REFIX AIRCON,CHECK,VACUUM & REFILL GAS	New	100.00 ✓
PUTTY & RESPRAY ON FRT SUPPORT PANEL,FRT LH FENDER INNER PANEL,BUMPER,BONNET,FRT LH DOOR,REINFORCEMENT & ALL AFFECTED AREAS	New	1,000.00 <i>9001</i>
RUSTPROOFING	New	60.00 ✓
Gross Labour Cost (S\$)		1,960.00

Report was unsubmitted during this print-out.
 Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: