



SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION			
INCIDENT NO. : /20210223/0797		LOCATION OF FIRE: Along Bartley Viaduct, Bartley Road East Towards Bartley Road, near lamp post no. V80F Singapore	
FIRE REPORTED ON : 23 February 2021			
TIME OF CALL : 19:32:35 hrs			
STATION COVERAGE : Paya Lebar Fire Station			
2. INCIDENT INFORMATION			
FIRE INVOLVED: The engine of a car (make, model and registration plate number burnt beyond recognition) at the above said location.			
METHOD OF EXTINGUISHMENT: By SCDF crew using two 38mm hose lines jets from fire appliance.			
PROBABLE CAUSE OF FIRE: Accidental (Overheating at the engine compartment)			
DAMAGE SUSTAINED: As a result of the fire, the engine was damaged. The front part of the car, including the windscreen, the car rear end and interior were also damaged.			
3. FATALITY/INJURY INFORMATION			
NAME	PIN/FIN	ADDRESS	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL	NIL
REPORT CERTIFIED TRUE AND CORRECT BY:			
 MUHAMMAD FAIZAL BIN MAZLAN for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE			

This is a computer generated Fire Report. No signature is required.