

Make H5140 Tony

Vehicle: CB7935K

Make & Model: Toyota Hiace

Chassis No:

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Left Rear Fender			\$ 1,436.70	20/3ent ✓
2	Left Taillamp		368.50	\$ 455.70	scr ✓
3	Left Rear Corner Panel Garnish			\$ 129.60	R X
4	Left Rear Bumper Bracket			\$ 65.80	12 X
5	Rear Bumper			\$450.70	cut ✓
6	Rear Bumper Clip			\$ 30.00 SN	1er ✓
7	Left Rear Tyre			\$ 200.00 SN	82 X
8	Left Rear Rim			\$ 200.00 SN	17 X
9	Left Rear Rim Cap			\$ 212.60	cut ✓
10	Rear Axel Shaft			\$ 1,883.20	12 X
11	Rear Axel Shaft Bearing	2	\$98.70	\$ 197.40	17 X
12	Rear Axel Shaft Oil Seal	2	\$38.60	\$ 77.20	12 X
13	Rear Axel Oil			\$ 50.00 SN	12 X
14	Rear LH Mudflap			\$50.00 SN	good ✓ s/n
15	Rear Fender Glass Sealant			\$60.00 SN	1er 50 s/n
16					
17					
18					
19					
20					
21					
22					
23					

s/n

s/n

s/n

not Authorized
26/1/21

2/5 \$2650 /
4 days.

When 2/1/21 after 12pm.

26/1/21

Labour					
1	Anti Rust Proofing			\$ 100.00	40
2	Check Wiring			\$ 80.00	20
3	Interior Upholstery & Remove Seat			\$ 250.00	100
4	Jack Axel Bearing			\$ 120.00	117X
5	Panel Beating			\$ 800.00	680
6	Paint Work			\$ 800.00	400
7	Remove & Fitting Rear Pender Glass			\$ 120.00	100

STYTECH AUTO PTE. LTD.
 2 Kaki Bukit Ave 2 #02-99 01-03
 Kaki Bukit Autohub Singapore 417921
 Tel: 6444 8125 Fax: 6445 3310
 GST Reg. No.: 201601539K
 Co. Reg. No.: 201601539K
 Email: stytechent@singnet.com.sg

P-2468.50
 252
 P-1851.37
 S/N-130.00
 L-1340.00
 3321.37
 20%
 2657

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: