

File No : SH/2021/000000/TP  
Date : 29-March-2021

LENTOR AMBULANCE PTE LTD  
51 LENTOR AVE  
SINGAPORE 786876

P/P = \$732.74

Estimated cost of repair for vehicle no : **SLH6267Z** Model **NISSAN NV 350**  
Accident involving vehicle no: **SLH6267Z** & **GBB6631E** on **25.02.2021**

Description	Quantity	Cost Price
LH head lamp	1	NETT \$ 481.50 ✓ 458.60
		\$ 481.50
	Less 10%	\$ 48.15
		\$ 433.35

To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp. \$ 25.00 200

To remove front damaged parts, to jack out front support panel, front body and to reshape and repair front bumper and inner panel, head lamp inner panel, front support panel and adjust body panel alignment. \$ 180.00 100

To spray paint front bumper, LH side mirror and affected front damaged portion inclusive of preparatory works and material. \$ 250.00 200

**\$ 888.35**

T/Party: AIG Asia Pacific Insurance Pte Ltd

*Not Authorized  
Returning After Repair  
1 day*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "No Prejudice" basis
- No illegal modification is allowed
- Supplementary work is subject to final approval from insurance company

Acknowledged by:  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_