Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: 23 Mar 2021 Tan Kah Leong Date:

Preliminary Advice

Insured Vehicle No : SJV5988H

TP Vehicle No : XE3875L : 21/02/2021 Accident Date Make : MAN TGS 18.320 **Assignment Date** : 26/02/2021

Date of Inspection : 01/03/2021 Est. Duration of Repair

Inspection At : WAH HONG MOTORS & CREDIT PTE LTD (HQ)

38 TOH GUAN ROAD EAST, #01-57, ENTERPRISE HUB

SINGAPORE 608581

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,565.00
Revised Amount	:S\$	4,275.00
Check Items (Estimated)	:S\$	400.00
Total	:S\$	4,675.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$ Pre-Accident Value :S\$ COE / PARF Rebate :S\$ Salvage Value :S\$ Margin for Repair :S\$

Remarks

)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindlet us have your authorisation.
)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
)	Other comments :