



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details			Account No.		Customer Details		
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept			S1000006 / ICIII1		Mr Low Jin Hui 807A Chai Chee Road #14-16 Singapore 461807 Mobile: 94790827		
			Document No. 39011673				
			Document Date 22/04/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	NSP170R	MWYQKT E3	31/12/2018	SMG7596K	50701	20759	67/DS/SMG7596K
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFZ28H3000059827		2NRX396910	60	Sam San Joi	25/02/2021 14.19		22/04/2021 7.59
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-GBJ9955J ACC DATE:24/02/2021 DRIVE IN:25/02/2021 DATE-IN:09/03/2021 DATE SURVEY:09/03/2021 NO OF REPAIR DAYS:7 DAYS BY:GUO QIANG(LKK)				30.00	
2	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON REAR ACCIDENT AREAS	0619			183.18	
3	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR	*			180.00	
4	B	BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST	*			180.00	
5	B	BP-LAB2 REMOVE & INSTALL REAR COMPARTMENT CARPET , GARNISH AND TRIMMING TO ASSIST REPAIR	*			360.00	
6	B	BP-LAB2 REPLACE & INSTALL REAR WINDSCREEN GLASS	*			462.00	
7	B	BP-LAB2 REMOVE & INSTALL REAR REVERSE CAMERA	*			180.00	
8	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW TAI LGATE	*			360.00	
9	B	BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS	*			2880.00	
10	B	BP-RES2 RESPRAY JOB ON REAR ACCIDENT AFFECTED AR EAS	*			2360.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details				Account No.		Customer Details				
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept				S1000006 / ICIII1		Mr Low Jin Hui 807A Chai Chee Road #14-16 Singapore 461807 Mobile: 94790827				
				Document No. 39011673						
				Document Date 22/04/2021						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks			
2018	NSP170R	MWYQKT E3	31/12/2018	SMG7596K	50701	20759	67/DS/SMG7596K			
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On			
MHFZ28H3000059827		2NRX396910	60	Sam San Joi	25/02/2021	14.19	22/04/2021	7.59		
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount	
11	S	BP-SUBLET ILM	INSTALL REAR WINDSCREEN GLASS 3M SOLAR F				0741			290.00
12	B	BP-ECU2	TO RESET ECU AND REPROGRAMME				*			180.00
13	1	S52159-0U919	COVER, RR BUMPER, L				1.00	316.10		316.10
14	2	S52161-0K040	PIECE, RR BUMPER				10.00	4.10		41.00
15	3	S52151-0D010	EXTENSION, RR BUMPER				1.00	190.00		190.00
16	4	S58307-0D320	PANEL,LAMP LOWER				1.00	433.60		433.60
17	5	S67005-0D360	PANEL SUB-ASSY, BACK				1.00	1131.90		1131.90
18	6	S67881-0D130	WEATHERSTRIP, BACK D				1.00	372.30		372.30
19	7	S68105-0D261	GLASS SUB-ASSY, BACK2				1.00	1029.30		1029.30
20	8	T90975-02086	EMBLEM,SYMBOL				1.00	72.20		72.20
21	9	S75442-0D290	PLATE, BACK DOOR NAM				1.00	35.50		35.50
22	0	S75441-0D070	PLATE, BACK DOOR NAM				1.00	53.20		53.20
23	1	T89997-30100	ANTENNA, ELECTRICAL				1.00	72.00		72.00
24	2	SPC507-0D014 70	BACK SENSOR (4R8,ORANGE ME)				1.00	172.40		172.40
25	3	T04562-12010	DAM KIT,WINDOW GLASS				1.00	121.00		121.00
26	4	T21000-20	SIKA 210002-0 TACK GO! (BLACK) SG				2.00	108.00		216.00
27	5	T21000-22	SIKA 210002-2 G+P 207 ADHESIVE PRIMER				1.00	200.00		200.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary			Total		12,101.68
			Please acknowledge receipt of vehicle		Parts	4,456.50	GST 7.00%		847.12	
					Labour	7,172.00				
					Sublet	473.18	Less		0.00	
					Lubrication/Fluid	0.00				
					Others	0.00	Amount Due		12,948.80	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details			Account No.		Customer Details		
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept			S1000006 / ICIII1		Mr Low Jin Hui 807A Chai Chee Road #14-16 Singapore 461807 Mobile: 94790827		
			Document No. 39011673				
			Document Date 22/04/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	NSP170R	MWYQKT E3	31/12/2018	SMG7596K	50701	20759	67/DS/SMG7596K
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFZ28H3000059827		2NRX396910	60	Sam San Joi	25/02/2021 14.19		22/04/2021 7.59
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-GBJ9955J ACC DATE:24/02/2021 DRIVE IN:25/02/2021 DATE-IN:09/03/2021 DATE SURVEY:09/03/2021 NO OF REPAIR DAYS:7 DAYS BY:GUO QIANG(LKK)				30.00	
2	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON REAR ACCIDENT AREAS	0619			183.18	
3	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR	*			180.00	
4	B	BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST	*			180.00	
5	B	BP-LAB2 REMOVE & INSTALL REAR COMPARTMENT CARPET , GARNISH AND TRIMMING TO ASSIST REPAIR	*			360.00	
6	B	BP-LAB2 REPLACE & INSTALL REAR WINDSCREEN GLASS	*			462.00	
7	B	BP-LAB2 REMOVE & INSTALL REAR REVERSE CAMERA	*			180.00	
8	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW TAI LGATE	*			360.00	
9	B	BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS	*			2880.00	
10	B	BP-RES2 RESPRAY JOB ON REAR ACCIDENT AFFECTED AR EAS	*			2360.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details				Account No.		Customer Details				
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept				S1000006 / ICIII1		Mr Low Jin Hui 807A Chai Chee Road #14-16 Singapore 461807 Mobile: 94790827				
				Document No. 39011673						
				Document Date 22/04/2021						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks			
2018	NSP170R	MWYQKT E3	31/12/2018	SMG7596K	50701	20759	67/DS/SMG7596K			
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On			
MHFZ28H3000059827		2NRX396910	60	Sam San Joi	25/02/2021	14.19	22/04/2021	7.59		
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount	
11	S	BP-SUBLET ILM	INSTALL REAR WINDSCREEN GLASS 3M SOLAR F				0741			290.00
12	B	BP-ECU2	TO RESET ECU AND REPROGRAMME				*			180.00
13	1	S52159-0U919	COVER, RR BUMPER, L				1.00	316.10		316.10
14	2	S52161-0K040	PIECE, RR BUMPER				10.00	4.10		41.00
15	3	S52151-0D010	EXTENSION, RR BUMPER				1.00	190.00		190.00
16	4	S58307-0D320	PANEL,LAMP LOWER				1.00	433.60		433.60
17	5	S67005-0D360	PANEL SUB-ASSY, BACK				1.00	1131.90		1131.90
18	6	S67881-0D130	WEATHERSTRIP, BACK D				1.00	372.30		372.30
19	7	S68105-0D261	GLASS SUB-ASSY, BACK2				1.00	1029.30		1029.30
20	8	T90975-02086	EMBLEM,SYMBOL				1.00	72.20		72.20
21	9	S75442-0D290	PLATE, BACK DOOR NAM				1.00	35.50		35.50
22	0	S75441-0D070	PLATE, BACK DOOR NAM				1.00	53.20		53.20
23	1	T89997-30100	ANTENNA, ELECTRICAL				1.00	72.00		72.00
24	2	SPC507-0D014 70	BACK SENSOR (4R8,ORANGE ME)				1.00	172.40		172.40
25	3	T04562-12010	DAM KIT,WINDOW GLASS				1.00	121.00		121.00
26	4	T21000-20	SIKA 210002-0 TACK GO! (BLACK) SG				2.00	108.00		216.00
27	5	T21000-22	SIKA 210002-2 G+P 207 ADHESIVE PRIMER				1.00	200.00		200.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary			Total 12,101.68		
			Please acknowledge receipt of vehicle 		Parts	4,456.50	GST 7.00% 847.12			
					Labour	7,172.00				
					Sublet	473.18	Less 0.00			
					Lubrication/Fluid	0.00				
					Others	0.00	Amount Due 12,948.80			

Company Copy