

Co Reg No : 1977014696

# ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV18765/LEE BOON KIAT (LI WENJIE) Reg No/Reg Date SMX6040P / 21/01/202 Date In/Mileage / 0 Chassis No MMBSTA13AMH004893 Engine No 3A92UKB2512 Make/Model MIT/21MY ATTRAGE 1.2 CVT (E57) Colour/Trim PO1 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	26/02/2021/ 15:32	BLE	261 / Edwin Caina	63439		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER & RH FENDER REPAIR / RE-ALIGN FRT SUPPORT PNL & BONNET				1.5 X 450			675 1800.00
E PNT98000 RESPRAY FRT BUMPER , RH FENDER , FRT SUPPORT & BONNET				2 X 350			700 1400.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
M SUNDRY SUPPLY FRT NUMBER PLATE WITH CASING							50.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS							40.00
M SUNDRY Sundries							20.00
M FACE,FR BUMPER				1.00	706.00	23.00	543.62
M COVER,FR BUMPER				1.00	12.00	23.00	9.24
M GRILLE ASSY,RADIATOR				1.00	600.00	23.00	462.00
M MARK,THREE-DIA				1.00	54.00	23.00	41.58
M GRILLE,FR UNDER				1.00	90.00	23.00	69.30
M GARNISH,FR BUMPER,RH				1.00	44.00	23.00	33.88
M COVER,FR BUMPER GRILLE				1.00	157.00	23.00	120.89
M BRACKET,FR BUMPER SIDE,RH				1.00	8.00	23.00	6.16
M AIR DAM,SIDE,FR RH				1.00	19.00	23.00	14.63
M GARNISH,FR BUMPER SIDE				1.00	168.00	23.00	129.36
M GARNISH,FR BUMPER SIDE				1.00	120.00	23.00	92.40
M FENDER,FR RH				1.00	430.00	23.00	331.10
M HEADLAMP ASSY,RH				1.00	1706.00	23.00	1313.62
M REINFORCEMENT,FR BUMPER				1.00	293.00	23.00	225.61

Estimate

CRU

CUT (Black)

REC

X NW

X NW

X NW

X NW

X NW

cut (chrome)

OR (chrome)

broken

BT

00

CRU

CUT (Black)

REC

X NW

X NW

X NW

X NW

cut (chrome)

OR (chrome)

broken

BT

SURVEYOR NAME: Steve CLKK

SURVEYOR SIGNATURE: 26/2/21, 3:00pm

# Estimate

SURVEYOR NAME: Stere CLKK

SURVEYOR SIGNATURE: 26/2/21, 3:00pm

DATE: 26/2/21

REMARKS: EXPRESS - ?

PTP 7% GST on

Ry Bel sm

4 days

Confirm & accepted by

Auto Consultants hence notify  
 repairer of the following:  
 survey before/after spray painting  
 display damaged part(s) during resurvey  
 prices are subject to confirmation

Authorized signatory and company stamp

Nett 6,853.39  
 479.74  
**Total Payable 7,333.13**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include  
 any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered  
 after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a  
 deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or  
 cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing  
 the rubber seal or other repair requiring the removal of the windscreen.