



AIG - OD CLAIM
SURVEY: 26/02/21
LKK - STEVE

VEHICLE NO : SMX 6040 P

MODEL : MIT/ATTRAGE 1.2 CVT

WIP : 63439

Material	:	\$	<u>3,200.95</u>
Labour	:	\$	<u>1,595.00</u>
Sub-Total	:	\$	<u>4,795.95</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>4,495.95</u>
GST 7%	:	\$	<u>314.72</u>
Grand Total	:	\$	<u>4,810.67</u>
Finalise By/Date : <u>Larry on 11/03/21</u>			

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 04 WORKING DAYS



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV18765/LEE BOON KIAT (LI WENJIE) Reg No/Reg Date SMX6040P / 21/01/2021 Date In/Mileage 01/03/2021/ 1349 Chassis/Package MMBSTA13AMH004893 Engine No 3A92UKB2512 Make/Model MIT/21MY ATTRAGE 1.2 CVT (E57) Colour/Trim P01 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	11/03/2021/ 15:46	BLE	884 / Lauro Songcuan	63439

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRONT BUMPER & RH FRONT FENDER				675.00 ✓
E PNT98000 SPRAY PAINT FRONT BUMPER & RH FRONT FENDER				700.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00 ✓
MISUNDRY SUNDRIES				20.00 ✓
S SPECIALISTJOB SUPPLY FRONT LICENSE PLATE WITH FRAME (RECTANGULAR & BLACK)				50.00 ✓
X EXC EXCESS				-300.00
X FACE,FR BUMPER ✓	1.00	706.00	23.00	543.62 ✓
X GRILLE ASSY,RADIATOR ✓	1.00	600.00	23.00	462.00 ✓
X MARK,THREE-DIA ✓	1.00	54.00	23.00	41.58 ✓
X GARNISH,FR BUMPER SIDE ✓	1.00	168.00	23.00	129.36 ✓
X GARNISH,FR BUMPER SIDE ✓	1.00	120.00	23.00	92.40 ✓
X FENDER,FR RH ✓	1.00	430.00	23.00	331.10 ✓
X REINFORCEMENT,FR BUMPER ?	1.00	293.00	23.00	225.61 ?
X PANEL,AIR GUIDE,RH	1.00	14.00	23.00	10.78 x
X RIVET,FR BUMPER	8.00	4.00	23.00	24.64 x
X COVER,FR BUMPER ?	1.00	12.00	23.00	9.24 ?
X EMBLEM ECO	1.00	17.00	00.00	17.00 x
X HEADLAMP ASSY,RH ?	1.00	1706.00	23.00	1313.62 ?
Z TEXT OD CLAIM - AIG SURVEY: STEVE (LKK) 26.02.2021 DOA: 26.02.2021 04 DAYS				

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	3,200.95	Nett	4,495.95
Labour	1,525.00	7% GST on	314.72
Standard Menu	0.00		
Specialist Job	50.00		
Diagnostics Job	0.00	Total Payable	4,810.67
Sundry/Others	-280.00		
Total(w/o GST)	4,495.95		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SMX 6040 P

<u>Materials</u>		<u>Cost \$</u>
1	Panel, Air Guide, RH	14.00 ✓ CRU
2	Rivet, FR Bumper (8 pcs)	32.00 ✓ REC
		46.00
23% Discount		10.58
		35.42
3	Emblem ECO	17.00 ✓ REC
		52.42
7% GST		3.67
Total		56.09

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SMX6040PWIP: 63439

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	2-20" Fanblower	<u>2 / SUPP</u>		☒ <u>PC</u>	
2	1st SUPPORT PRT <u>Support Reinforced</u>	<u>2 / SUPP</u>		☒ <u>00</u>	
3	TOWING COVER	<u>2 / SUPP</u>		☒ <u>CR4</u>	
4	RIVET X10	<u>2 / SUPP</u>		☒ <u>PC</u>	
5	HEADLAMP RH	<u>2 / SUPP</u>		☒ <u>RR</u>	
6	FOOT NUMBER PLATE W/ CHAIN	<u>2 / SUPP</u>		☒ <u>RT</u>	<u>Steve</u> <u>2/10/21</u>
7	COOLANT	<u>2 / SUPP</u>		☒	
8	REMOVE / REFIT AC COOL & PROTECTION	<u>2 / SUPP</u>	<u>\$1100</u>	☒	
9	TOP UP GAS	<u>2 / SUPP</u>	<u>\$80</u>	☒	
10	<u>Deflectors RH (Clown)</u>	<u>2 / SUPP</u>		☒ <u>- CR4</u>	
11		<u>2 / SUPP</u>			
12	<u>ADDITIONAL 3 DAYS</u>	<u>2 / SUPP</u>		☒	
13		<u>2 / SUPP</u>			
14		<u>2 / SUPP</u>			
15		<u>2 / SUPP</u>			
16		<u>2 / SUPP</u>			
17		<u>2 / SUPP</u>			
18		<u>2 / SUPP</u>			
19		<u>2 / SUPP</u>			
20		<u>2 / SUPP</u>			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT	<u>3/3</u>	<u>SM</u>
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBOARD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: ATTAGESURVEYOR: STEVE

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	A13A 2021MY

For No: SEW20091-00
Before use MUT-3x, you need to check all the board

2021.03.08

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition	
MPI/GDI/DIESEL	KOSOSS_99880010		No DTCs		
AT/CVT/A-MT/T-C-SST	KOSOSS_99880010		No DTCs		
4WS/Electric Power Steering	KOSOSS_99880010		No DTCs		
ABS/ASC/ASTC/WSS	KOSOSS_99880010		No DTCs		
SRS-AIR BAG	KOSOSS_99880010	B1419	Front-LH G sensor open circuit	Active	
Air Conditioner	KOSOSS_99880010		No DTCs		
ETACS	KOSOSS_99880010	B1707	Flasher open	Active	
Meter	KOSOSS_99880010		No DTCs		
Steering Angle Sensor	KOSOSS_99880010		Non-target System		
KOS/OSS/IMMO/Keyless (with KOS)	KOSOSS_99880010		No DTCs		

All DTCS

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	A13A 2021MY

For M.U.T.-3 Version

Refer to

use

M.U.T.-3 NOS unit

to be done

to Job Done

to Test drive check all system

2021.03.08

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition	
MPI/GDI/DIESEL	KOSOSS_99880010		No DTCS		
AT/CVT/A-MT/TC-SST	KOSOSS_99880010		No DTCS		
4WS/Electric Power Steering	KOSOSS_99880010		No DTCS		
ABS/ASC/ASTC/WSS	KOSOSS_99880010		No DTCS		
SRS-AIR BAG	KOSOSS_99880010		No DTCS		
Air Conditioner	KOSOSS_99880010		No DTCS		
ETACS	KOSOSS_99880010		No DTCS		
Meter	KOSOSS_99880010		No DTCS		
Steering Angle Sensor	KOSOSS_99880010		Non-target System		
KOS/OSS/IMMO/Keyless (with KOS)	KOSOSS_99880010		No DTCS		