

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Reg. No: 199607	'198R GST Reg. No. 19-	.960/198-R
		Affiliated to Federation Internation	nale Des Experts En Au	tomobile
	AUTO & GENERA	L INSURANCE (S) PL	Re	ef: CS/AGI21002672/Avf3n2
		TINSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Da	ate: 08/06/2021
			Co	ode: AGI
1.		Policy Particulars	:- THIRD PARTY C	LAIM
	Insured Veh.	SJQ 548D	Veh. Inspected	SMV 1540G
	Policy No.		Coverage (\$)	0.00
	Claim No.	C10009213/CH	Excess (\$)	0.00
	Assign From	IVY RATILLA	Assign Date	26/02/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALTIS	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	MR2BE3BE000009388	Colour	WHITE
	Odometer	10783 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.	3. Conditions of Tyres			
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	MICHELIN	6 mm
	L/H Front Tyre	225/45 R17	MICHELIN	6 mm
	R/H Rear Tyre	225/45 R17	MICHELIN	6 mm
	L/H Rear Tyre	225/45 R17	MICHELIN	6 mm
4.	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	26/02/2021	Inspection Date	01/03/2021
	Survey held at ISHARE AUTO PTE. LTD.			
	8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
5a.		R	emarks	
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.			
	B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: