

SLX 6658 U. 2013 Sept

TP A14.
Jumper.

BMW 316i 1598cc

WBA3A12050J721339.

Rear RH Door Dented 1373. ✓

Rear RH Door Weatherstripe ^{new} 154 ✓

Rear RH Door Inner Trim Board ^{new} 988 +

Rear RH Door Inner Trim Board Clips. 30 (sw) +

Front RH Door Repair 1298. +

Front RH Door Weatherstripe ^{new} 165 +

Panel Beating.
Spray Painting.
Wiring

~~600~~ 300
~~600~~ 500
~~50~~ 30

To transfer door fittings (Front and Rear) ~~300~~ 80

List: (152)

Labour: 910

10%: 1374.30

Total: 2284.30

1/s: 1.81c.

0.30 days.

1,800

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: