

# XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933  
Tel : 6844-1985 Fax : 6844-5185  
Reg : 201838521G

## Repair Estimate

Date :25/02/2021

Reference: CHEVROLET  
Make: ORLANDO

To Whom It May Concern

TPA x A  
Cecilia.

Dear Sir,

**RE: VEHICLE :.SLJ9573J**  
**CHASSIS NO.: KL1YA7589HK608212**  
**ENGINE NO.: B14NET162500103**

Name of insured :.TAN JIAN HAO  
Date of accident.: 06/02/2021

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

### Parts

No.	Qty	Part Description	Price (SGD)
1	1	REAR BUMPER STEP PLATE <i>dented</i>	\$ 166.00
2	1	REAR BUMPER UPPER <i>3 dented</i>	\$ 1,330.00
3	1	REAR BUMPER LOWER	\$ 493.00
4	1	REAR BUMPER SILL PLATE(SILVER) <i>cut</i>	\$ 223.00
5	1	REAR BUMPER TOWING COVER <i>new</i>	\$ 93.00
6	1	LHR BUMPER REFLECTOR <i>crack</i>	\$ 140.00
7	1	RHR BUMPER REFLECTOR <i>crack</i>	\$ 140.00
8	1	REAR REVERSE LIGHT AND BRAKE LIGHT <i>crack</i>	\$ 307.00
9	1	REAR TAILGATE <i>Dented Repair</i>	\$ 1,528.00
10	1	RHR TAILLAMP	\$ 468.00
11	1	RHR TAILGATE LAMP <i>cut</i>	\$ 328.00
12	1	LHR TAILLAMP	\$ 468.00
13	1	LHR TAILGATE LAMP	\$ 328.00
14	1	RR TAILGATE KEYLESS RECEIVER SENSOR <i>new</i>	\$ 274.00
15	1	REAR END PANEL <i>Dented</i>	\$ 776.00
16	1	REAR END PANEL TRIM <i>crack</i>	\$ 186.00
17	1	REAR SPARE TYRE TOOL BOX TOP COVER <i>crack</i>	\$ 284.00
18	1	REAR SPARE TYRE TOOL BOX <i>crack</i>	\$ 418.00
19	1	REAR FENDER INNER TRIM LOW RH <i>3 up</i>	\$ 781.00
20	1	REAR FENDER INNER TRIM LOW LH <i>3 up</i>	\$ 781.00
21	1	REAR BUMPER CENTRE GUIDE <i>crack</i>	\$ 148.00
22	1	RHR BUMPER GUIDE, OTR <i>new</i>	\$ 118.00
23	1	LHR BUMPER GUIDE, OTR <i>new</i>	\$ 118.00
24	1	REAR BUMPER LEFT CENTRE GUIDE, INR <i>new</i>	\$ 112.00

25	1	REAR BUMPER RIGHT CENTRE GUIDE, INR	new	\$ 112.00	2
26	1	REAR BUMPER BEAM	Bent	\$ 863.00	2
27	1	RR WINDSCREEN	new	\$ 712.00	+
28	1	RR TAILGATE LOGO	new	\$ 187.00	✓
29	1	RR TAILGATE EMBLEM "CHEVROLET"	✓	\$ 133.00	✓
30	1	RR TAILGATE EMBLEM "ORLANDO LS"	✓	\$ 148.00	✓
31	1	RR TAILGATE EMBLEM TURBO	✓	\$ 151.00	✓
32	1	RR TAILGATE LOCK	Damaged	\$ 331.00	✓
33	1	RR TAILGATE LOCK CATCH	new	\$ 121.00	+
34	1	RR TAILGATE INNER TRIM BOARD	new	\$ 311.00	+
35	1	RR TAILGATE RUBBER BEADING	cut	\$ 272.00	2
36	4	RR BUMPER REVERSE SENSOR	1 piece damaged	\$ 860.00	215
37	4	RR BUMPER REVERSE SENSOR SEAL	new	\$ 60.00	-
38	1	RR BUMPER REVERSE SENSOR WIRE HARNESS	snapped	\$ 291.00	+
39	1	RR FENDER PROTECTOR RH	3 new	\$ 167.00	+
40	1	RR FENDER PROTECTOR LH	3 new	\$ 167.00	+

10842  
9757.80

Parts Total: \$ 14,894.00  
Less 10%: \$ 1,489.40  
Total: \$ 13,404.60

9314  
838260

Labour

No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 1,200.00
2	Carry out spray painting on affected area, RR BUMPER, RR TAILGATE, RR END PANEL, RR FENDER RH, RR FENDER LH	\$ 1,200.00
3	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 120.00
4	Remove and refix seat cushion/upholstery & roof lining to facilitate repairs	\$ 200.00
5	To remove and refix reverse sensor and conduct test	\$ 120.00
6	To conduct transfer of parts from old tailgate to new tailgate	\$ 200.00
7	To conduct water leakage test after repairs of vehicle	\$ 80.00
8	To conduct reset of engine light on	\$ 200.00
9	To remove and refix rear tail gate windscreen	\$ 180.00

1970

Labour Total: \$ 3,500.00

Others

Other Description

No.	Other Description	Price (SGD)
1	FENDER INNERSHIELD CLIP	\$ 40.00
2	RR BUMPER CLIP	\$ 40.00
3	RR TAILGATE INNER TRIM BOARD CLIP	\$ 40.00
4	RR END PANEL TRIM CLIP	\$ 20.00
5	RR FENDER PROTECTOR CLIP	\$ 80.00
6	RR WINDSCREEN SEALANT	\$ 65.00
7	RR WINDSCREEN INNER SEAL	\$ 40.00
8	RR WINDSCREEN SOLAR FILM	\$ 200.00
9	RR NUMBER PLATE	\$ 65.00

120 60

Other Total: 590.00

TOTAL: 17,494.60

GRAND TOTAL : 17,494.60

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor  
Kelvin Chew  
HP: 8292 5595 Fax: 68445185

Adrian Lj

L/S 26/02/21

06 hrs. ✓

~~total: 11847.80~~

~~L/S: 94K~~

total: 10092.60

L/S: 8K ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: