

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21002682/DGS3Q2**Date:** 09/02/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SHC7154H**Insured Vehicle No :** SLG8124U

Date of Loss: 10/02/2021

Nature of Claim: TP

Claim No: 9771514628SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHC7154H**

Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A) Engine No: D4DFU606741

Reg. Date: 07/04/2016 (Man. Year: 2015)

Chassis No: KMHLB41UMGU086973

Colour: Yellow

Odometer: 817997 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: West Lake 5 mm

Rear Left Side: West Lake 5 mm

Front Right Side: West Lake 5 mm

Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,961.08	14,470.20	13,490.88	48.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,200.00	2,280.00	3,920.00	63.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	34,161.08	16,750.20	17,410.88	50.97
Approved Total (Overridden) (S\$)		13,400.00		
(S\$)	34,161.08	13,400.00	20,761.08	60.77
+ GST 7.00/7.00% (S\$)	2,391.28	938.00	1,453.28	60.77
Nett Amount (S\$)	36,552.36	14,338.00	22,214.36	60.77
+ Loss of Use (13.0 x S\$50.00/day) (S\$)		650.00		
+ Car Rental (13.0 x S\$110.67/day) (S\$)		1,438.71		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		80.00		
Nett Liability (S\$)		16,514.16		
Global Sum Settlement (S\$)		16,200.00		

INSPECTION

Date of Assignment: 26/02/2021

Date Inspected: 01/03/2021 Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 9.0 days

Adjuster: BRYAN TANI

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	2,265.90 FL	*2,265.90 FL
2	1		*BONNET RUBBER (LH)	Not Necessary	35.70 FL	*- FL
3	1		*BONNET RUBBER (RH)	Not Necessary	35.70 FL	*- FL
4	2		*BONNET HINGE (LH/RH)	Bent	253.40 FL	*253.40 FL
5	1		*BONNET LOCK	Serviceable	142.40 FL	*- FL
6	1		*BONNET ABSORBER (LH ONLY)	Not Necessary	61.60 FL	*- FL
7	1		*BONNET SEAL	Not Necessary	31.90 FL	*- FL
8	1		*BONNET INSULATOR CLIPS	Not Necessary	15.00 FL	*- FL
9	1		*RADIATOR GRILLE H EMBLEM	Necessary	129.50 FL	*129.50 FL
10	1		*RADIATOR GRILLE	Cracked	1,480.00 FL	*1,110.10 FL
11	1		*FRONT BUMPER COVER	Torn / Dented	1,052.20 FL	*1,052.20 FL
12	1		*FRONT BUMPER SPONGE	Torn	379.20 FL	*379.20 FL
13	1		*FRONT BUMPER REINFORCEMENT	Bent	588.40 FL	*588.40 FL
14	1		*FRONT BUMPER GRILLE (LH)	Torn / Cut	149.20 FL	*149.20 FL
15	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	89.60 FL	*- FL
16	1		*FRONT BUMPER CENTRE GRILLE TOP GARNISH (I40)	Not Necessary	80.00 FL	*- FL
17	1		*FRONT BUMPER BRACKET (LH/RH)	O/S Not Necessary / N/S Broken	98.40 FL	*49.20 FL
18	2		*FRONT BUMPER SIDE BRACKET (LH/RH)	Not Necessary	57.20 FL	*- FL
19	2		*FRONT BUMPER PROTECTOR (LH/RH)	No such part	50.80 FL	*- FL
20	2		*FRONT BUMPER RETAINER MOUNTING	No such part	152.40 FL	*- FL
21	2		*FRONT BUMPER GRILLE AIR DUCT (LH/RH)	Not Necessary	252.40 FL	*- FL
22	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	907.40 FL	*907.40 FL
23	2		*HEADLAMP (LH/RH)	Broken / Mtg Broken	5,552.00 FL	*2,776.00 FL
24	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	*- FL
25	1		*HEADLAMP HALOGEN BULB (LH)	Not Necessary	28.80 FL	*- FL
26	1		*RADIATOR	Bent	1,637.20 FL	*708.50 FL
27	2		*RADIATOR GUARD (LH/RH)	Not fitted	153.00 FL	*- FL
28	2		*RADIATOR BRACKET (LH/RH)	Not Necessary	26.00 FL	*- FL
29	1		*COOLANT	Not Necessary	45.00 FL	*- FL
30	1		*RADIATOR FAN BLADE ,COWLING ,MOTOR ASSY	Broken	1,194.20 FL	*792.95 FL
31	1		*AIR CLEANER ASSY	Broken	118.60 FL	*118.60 FL
32	1		*AIR FILTER	Not Necessary	63.70 FL	*- FL
33	1		*AIR CLEANER COVER	Not Necessary	228.60 FL	*- FL
34	1		*AIR CLEANER BOTTOM ASSY	Broken	325.00 FL	*325.00 FL
35	1		*AIR CLEANER HOSE	Not Necessary	432.60 FL	*- FL
36	1		*AIR CLEANER HOUSING	Not Necessary	88.50 FL	*- FL
37	1		*FRONT FENDER (LH)	Buckled	663.00 FL	*663.00 FL
38	1		*FRONT FENDER APRON PANEL (LH)	Dented	637.00 FL	*637.00 FL
39	1		*FRONT FENDER SHIELD (LH)	Deformed / Torn	174.90 FL	*174.90 FL
40	1		*FRONT FENDER MUDFLAP (LH)	Not Necessary	16.20 FL	*- FL
41	1		*FRONT FENDER RETAINER	Not Necessary	24.60 FL	*- FL
42	1		*FRONT FENDER GUARD	Not Necessary	120.00 FL	*- FL
43	1		*AIRCON CONDENSER	Bent	947.80 FL	*947.80 FL
44	1		*AIRCON SUCTION & LIQUID HOSE	Not Necessary	624.00 FL	*- FL
45	1		*FRONT WINDSCREEN SIDE GARNISH	Not Necessary	298.00 FL	*- FL
46	1		*FRONT PILLAR UPPER COVER /GARNISH	Not Necessary	225.00 FL	*- FL
47	1		*FRONT WINDSCREEN GLASS	Cracked	1,017.80 FL	*1,017.80 FL
48	1		*FRONT WINDSCREEN MOULDING	Necessary	133.70 FL	*133.70 FL
49	1		*FRONT WHEEL RIM (LH)	Not Necessary	650.60 FL	*- FL
50	1		*FRONT WHEEL HUB CAP (LH)	Not Necessary	214.20 FL	*- FL
51	1		*FRONT WHEEL NUT	Not Necessary	6.80 FL	*- FL
52	1		*KNUCKLE ARM (LH)	Distorted	1,104.00 FL	*552.00 FL
53	1		*FRONT WHEEL BEARING (LH)	Damaged	673.20 FL	*362.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*FRONT WHEEL HUB ASSY	Not Necessary	158.60 FL	*- FL
55	1		*FRONT SUSPENSION LOWER ARM (LH)	Distorted	595.90 FL	*529.30 FL
56	1		*FRONT SHOCK ABSORBER ASSY (LH)	Distorted	684.40 FL	*342.20 FL
57	1		*FRONT SHOCK ABSORBER MOUNTING (LH)	Not Necessary	217.60 FL	*- FL
58	1		*FRONT SHOCK ABSORBER FORK (LH)	Not Necessary	212.15 FL	*- FL
59	1		*STG TIE ROD (LH)	Not Necessary	186.40 FL	*- FL
60	1		*STG TIE END (LH)	Not Necessary	125.20 FL	*- FL
61	1		*STABILIZER BAR ASSY	Not Necessary	463.70 FL	*- FL
62	1		*STABILIZER BAR LINK (LH)	Not Necessary	85.90 FL	*- FL
63	1		*ABS SENSOR	Not Necessary	217.90 FL	*- FL
64	1		*FRONT SUSPENSION UPPER ARM (LH)	Not Necessary	250.40 FL	*- FL
65	1		*FRONT DRIVE SHAFT (LH)	Not Necessary	2,061.60 FL	*- FL
66	1		*RACK & PINION ASSY	Not Necessary	1,820.00 FL	*- FL
67	1		*INTER COOLER	Bent / Punctured	1,032.50 FL	*1,032.50 FL
68	1		*HOSE B TO INTER COOLER	Not Necessary	229.70 FL	*- FL
69	1		*HOSE C TO INTER COOLER INLET	Not Necessary	294.50 FL	*- FL
70	1		*FRONT WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
71	1		*FRONT ERP STICKER	Necessary	26.00 FS	*26.00 FS
72	1		*FRONT TYRE (LH)	Not Necessary	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	34,879.35	18,069.75
- List Item Discount on L Items 20.00/20.00% (\$\$)	6,918.27	3,599.55
Total Parts (\$\$)	27,961.08	14,470.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	1,200.00
2	SPRAY PAINTING CHARGE	New	1,400.00	800.00
3	WIRING CHARGE	New	120.00	30.00
4	TUFF KOTE	New	120.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	FOOT WHEEL ALIGNMENT	New	120.00	0.00
7	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	400.00	0.00
8	RE-SET FRT ABS SYSTEM	New	200.00	0.00
9	REMOVE/REFIX RADIATOR	New	90.00	50.00
10	REMOVE/REFIX AIRCON & REFILL GAS	New	130.00	80.00
11	REMOVE/REFIX FUSE BOX	New	120.00	0.00
12	REMOVE/REFIX FRONT WINDSCREEN GLASS	New	120.00	80.00
13	REMOVE/REFIX ENGINE	New	600.00	0.00
14	REMOVE/REFIX DASHBOARD	New	350.00	0.00
15	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
Gross Labour Cost (\$)			6,200.00	2,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >