



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21002692/T1Utf3e2	
			Date: 29/10/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLS 2629G	Veh. Inspected	SMH 7584P
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2100624/MYE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	26/02/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALTIS	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	MR053REH104548246	Colour	SILVER
	Odometer	86357 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	YOKOHAMA	6 mm
	L/H Front Tyre	205/55 R16	YOKOHAMA	6 mm
	R/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm
	L/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	25/02/2021	Inspection Date	03/03/2021
	Survey held at	56 Loyang Way #06-07, Loyang Enterprise Building		
	Repairer	AP AUTOMOTIVE SERVICES PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	