

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Estimate for SLD3110H Honda Shuttle

Acknowledged by Repairer

Signature:

Date:

- 1 \*BONNET / *mc*
- 2 \*BONNET SEAL / *BT*
- 3 \*BONNET HINGES / *BT*
- 4 \*BONNET INSULATOR / *nn*
- 5 \*BONNET LOCK ASSY / *BT*
- 6 \*FRONT BUMPER / *nn*
- 7 \*FRONT BUMPER FOG LAMP GARNISH / *BR*
- 8 \*FRONT BUMPER RETAINERS / *ce*
- 9 \*FRONT BUMPER REINFORCEMENT / *X NN*
- 10 \*FRONT BUMPER LOWER COVER / *X NN*
- 11 \*FRONT BUMPER LOWER GRILLE / *ce*
- 12 \*FRONT GRILLE / *CRA*
- 13 \*RADIATOR GRILLE BASE / *X NN*
- 14 \*RADIATOR GRILLE CHROME MOULDING / *mc*
- 15 \*RADIATOR GRILLE EMBLEM / *mc*
- 16 \*HEADLAMP @ 1,358.70 / *CRA*
- 17 \*HEADLAMP LOWER BRACKET / *X NN*
- 18 \*FRONT FENDER @ 511.60 / *mc*
- 19 \*FRONT FENDER EMBLEM HYBRID / *X NN*
- 20 \*FRONT FENDER INNER SHIELD / *X NN*
- 21 \*FRONT SUPPORT PANEL / *BUC*
- 22 \*FRONT SUPPORT PANEL TOP GARNISH / *DE*
- 23 \*RADIATOR / *CUT*
- 24 \*RADIATOR FAN COWLING / *X NN*
- 25 \*RADIATOR FAN BLADE / *X NN*
- 26 \*RADIATOR FAN MOTOR / *X NN*
- 27 \*RESONATOR BOX / *X NN*
- 28 \*WIPER WASHER TANK C/W MOTOR / *DE*
- 29 \*AIR DUCT / *DE*
- 30 \*A/C CONDENSER / *CUT*
- 31 \*A/C FAN COWLING / *CRA*
- 32 \*A/C FAN BLADE / *JM*
- 33 \*A/C FAN MOTOR / *NW*
- 34 \*A/C SUCTION PIPE / *BT*
- 35 \*A/C DISCHARGE PIPE / *BT*
- 36 \*TAILGATE / *mc*
- 37 \*TAILGATE INNER TRIM / *DE*
- 38 \*TAILGATE DAMPER / *X*
- 39 \*TAILGATE DETECTOR / *X NN*
- 40 \*TAILGATE DETECTOR STOPPER / *X NN*
- 41 \*TAILGATE EMBLEM SHUTTLE / *mc*
- 42 \*TAILGATE EMBLEM HYBRID / *X NN*
- 43 \*TAILGATE LOGO / *mc*
- 44 \*TAILGATE INNER LOCK / *BT*
- 45 \*TAILGATE CHROME MOULDING / *X NN*
- 46 \*TAILGATE WEATHER STRIP / *twi*
- 47 \*TAILGATE WINDSCREEN MOULDING / *mc*
- 48 \*TAILGATE REFLECTOR @ 489.00 / *BR*
- 49 \*TAILLAMP @ 687.60 / *CRA*
- 50 \*REAR BUMPER / *o's*
- 51 \*REAR BUMPER SPONGE / *X NN*
- 52 \*REAR BUMPER SIDE RETAINER / *ce*
- 53 \*REAR BUMPER REFLECTOR RH / *mc*
- 54 \*REAR BUMPER REFLECTOR GARNISH RH / *mc*
- 55 \*REAR BUMPER TOWING COVER / *mc*
- 56 \*REAR FENDER / *X NN*
- 57 \*REAR FENDER WHEEL HOUSING RH / *BUC*
- 58 \*REAR FENDER INNER TRIM / *X NN*
- 59 \*REAR FENDER QUARTER GLASS WITH MLDG / *X NN*
- 60 \*REAR FENDER COWLING / *BR*
- 61 \*REAR DOOR RH / *X NN*
- 62 \*REAR DOOR INNER TRIM RH / *X NN*

|       |            |   |
|-------|------------|---|
| 642   | \$966.50   | ✓ |
|       | \$97.40    | ✓ |
|       | \$118.80   | ✓ |
|       | \$143.20   | ✓ |
|       | \$146.10   | ✓ |
|       | \$796.40   | ✓ |
| 144.8 | \$202.00   | ✓ |
|       | \$69.00    | ✓ |
|       | \$421.10   | ✓ |
|       | \$312.00   | ✓ |
| 189.5 | \$289.00   | ✓ |
| 315   | \$498.00   | ✓ |
|       | \$512.20   | ✓ |
| 366   | \$422.60   | ✓ |
| 24    | \$76.20    | ✓ |
| 2250  | \$2,717.44 | ✓ |
|       | \$183.60   | ✓ |
| 870   | \$1,023.20 | ✓ |
|       | \$136.00   | ✓ |
|       | \$302.80   | ✓ |
| 510   | \$749.40   | ✓ |
|       | \$312.00   | ✓ |
|       | \$1,258.00 | ✓ |
|       | \$177.60   | ✓ |
|       | \$218.30   | ✓ |
|       | \$352.20   | ✓ |
|       | \$359.00   | ✓ |
| 318   | \$412.00   | ✓ |
|       | \$120.00   | ✓ |
|       | \$947.80   | ✓ |
| 72    | \$187.30   | ✓ |
| 61    | \$204.00   | ✓ |
| 165   | \$347.30   | ✓ |
| 151   | \$273.30   | ✓ |
| 151   | \$175.90   | ✓ |
|       | \$982.00   | ✓ |
| 320.2 | \$698.00   | ✓ |
|       | \$308.00   | ✓ |
|       | \$425.00   | ✓ |
|       | \$80.00    | ✓ |
|       | \$51.90    | ✓ |
|       | \$52.90    | ✓ |
| 37.4  | \$65.20    | ✓ |
| 158.9 | \$298.50   | ✓ |
|       | \$321.00   | ✓ |
| 108.6 | \$210.00   | ✓ |
| 78    | \$164.30   | ✓ |
| 681.6 | \$978.00   | ✓ |
| 820   | \$1,375.20 | ✓ |
|       | \$1,189.00 | ✓ |
|       | \$369.20   | ✓ |
| 53    | \$128.40   | ✓ |
| 90    | \$159.00   | ✓ |
| 90.6  | \$120.00   | ✓ |
| 25    | \$45.00    | ✓ |
|       | \$1,112.00 | ✓ |
|       | \$898.00   | ✓ |
| 911.2 | \$1,690.00 | ✓ |
|       | \$1,424.00 | ✓ |
| 217.8 | \$424.00   | ✓ |
|       | \$1,258.00 | ✓ |
|       | \$598.00   | ✓ |

Umpsun Repair  
After repair photos.  
One Claim  
01/31/2021  
15 Days.

4057 64



63 \*REAR DOOR WEATHER STRIP RH X  
 64 \*REAR DOOR INNER LOCK RH X  
 65 \*REAR DOOR OUTER MOULDING RH X  
 66 \*REAR END PANEL  
 67 \*REAR END PANEL TOP GARNISH  
 68 \*TOOLS BOX X NN  
 69 \*REAR FLOOR PANEL  
 70 \*REAR FLOOR PANEL EXTENSION RH BUC  
 71 \*REAR FLOOR PANEL COVER BOARD X NN  
 72 \*REAR FLOOR SIDE BOARD X NN  
 73 \*REAR FLOOR TOOLS SPONGE CRA  
 74 \*REAR FLOOR COMPARTMENT CRA  
 75 \*REAR CHASSIS FRAME RH  
 76 \*REVERSE SPEAKER NN  
 77 \*EXHAUST PIPE  
 78 \*EXHAUST CENTER PIPE BT

\$210.00 X  
 \$321.00 X  
 \$159.00 X  
 \$668.00 X  
 155.5 \$324.20 X  
 \$498.00 X  
 1056.2 \$2,015.00 X  
 \$784.00 X  
 \$589.00 X  
 \$318.00 X  
 \$289.00 X  
 322 \$541.00 X  
 \$1,548.00 X  
 \$165.00 X  
 788.6 \$987.00 X  
 \$948.00 X  
 \$41,316.44 22033.3  
 \$8,263.29  
 \$33,053.15 17626.64

Less 20%

S/Nett

79 \*FRONT BUMPER CLIP SET / MCL  
 80 \*FRONT LOWER SPLASH SHIELD CLIP SET X NN  
 81 \*RADIATOR GRILLE CLIP SET MCL  
 82 \*BONNET INSULATOR CLIP SET NEC  
 83 \*FRONT FENDER INNER SHIELD CLIP SET MCL  
 84 \*RADIATOR COOLANT MCL  
 85 \*REAR NUMBER PLATE X NN  
 86 \*REAR BUMPER CLIPS MCL  
 87 \*REAR FENDER INNER TRIM CLIPS NEC  
 88 \*REAR FENDER COWLING CLIPS (SET) NEC  
 89 \*REAR END PANEL TOP GARNISH CLIPS MCL  
 90 \*REAR FLOOR PANEL INSULATION SEAL X NN  
 91 \*TAILGATE WINDSCREEN SEALANT MCL  
 92 \*TAILGATE WINDSCREEN INNER SHIELD X NN  
 93 \*TAILGATE INNER TRIM CLIPS nec  
 94 \*REAR DOOR INNER TRIM CLIP X  
 95 \*REAR END PANEL INSULATION SEAL X NN  
 96 \*REVERSE CAMERA X NN  
 97 \*REVERSE SENSOR MCL

30 \$65.00 X  
 \$70.00 X  
 20 \$50.00 X  
 20 \$80.00 X  
 20 \$150.00 X  
 40 \$165.00 X  
 \$50.00 X  
 30 \$52.00 X  
 30 \$130.00 X  
 20 \$60.00 X  
 10 \$25.50 X  
 \$150.00 X  
 40 \$80.00 X  
 \$60.00 X  
 20 \$65.00 X  
 \$65.00 X  
 \$150.00 X  
 \$450.00 X  
 \$220.00 X  
 \$2,137.50 500

1 CUT OFF AND REPLACE FRONT SUPPORT PANEL. RESTRUCTURE FRONT CRASH MANAGEMENT COMPONENT AND RENEW OTHER DAMAGE PARTS  
 2 SPRAY PAINTING ON DAMAGE AND AFFECTED AREA  
 3 DISMANTLE AND REPLACE A/C CONDENSER ASSY. REFILL, RECHARGE A/C REFRIGERANT GAS AND PERFORM PRESSURE TEST  
 4 ADJUST AND FOCUS FRONT LIGHTING SYSTEM. PERFORM HEADLAMP ADJUSTMENT TO POSITION  
 5 REMOVE AND INSTALL RADIATOR ASSY. PERFORMED RADIATOR PRESSURE TEST  
 6 TOWING SERVICE  
 7 TO PANEL BEAT, REMOVE AND REPLACE PARTS  
 8 TO SPRAY PAINT AFFECTED AREA  
 9 TUFF KOTE  
 10 WIRING AND BULB CHECK  
 11 REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR  
 12 REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING  
 13 REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING  
 14 REMOVE AND REFIX TAILGATE WINDSCREEN  
 15 REMOVE AND REFIX REAR QUARTER GLASS RH  
 16 TRANSFER TAILGATE MECHANISM  
 17 CONDUCT WATER LEAKAGE TEST  
 18 REAR CHASSIS ALIGNMENT  
 19 REMOVE AND REFIX REAR EXHAUST PIPE

\$1,400.00 800  
 \$1,400.00 1000  
 \$180.00 100  
 \$80.00 30  
 \$150.00 X NN  
 \$180.00 X NN  
 \$3,200.00 1600  
 \$2,600.00 1200  
 \$200.00 80  
 \$80.00 X NN  
 \$600.00 80  
 \$80.00 40  
 \$80.00 40  
 \$120.00 100  
 \$100.00 60  
 \$120.00 40  
 \$80.00 X NN  
 \$800.00 X NN  
 \$150.00 60  
 \$11,600.00 5230

Total

\$46,790.65

23356.64

-20%: 18k