

Enl.

CS/CTI 21002696/Gvf3

ASSIGNMENT

From

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop n/s

of

Insured: SLR 499H

Policy No. DMHCSNW00002312000

Claims No. SNM21D201035/C02

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

~~\$52k~~ 53k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

15

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLD 3110H

yr Regn:

13 Jun 2016

Type: M/Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Shuttle 1.5L 1496

Colour

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GK 8100 5717

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/50 8R16

R:

17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

22-02-21

D.O.I.

01-03-21

Survey held at

Des. of Damages / Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Col: 34991

Net: ~~17k~~ 18k

8/7/21

LS \$18,000 confirmed by email (Red 28,790.65,61%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 12/7/21-Typist

Days Of Repair: 15

Resurvey No. of Trip: 2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Final Insp (\$

Survey Fee:

Transportation:

3 + RS \$

Photos

Other:

Report by: Merimen

Final Sum: LS \$18,000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Upsun Repair
After repair photos.
Bue Qianf
01/3/2021

Estimate for SLD3110H Honda Shuttle

Acknowledged by Repairer

Signature:

Date:

1 *BONNET / <i>me</i>	\$966.50
2 *BONNET SEAL	\$97.40
3 *BONNET HINGE / <i>BT</i>	\$118.80
4 *BONNET INSULATOR	\$143.20
5 *BONNET LOCK ASSY	\$146.10
6 *FRONT BUMPER / <i>W</i>	\$796.40
7 *FRONT BUMPER FOG LAMP GARNISH ?	\$202.00
8 *FRONT BUMPER RETAINER / <i>ce</i>	\$69.00
9 *FRONT BUMPER REINFORCEMENT	\$421.10
10 *FRONT BUMPER LOWER COVER X <i>NN</i>	\$312.00
11 *FRONT BUMPER LOWER GRILLE / <i>ce</i>	\$289.00
12 *FRONT GRILLE / <i>CAS</i>	\$498.00
13 *RADIATOR GRILLE BASE ?	\$512.20
14 *RADIATOR GRILLE CHROME MOULDING / <i>mis</i>	\$422.60
15 *RADIATOR GRILLE EMBLEM	\$76.20
16 *HEADLAMP @ 1,358.70 / <i>CAS</i>	\$2,717.44
17 *HEADLAMP LOWER BRACKET	\$183.60
18 *FRONT FENDER @ 511.60 / <i>me</i>	\$1,023.20
19 *FRONT FENDER EMBLEM HYBRID X <i>NN</i>	\$136.00
20 *FRONT FENDER INNER SHIELD ?	\$302.80
21 *FRONT SUPPORT PANEL ?	\$749.40
22 *FRONT SUPPORT PANEL TOP GARNISH ?	\$312.00
23 *RADIATOR ?	\$1,258.00
24 *RADIATOR FAN COWLING ?	\$177.60
25 *RADIATOR FAN BLADE ?	\$218.30
26 *RADIATOR FAN MOTOR ?	\$352.20
27 *RESONATOR BOX ?	\$359.00
28 *WIPER WASHER TANK C/W MOTOR ?	\$412.00
29 *AIR DUCT ?	\$120.00
30 *A/C CONDENSER ?	\$947.80
31 *A/C FAN COWLING ?	\$187.30
32 *A/C FAN BLADE ?	\$204.00
33 *A/C FAN MOTOR ?	\$347.30
34 *A/C SUCTION PIPE ?	\$273.30
35 *A/C DISCHARGE PIPE ?	\$175.90
36 *TAILGATE / <i>Bue</i>	\$982.00
37 *TAILGATE INNER TRIM ?	\$698.00
38 *TAILGATE DAMPER X <i>NN</i>	\$308.00
39 *TAILGATE DETECTOR X <i>NN</i>	\$425.00
40 *TAILGATE DETECTOR STOPPER X <i>NN</i>	\$80.00
41 *TAILGATE EMBLEM SHUTTLE / <i>me</i>	\$51.90
42 *TAILGATE EMBLEM HYBRID X <i>NN</i>	\$52.90
43 *TAILGATE LOGO / <i>me</i>	\$65.20
44 *TAILGATE INNER LOCK / <i>BT</i>	\$298.50
45 *TAILGATE CHROME MOULDING X <i>NN</i>	\$321.00
46 *TAILGATE WEATHER STRIP / <i>W</i>	\$210.00
47 *TAILGATE WINDSCREEN MOULDING / <i>me</i>	\$164.30
48 *TAILGATE REFLECTOR @ 489.00 ?	\$978.00
49 *TAILLAMP @ 687.60 ?	\$1,375.20
50 *REAR BUMPER / <i>D'S</i>	\$1,189.00
51 *REAR BUMPER SPONGE ?	\$369.20
52 *REAR BUMPER SIDE RETAINER / <i>ce</i>	\$128.40
53 *REAR BUMPER REFLECTOR RH / <i>mis</i>	\$159.00
54 *REAR BUMPER REFLECTOR GARNISH RH / <i>me</i>	\$120.00
55 *REAR BUMPER TOWING COVER / <i>mis</i>	\$45.00
56 *REAR FENDER X <i>Repair</i>	\$1,112.00
57 *REAR FENDER WHEEL HOUSING RH X <i>NN</i>	\$898.00
58 *REAR FENDER INNER TRIM ?	\$1,690.00
59 *REAR FENDER QUARTER GLASS WITH MLDG X <i>NN</i>	\$1,424.00
60 *REAR FENDER COWLING ?	\$424.00
61 *REAR DOOR RH X <i>Repair</i>	\$1,258.00
62 *REAR DOOR INNER TRIM RH X	\$598.00

63	*REAR DOOR WEATHER STRIP RH	X	\$210.00
64	*REAR DOOR INNER LOCK RH	X	\$321.00
65	*REAR DOOR OUTER MOULDING RH	X	\$159.00
66	*REAR END PANEL	✓	\$668.00
67	*REAR END PANEL TOP GARNISH	✓	\$324.20
68	*TOOLS BOX	?	\$498.00
69	*REAR FLOOR PANEL	✓	\$2,015.00
70	*REAR FLOOR PANEL EXTENSION RH	?	\$784.00
71	*REAR FLOOR PANEL COVER BOARD	?	\$589.00
72	*REAR FLOOR SIDE BOARD	?	\$318.00
73	*REAR FLOOR TOOLS SPONGE	?	\$289.00
74	*REAR FLOOR COMPARTMENT	?	\$541.00
75	*REAR CHASSIS FRAME RH	X	\$1,548.00
76	*REVERSE SPEAKER	?	\$165.00
77	*EXHAUST PIPE	✓	\$987.00
78	*EXHAUST CENTER PIPE	?	\$948.00
Less 20%			\$41,316.44
			\$8,263.29
			\$33,053.15

S/Nett

79	*FRONT BUMPER CLIP SET	✓	\$65.00
80	*FRONT LOWER SPLASH SHIELD CLIP SET	X	\$70.00
81	*RADIATOR GRILLE CLIP SET	✓	\$50.00
82	*BONNET INSULATOR CLIP SET	?	\$80.00
83	*FRONT FENDER INNER SHIELD CLIP SET	✓	\$150.00
84	*RADIATOR COOLANT	✓	\$165.00
85	*REAR NUMBER PLATE	X	\$50.00
86	*REAR BUMPER CLIPS	✓	\$52.00
87	*REAR FENDER INNER TRIM CLIPS	?	\$130.00
88	*REAR FENDER COWLING CLIPS (SET)	?	\$60.00
89	*REAR END PANEL TOP GARNISH CLIPS	✓	\$25.50
90	*REAR FLOOR PANEL INSULATION SEAL	?	\$150.00
91	*TAILGATE WINDSCREEN SEALANT	✓	\$80.00
92	*TAILGATE WINDSCREEN INNER SHIELD	?	\$60.00
93	*TAILGATE INNER TRIM CLIPS	?	\$65.00
94	*REAR DOOR INNER TRIM CLIP	X	\$65.00
95	*REAR END PANEL INSULATION SEAL	X	\$150.00
96	*REVERSE CAMERA	X	\$450.00
97	*REVERSE SENSOR	✓	\$220.00
			\$2,137.50

1	CUT OFF AND REPLACE FRONT SUPPORT PANEL. RESTRUCTURE FRONT CRASH MANAGEMENT COMPONENT AND RENEW OTHER DAMAGE PARTS	\$1,400.00
2	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA	\$1,400.00
3	DISMANTLE AND REPLACE A/C CONDENSER ASSY. REFILL, RECHARGE A/C REFRIGERANT GAS AND PERFORM PRESSURE TEST	\$180.00
4	ADJUST AND FOCUS FRONT LIGHTING SYSTEM. PERFORM HEADLAMP ADJUSTMENT TO POSITION	\$80.00
5	REMOVE AND INSTALL RADIATOR ASSY. PERFORMED RADIATOR PRESSURE TEST	\$150.00
6	TOWING SERVICE	\$180.00
7	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$3,200.00
8	TO SPRAY PAINT AFFECTED AREA	\$2,600.00
9	TUFF KOTE	\$200.00
10	WIRING AND BULB CHECK	\$80.00
11	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$600.00
12	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$80.00
13	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$80.00
14	REMOVE AND REFIX TAILGATE WINDSCREEN	\$120.00
15	REMOVE AND REFIX REAR QUARTER GLASS RH	\$100.00
16	TRANSFER TAILGATE MECHANISM	\$120.00
17	CONDUCT WATER LEAKAGE TEST	\$80.00
18	REAR CHASSIS ALIGNMENT	\$800.00
19	REMOVE AND REFIX REAR EXHAUST PIPE	\$150.00
		\$11,600.00

Total

\$46,790.65