

**AUTO BULLOX PTE LTD**

53 Ubi Avenue 1#01-25 Paya Ubi Industrial Park Singapore 408934  
 Tel: 6844 4290 Fax: 6841 6043 Kaman Koh: 9769 9299 Email: motorcarzgarage@gmail.com  
 UEN:201919765N

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged parts for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Estimation

VEHICLE NO : SMP9835K  
 MAKE MODEL: HONDA/VEZEL  
 DOA : 08/02/2021  
 CLAIM TYPE :THIRD PARTY CLAIM  
 SURVEYOR NAME:ADRIAN LING (LKK)

TPAWA  
 Xiao Chen.

No.	Description	Unit	Unit Price	Amount (S\$)
<b>Parts Replacement:</b>				
1	BONNET <i>Dented</i>	1	995.00	995.00 ✓
2	BONNET HINGE <i>3 Area</i>	2	110.00	220.00 +
3	BONNET INSULATOR <i>3 Area</i>	1	145.00	145.00 +
4	BONNET LOCK <i>new</i>	1	311.00	311.00 +
5	FRONT GRILLE ASSY <i>embled</i>	1	900.00	<del>900.00</del> 412
6	FRONT GRILLE EMBLEM <i>new</i>	1	45.00	45.00 ✓
7	FRONT BUMPER <i>Dented</i>	1	902.00	<del>902.00</del> 825
8	FRONT BUMPER LOWER GRILLE <i>new</i>	1	80.00	80.00 +
9	FRONT BUMPER RETAINER <i>new</i>	2	74.00	<del>148.00</del> 75
10	FRONT BUMPER REINFORCEMENT <i>Dented</i>	1	371.00	371.00 ✓
11	FRONT BUMPER TOW COVER <i>Dented</i>	1	75.00	75.00 45
12	FRONT HEADLAMP LH <i>embled</i>	1	2,150.00	<del>2,150.00</del> 1827
13	FRONT HEADLAMP RH <i>embled</i>	1	2,150.00	<del>2,150.00</del> 1827
14	FRONT HEADLAMP TOP CHROME MOULDING LH <i>new</i>	1	156.00	156.00 +
15	FRONT HEADLAMP TOP CHROME MOULDING RH <i>new</i>	1	156.00	156.00 +
16	FRONT FOG LAMP LH <i>new</i>	1	341.00	341.00 +
17	FRONT FOG LAMP RH <i>new</i>	1	341.00	341.00 +
18	FRONT FOG LAMP COVER LH <i>new</i>	1	108.00	108.00 +
19	FRONT FOG LAMP COVER RH <i>new</i>	1	108.00	108.00 +
20	FRONT FENDER LH <i>new</i>	1	689.00	689.00 +
21	FRONT FENDER RH <i>Repair</i>	1	689.00	689.00 +
22	FRONT FENDER INNER SHIELD LH <i>3 Area</i>	1	115.00	115.00 +
23	FRONT FENDER INNER SHIELD RH <i>3 Area</i>	1	115.00	115.00 +
24	FRONT FENDER SIDE GARNISH LH <i>3 Area</i>	1	291.00	291.00 +
25	FRONT FENDER SIDE GARNISH RH <i>3 Area</i>	1	291.00	291.00 +
26	FRONT SUPPORT PANEL <i>Repair</i>	1	641.00	641.00 +
27	FRONT SUPPORT PANEL TOP COVER <i>new</i>	1	55.00	55.00 +

No.	Description	Unit	Unit Price	Amount (S\$)
28	CONDENSER	1	551.00	551.00
29	CONDENSER FAN COWLING	1	95.00	95.00
30	CONDENSER FAN MOTOR	1	295.00	295.00
31	FAN BLADE	1	84.00	84.00
32	RADIATOR	1	1,335.00	1,335.00
33	RADIATOR FAN COWLING	1	94.00	94.00
34	RADIATOR FAN MOTOR	1	328.00	328.00
35	WIPER TANK	1	75.00	75.00
36	SPARE TANK	1	90.00	90.00
	Handy lower Bracket @ 55 110 ✓ cancel			
				15,535.00
			Less 20%	3,107.00
				12,428.00
	<b>S/Nett items:</b>			
				6532
				522560
37	FRONT NUMBER PLATE Bent	1	80.00	80.00
38	FRONT BUMPER CLIP 3/4	1 SET	30.00	30.00
39	FRONT GRILLE CLIP	1 SET	20.00	20.00
40	FRONT FENDER INNER SHIELD CLIP new	1 SET	30.00	30.00
41	REAR BUMPER CLIP new	1 SET	30.00	30.00
42	COOLANT new	1 BOT	190.00	190.00
				380.00
	<b>Labour to:</b>			
43	CHECK FRONT WIRING AND LIGHTNING SYSTEM		60.00	60.00
44	REMOVE, RENEW CONDENSER AND TOP UP GAS		150.00	150.00
45	REMOVE, RENEW RADIATOR AND TOP UP COOLANT		150.00	150.00
46	PANEL BEATING AND RENEW DAMAGE PARTS ON AFFECTED AREAS		1,200.00	1,200.00
47	SPRAY PAINTING ON AFFECTED AREAS		1,500.00	1,500.00
48	APPLY ANTI RUST ON AFFECTED AREAS		120.00	120.00
				3,180.00
	<b>Total Parts Replacement Amount</b>			12,808.00
	<b>Total Amount for Labour</b>			3,180.00
	<b>Total Amount</b>			15,988.00

total: 660560  
 H/S: 52K w/s 01/03/21.  
 04 Days.