

ESTIMATE

27/10/16

T & C AUTOMOTIVE
1 Kaki Bukit Avenue 6
#01-68
Singapore 417883

TP ALG.
Ceilia.

Vehicle No.: SLZ1402M
Make/Model: Audi A3
Chassis: WAUZZZ8V6J1055658

Descriptions	Qty	Unit Price	AMOUNT
Spare Parts			
Boot lid <i>Dented</i> ✓	1		3404.00 ✓
Boot lid weatherstrip <i>ut</i> ✓	1		205.00 ✓
Boot lid lock <i>Den</i> ✓	1		189.00 ✓
Boot lid catch <i>new</i> x	1		491.60 x
Boot lid reflector <i>new</i> <i>ref</i> ✓	2	877.00	1754.00 ✓
Boot lid "A3" emblem ✓	1		98.80 ✓
Boot lid "TFSI" emblem <i>new</i> ✓	1		98.80 ✓
Boot lid "Audi" logo ✓	1		137.50 ✓
Boot lid damper <i>new</i> x	2		103.50 x
Boot lid trimboard <i>new</i> x	1		386.50 x
Boot lid trimboard clip <i>new</i> x	10	5	50.00 x
Tail lamp <i>LH changed</i> ✓	2	877.00	1754.00 ✓
Rear bumper <i>Dented</i> ✓	1		1944.00 ✓
Rear bumper clip <i>new</i> ✓	10	5	50.00 ✓
Rear bumper side retainer <i>new</i> ✓	2	66.20	132.40 ✓
Rear bumper reflector <i>new</i> x	2	40.70	81.40 ✓
Rear bumper center bracket <i>new</i> ✓	1		- ✓
Rear bumper reinforcement <i>new</i> ✓	1		602.50 ✓
Rear bumper foam <i>new</i> x	1		- x
Rear bumper pad <i>ut</i> ✓	1		237.00 ✓
Rear bumper tow hook cover <i>new</i> x	1		421.60 x
Rear parking sensor <i>2 pieces changed</i> x 2	4	111.98	447.92 ✓
Rear license plate lamp <i>new</i> x	2		107.00 x
Rear fender inner trim <i>new</i> x	2		2391.50 x
Rear fender inner trim clip <i>new</i> x	20	5	100.00 x
Rear end panel <i>Dented</i> ✓	1		1092.50 ✓
Rear end panel garnish <i>Dented</i> ✓	1		154.50 ✓
Rear end panel garnish clip <i>new</i> ✓	8	5	40.00 ✓
Spare tyre panel <i>new</i> x	1		662.00 x
Spare tyre board <i>new</i> x	1		541.50 x
Exhaust silencer <i>new</i> x	1		72.00 x
			11240.96
			\$0.00
		Less 10%	\$0.00
		Sub-total 1	10116.86
S/Nett			
Rear number plate w/casing <i>new</i> x	1	90	\$90.00 x
Reverse camera <i>new</i> x	1	368	\$368.00 x
		Sub-Total 2	\$458.00
		Total Spare Parts	\$458.00
Labour			
Rewiring		1710	\$80.00 30
Anti-rust undercoating			\$90.00 20
Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$1,200.00 800
Putty and spray painting all affected parts & areas.			\$1,200.00 800
		Labour	\$3,170.00 1710
		Total Repair Cost	\$

877
22346
11240.96
- 10%
10116.86
30
20
800
800
1710
11826.86
- 20%
9461.49

Toll: 11826.86
L/S: 9.4K
06 Days

Acknowledged by Repairer
Signature:
Date: