

ASS. REG. BY: Bul

ASSIGNMENT

From

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In Order / Jammed / Leaked / Burnt or

Brake: In Order / Jammed / Leaked / Burnt or

Modi: N / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

02/3

Estimated \$ 575.5 with charge Guamp.

SUBMIT 383.50

RED: 242;38%

Date/Time, File Pass to?

☐ : Prell. Report
☐ : Final Report

Date/Time, File Return to?

1)

2)

Days Of Repair: 2

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Insp (\$)
☐ : Total (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Other

Total

Accident Repair Est
GVO Bldg
- 8288 0282

11/02/21

1153 hrs

07632021

Gr 8237A

SG5064X

89TL Vols,

02/03/21

[illegible]

$\approx 4 \text{ MeV}$

Assessment/Repair/Spray paint (labour Cost)	
Contractor Labour Cost	\$ 400.00
Workshop Admin Cost	\$ 192.00
Livery/Advertisement Cost	
Towing Cost	\$ -
Total Labour Cost	\$ 592.00

350
X

Summary		
Total Cost	\$	625.50

~~8~~ 8 May Gay Group
Seater UK
8133 5877

2 Days.

575.5

After repair photos.
loading
02/3/21

TAC - ACCIDENT REPORT VIEW

Page 1 of 2

RERPORT-ID : TAC019R

USER-ID : edsfof02

ACCIDENT REPORT

DATE : 16/02/2021 16:29:39

Page : 1 of 2

Company	SBS	District	SE	IP NUMBER	
Duty IO	Seow Yong Hua	Report No.	R/0763/2021	Accident Date	11/02/2021
Report Date	16/02/2021	Shift Code	AM SHIFT	Accident Time	11:55
Place of Accident	AMK AVE. 6 ROAD AND YCI EGRESS JUNCTION				
Road Name	AMK AVE. 6 ROAD	Road Name Junction	YCI EGRESS	Final Cause	
Accident Type	TRAFFIC	Nature Of Accident	MINOR		
Weather Code	CLEAR	Road Surface	DRY		
Operating Hours	WORKED 5 HRS	Type Of Location	CONTROLLED T-JUNCTION		
Traffic Volume	LIGHT	Traffic Flow	TWO WAYS		
Traffic Control	TRAFFIC LIGHT CONTROLLED	Ambulance Convey	N		
Collision With	VEHICLE	Type Of Collision	REVERSING		
Fatal	0	Serious Injury	0	Minor Injury	0
Police Report	N	Police Report Number		Photo Taken	Y
Bus Towed	N	Sketch	Y	Mechanical Fault	N
Urgent CBR Status	N	CFMS Case	N	CFMS No	
Damage To Bus	SG5064X - FRONT DMG				
Facts of Incident	My bus was stationary along AMK Ave. 6 road at the traffic junction with YCI egress road. In front of my bus about 2 ft away, there was a stationary lorry (GBC8234A). The latter suddenly reversed. I did horned the lorry. I did not know why the lorry reversed. 3P said I stopped too close behind his lorry. No injury. That 's all.				
Brief Particulars	NA				
Reason for Late Report	Due to weekend and holiday				

STATEMENT READ OVER TO ME
AND I AFFIRM IT TO BE TRUE AND CORRECT

SIGNATURE OF STAFF

THAM MENG KHUAN
Safety Officer
Selat Depot

NAME AND DESIGNATION OF RECORDER

CCTV