

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0167/2021/K5
DATE : 25-Feb-21
WIP : 16672

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR IRAWAN BAHTERA
ADDRESS : 2 MISTRI ROAD
#33-01 LUMIERE
SINGAPORE 079624
TELEPHONE : HP +65 96415305
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900016831-02
VEHICLE NO : **SMJ 2427 H**
MODEL CODE : A5 SPORTSBACK 2.0 TFSI S TRONIC
MODEL YEAR : 26/2/2019
ENGINE NO : CVK 074678
CHASSIS NO : WAUZZZF5XKA016155
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 23/2/2020
PLACE OF ACCIDENT : TAMPINES AVE 4 & TAMPINES AVE 5, SG
LEFT TURN FROM AVE 5 TO AVE 4, INFRONT OF
TAMPINES HUB

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SMJ 2427 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING LTD.	S/N \$ 480.00	✓
2	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	X ✓
3	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNITS AND POWER MODULES.	S/N \$ 800.00	250 ✓
4	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAYING OF BOTH FRONT DOORS	S/N \$ 560.00	280 ✓
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 5,600.00	2750 1500 ✓
6 ✓	TO RESPRAY FRONT BUMPER, BONNET, HINGES, LHS FRONT FENDER, RHS FRONT FENDER, RHS FRONT DOOR AND LHS FRONT DOOR.	\$ 6,000.00	2200 ✓
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 15,032.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
E-MAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 2427 H

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER <i>Deformed.</i>	1	\$	2,251.00	✓ 1800.80
2	FRONT BUMPER FIXING PARTS <i>Not nec</i>	1	\$	407.00	+
3	FRONT BUMPER SECURING STRIP <i>Not nec</i>	1	\$	71.00	+. 56.32 ✓
4	FRONT BUMPER LOWER GRILLE <i>Not nec</i>	1	\$	196.00	x
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Not nec</i>	1	\$	228.00	x.
6	FRONT BUMPER LOWER SPOILER <i>Not nec</i>	1	\$	535.00	x
7	RADIATOR GRILLE <i>Cracked</i>	1	\$	2,326.00	✓ 1860.80
8	RADIATOR GRILLE SENSOR SUPPORT LH / RH <i>Not nec</i>	2	\$	102.00	? x
9	RADIATOR GRILLE TOP COVER <i>Not nec</i>	1	\$	189.00	? x
10	FRONT BUMPER AIR GUIDE GRILLE LH / RH <i>Not nec</i>	2	\$	948.00	x.
11	FRONT BUMPER CARRIER <i>Dented.</i>	1	\$	845.00	? 675.60 ✓
12	FRONT BUMPER FOAM FILLER PIECE <i>Cracked</i>	1	\$	124.00	✓ 99.70
13	FRONT BUMPER TOP COVER <i>Deformed.</i>	1	\$	127.00	✓ 101.60
14	FRONT BUMPER GUIDE SECTION LH / RH <i>Not nec</i>	2	\$	72.00	x
15	FRONT BUMPER REINFORCEMENT BRACKET LH <i>Not nec</i>	1	\$	214.00	? x
16	"CAUTION" STICKER <i>3 new</i>	1	\$	14.00	✓ 10.88
17	"AIR COND" STICKER	1	\$	8.00	✓ 5.68
18	LOCK CARRIER BRACKET <i>Cracked.</i>	1	\$	137.00	? 109.60 ✓
19	LOCK CARRIER BRACKET SUPPORT LH / RH <i>LH cracked</i>	2	\$	58.00	29 77.48
20	FRONT PARKING AID SENSOR <i>Not nec</i>	2		TBC	x.
SUB TOTAL SPARE PARTS		:	\$	8,852.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 2427 H

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	FRONT PARKING AID SENSOR SEAL RING <i>N/A</i>	4	\$ 14.00	? X
22	HORN LH <i>N/A</i>	1	\$ 126.00	? X
23	HORN BRACKET LH <i>N/A</i>	1	\$ 29.00	? X
24	FRONT FENDER LH <i>Buckled</i>	1	\$ 1,060.00	✓ 848
25	FRONT FENDER ATTACHMENT PARTS LH <i>N/A</i>	1	\$ 53.00	X
26	FRONT BUMPER CLOSING ELEMENT LH <i>Dented</i>	1	\$ 74.00	? 59.04 ✓
27	FRONT FENDER BRACKET LH <i>Bent</i>	1	\$ 35.00	? 27.92 ✓
28	FRONT FENDER BRACE LH <i>Bent</i>	1	\$ 118.00	? 94.40 ✓
29	FRONT FENDER CENTER BRACKET LH <i>N/A</i>	1	\$ 49.00	? X
30	FRONT FENDER REAR BRACKET LH <i>N/A</i>	1	\$ 35.00	X
31	FRONT FENDER TRIM LH <i>N/A</i>	1	\$ 164.00	✓ 130.80
32	FRONT WHEEL HOUSING LINER LH <i>N/A</i>	1	\$ 275.00	X
33	WHEEL HOUSING LINER ATTACHMENT PARTS <i>N/A</i>	1	\$ 169.00	X
34	FRONT WHEEL SPOILER LH <i>N/A</i>	1	\$ 73.00	X
35	FRONT STONE CHIP GUARD <i>N/A</i>	1	\$ 51.00	X
36	FRONT FENDER LEDGE COVER LH - LONG <i>N/A</i>	1	\$ 36.00	? X
37	FRONT FENDER LEDGE COVER LH - SHORT <i>N/A</i>	1	\$ 16.00	? X
38	BONNET <i>Dented</i>	1	\$ 3,312.00	✓ 2649.60
39	BONNET ATTACHMENT PARTS <i>N/A</i>	1	\$ 123.00	X
40	BONNET HINGE LH / RH <i>N/A</i>	2	\$ 838.00	X
SUB TOTAL SPARE PARTS		:	\$ 6,650.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 2427 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET IMPACT PROTECTION - CENTER <i>{New}</i>	1	\$ 28.00 ✓	✓
42	BONNET IMPACT PROTECTION - LH / RH	2	\$ 56.00 ✓	✓ 43.68
43	BONNET SOUND ABSORBER <i>Not m</i>	1	\$ 343.00 x	
44	BONNET STRIKER LH / RH <i>Not m</i>	2	\$ 100.00 +	
45	BONNET LOCK <i>Not m</i>	2	\$ 427.00 +	
46	BONNET RELEASE CABLE CENTER <i>{Not m}</i>	1	\$ 58.00 +	
47	BONNET RELEASE CABLE COVER <i>{Not m}</i>	1	\$ 10.00 +	
48	BONNET RELEASE CABLE CENTER <i>{Not m}</i>	1	\$ 58.00 +	
49	RELEASE LEVER <i>Not m</i>	1	\$ 14.00 +	
50	LED HEADLIGHT LH / RH <i>LH cracked.</i>	2	\$ 15,804.00	7902 6321.60
51	HEADLIGHT WASHER LIFT CYLINDER LH / RH <i>RH Dmd.</i>	2	\$ 396.00 ?	158.40 ✓
52	HEADLIGHT WASHER HOSE <i>Not m</i>	1	\$ 86.00 x	
53	HEADLIGHT LIFT CYLINDER BRACKET LH <i>Not m</i>	1	\$ 15.00 x	
54	LOCK CARRIER <i>Not m</i>	1	\$ 1,016.00 x	812.80 ✓
55	LOCK CARRIER RADIATOR SUPPORT LH <i>Not m</i>	1	\$ 38.00 x	
56	RADIATOR COOLANT <i>Not m</i>	4	\$ 179.00 x	143.04 ✓
57	RADIATOR AIR GUIDE LH - LONG <i>Not m</i>	1	\$ 32.00 ?	24.88 ✓
58	RADIATOR AIR GUIDE RH - LONG <i>Not m</i>	1	\$ 31.00 x	
59	RADIATOR AIR GUIDE LH - SHORT <i>Not m</i>	1	\$ 16.00 ?	12.80 ✓
60	RADIATOR AIR GUIDE RH - SHORT <i>Not m</i>	1	\$ 16.00 x	
SUB TOTAL SPARE PARTS		:	\$ 18,723.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 2427 H

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
61	RAIDATOR AIR GUIDE - TOP <i>crushed.</i>	1	\$ 16.00	? 12.24 ✓
62	RAIDATOR AIR GUIDE - LOWER <i>Not New</i>	1	\$ 22.00	? X
63	FRONT NO PLATE <i>NOC</i>	S/N	\$ 60.00	✓
64	SUNDRIES <i>Not</i>		\$ 350.00	? 20.80 ✓
TOTAL SPARE PARTS		:	\$ 34,673.00	
TOTAL LABOUR CHARGES		:	\$ 15,032.00	
GRAND TOTAL		:	\$ 49,705.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King*
SURVEYED DATE : *24/02/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *not Authorised, 06 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: