

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mithoo Singh, Aashweenjeet Kaur

Date: 01 Mar 2021

Preliminary Advice

Vehicle No	: SMJ2427H	Accident Date	: 23/02/2021
Make	: AUDI A5	Policy No.	: 1900016831-02
Assignment Date	: 01/03/2021	Excess	: S\$0.00
Date of Inspection	: 24/02/2021	Est. Duration of Repair	: 6
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	49,705.00
Revised Amount	:S\$	22,363.00
Check Items (Estimated)	:S\$	2,816.00
Total	:S\$	25,179.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	146,000.00
COE / PARF Rebate	:S\$	64,632.00
Salvage Value	:S\$	
Margin for Repair	:S\$	81,368.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :